


**PERMIT INFORMATION**

<b>Permit Number:</b> C-1981-014 <b>Mine Name:</b> Southfield Mine <b>Operator:</b> Energy Fuels Coal, Inc. <b>Operator Address:</b> Mr John Adams P.O. Box 773457 Steamboat Springs, CO 80477	<b>County:</b> Fremont <b>Operation Type:</b> Underground <b>Permit Status:</b> Revoked <b>Ownership:</b> Private
	<b>Operator Representative Present:</b>  None
<b>Operator Representative Signature:</b> (Field Issuance Only)	

**INSPECTION INFORMATION**

<b>Inspection Start Date:</b> December 27, 2020 <b>Inspection Start Time:</b> 13:00 <b>Inspection End Date:</b> December 27, 2020 <b>Inspection End Time:</b> 13:30		<b>Inspection Type:</b> Coal Complete Inspection <b>Inspection Reason:</b> Normal I&E Program <b>Weather:</b> Clear	
<b>Joint Inspection Agency:</b>  None		<b>Joint Inspection Contacts:</b>  None	
<b>Post Inspection Agency:</b>  None		<b>Post Inspection Contacts:</b>  None	
<b>Inspector(s):</b>  Zach Trujillo	<b>Inspector's Signature:</b> 		<b>Signature Date:</b>  12/29/20

## Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection  
N - Availability of Records  
N - Backfill & Grading  
N - Excess Spoil and Dev. Waste  
N - Explosives  
N - Fish & Wildlife  
N - Hydrologic Balance  
N - Gen. Compliance With Mine Plan  
N - Other  
N - Processing Waste

R - Roads  
R - Reclamation Success  
N - Revegetation  
N - Subsidence  
N - Slides and Other Damage  
N - Support Facilities On-site  
N - Signs and Markers  
N - Support Facilities Not On-site  
N - Special Categories Of Mining  
N - Topsoil

## COMMENTS

This was a complete inspection of the Southfield Mine conducted by Zach Trujillo of Colorado Division of Reclamation, Mining and Safety (DRMS) on December 27, 2020. The Southfield Mine was an underground mine which the Division has revoked the bond and terminated the permit. Therefore, no mine operator remains. All bond monies available to the Division will be utilized as needed for reclamation and maintenance activities. The weather was clear and ground conditions were dry. Temperatures during the inspection were around forty degrees fahrenheit.

On November 13, 2018, a meeting was held between the Division and The Corley Company. During this meeting, Dr. Corely, president of The Corley Company, informed the Division that it was best that the Division no longer access the site on the lands owned by The Corely Company. Based upon that meeting, the Division no longer inspects that portion of the Southfield Mine.

### ROADS – Rule 4.03

Construction 4.03.1(3)/4.03.2(3), Drainage 4.03.1(4)/4.03.2(4), Surfacing and Maintenance 4.03.1(5) and (6)/4.03.2(5) and (6), Reclamation 4.03.1(7)/4.03.2(7):

The light use road that was not reclaimed continues to self-heal due to lack of use. Vegetation is establishing itself along the corridor and the area is blending into the adjacent undisturbed areas.

The light use road along the reclaimed substation pad was inspected. Visible vehicle use was observed and it appears that adjacent residents use this road for personal use to access other roads around the site.

### RECLAMATION SUCCESS - Rule 4.15, Rule 3:

Vegetation along the Road Spur is well established and mature. It blends well in the adjacent undisturbed with no issues observed.

Vegetation continues to establish itself along the well pad and its associated access road. No erosion or issues were observed.

The reclaimed substation pad remains stable and well vegetated. No erosion, noxious weeds or issues were observed.

