

Notes:

In Lake Robert the above water areas around the remaining lake area continues to return to near pre-flood conditions except where water scoured soil and vegetation from the land along the river. An armored outlet was built on the north end of Lake Robert in Early 2016 and worked as designed in 2016 when the river again enter the mine area during high water periods. There has been no flooding since the spring of 2016 so no filling has taken place. This Annual Report is the first due after the amendment was approved on 9/24/2019 that added new area, increased the allowed disturbance and increased the bond. The Annual Report maps have been revised to reflect these changes.

(4) Mining continued in areas previously disturbed and material was removed from stockpiled material.

(8) Of the 85.5 acres disturbed approximately 20.7 acres is water surface area does not need reclamation. Another 5.0 acres of river fill area is also included in the total disturbance that needs no reclamation. Under the water sloping is complete in all lake areas but the small section on the north end of the East Lake where mining will resume this year.

(9) No new area was disturbed for mining.