

Zuber - DNR, Rob <rob.zuber@state.co.us>

KEENESBURG REPORT

1 message

Zuber - DNR, Rob <rob.zuber@state.co.us>
To: "Moline, Ben"

>ben.moline@molsoncoors.com>

Tue, Feb 23, 2021 at 5:20 PM

Ben -

Please see attached report from my inspection today. In our earlier correspondence, I did not mention the sign. It still needs information for the Division.

Best of luck with your mom.

Talk to you soon. Rob

Rob Zuber, P.E. Environmental Protection Specialist II Active Mines Regulatory Program



P 303.866.3567, extension 8113 | Cell 720.601.2276 1313 Sherman Street, Room 215, Denver, CO 80203 rob.zuber@state.co.us | http://mining.state.co.us

INSP-REPORTC_C1981028_RDZ_02232021045752.pdf 1492K



PERMIT INFORMATION

Permit Number: C-1981-028 Mine Name: Keenesburg Strip Mine Operator: Coors Energy Company Operator Address: Mr. Ben Moline PO Box 4030 Golden, CO 80402	County: Weld Operation Type: Surface Permit Status: Permanent Cessation Ownership: Private Operator Representative Present: None		
Operator Representative Signature: (Field Issuance Only)			

INSPECTION INFORMATION

Inspection Start Date: February 23, 2021 Inspection Start Time: 09:30 Inspection End Date: February 23, 2021 Inspection End Time: 11:00			Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Clear	
Joint Inspection Agency: Join		Joint	oint Inspection Contacts:	
None				
Post Inspection Agency: P		Post	Post Inspection Contacts:	
None				
Inspector(s):	Inspector's Signature: Signature Dat		ature Date:	
Robert Zuber, P.E.	Phot D. The			
			2/2	23/2021

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

Y - Air Resource Protection NA - Roads

N - Availability of Records R - Reclamation Success

NA - Backfill & Grading N - Revegetation

NA - Excess Spoil and Dev. Waste

NA - Subsidence

NA - Explosives Y - Slides and Other Damage
R - Fish & Wildlife R - Support Facilities On-site
R - Hydrologic Balance R - Signs and Markers

R - Gen. Compliance With Mine Plan
 N - Other
 NA - Support Facilities Not On-site
 NA - Special Categories Of Mining

NA - Processing Waste NA - Topsoil

COMMENTS

A partial inspection was conducted by Rob Zuber of DRMS. No Coors Energy Company (CEC) representatives participated in the inspection. The site is in Permanent Cessation. Reclamation activities (including seeding) were completed in the fall of 2020.

The weather was clear and windy, and it was warm for February.

FISH and WILDLIFE - Rule 4.18:

One owl and other birds were seen around the ponds. No coyotes were seen.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Both Sediment Pond 2 and the Dugout Pond were essentially empty. Neither pond was discharging during the inspection. There were no signs that they had discharged recently. As usual, they both contained large amounts of riparian vegetation. No problems were observed with the two ponds except for **two holes in the embankment at Sediment Pond 2** (each approximately 10 inches deep). These should be filled.

GENERAL MINE PLAN COMPLIANCE:

The eastern portion of the northern boundary of the site (including the ditch to Sediment Pond 2) was observed, and no signs of pollutant loading from the mine site, or any other problems, were seen.

The entire southern boundary was observed, and no issues were identified.

RECLAMATION SUCCESS - Rule 4.15, Rule 3:

Most of the site was walked (all except northwest corner and B Pit), and no erosion or other problems were seen. This includes:

- * The older reclamation near the southwest corner of the current permit area (Areas 29 and 30)
- * Area 25 west of the Dugout Pond
- * Area 33 along the southern permit boundary
- * The areas that were reclaimed in 2019 and 2020, including roads, the Long Term Spoil Area, and the footprints of old soil piles
- * Area 34 at the southeast part of the site.
- * The relatively steep slope between the Dugout Pond and the area where topsand was stored (south of facilities).

SUPPORT FACILITIES - Rule 4.04:

No problems were seen at the facilities area. The garage was being used by a third party. This was approved by Coors Energy, as confirmed by Ben Moline via telephone.

SIGNS AND MARKERS - Rule 4.02:

The entrance sign still lacks contact information for DRMS (including division name, address and telephone number). This should be remedied.

No problems were identified with boundary markers; they were seen in many locations.

DOCUMENTS RECEIVED - none

OTHER (SPECIFY) - none

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



North side of site, looking west from Sediment Pond ${\bf 2}$



Area 42, looking northwest



Area 33 (right side of photo)



Southwest corner of permit area (Area 29)



Area 34 to right and reclaimed topsoil area to left (marker is northwest corner of Area 34)



Dugout Pond to left and reclaimed topsoil area to right