


PERMIT INFORMATION

Permit Number: C-1982-056 Mine Name: Foidel Creek Mine Operator: Twentymile Coal, LLC Operator Address: Ms Miranda Kawcak 29515 Routt County Road No. 27 Oak Creek, CO 80467	County: Routt Operation Type: Underground Permit Status: Active Ownership: Private
	Operator Representative Present: None
Operator Representative Signature: (Field Issuance Only)	

INSPECTION INFORMATION

Inspection Start Date: March 2, 2021 Inspection Start Time: 12:15 Inspection End Date: March 2, 2021 Inspection End Time: 12:30		Inspection Type: Aerial Inspection Inspection Reason: Normal I&E Program Weather: Clear	
Joint Inspection Agency: None		Joint Inspection Contacts:	
Post Inspection Agency: None		Post Inspection Contacts:	
Inspector(s): Tabetha Lynch Brock Bowles	Inspector's Signature: 		Signature Date: 3/5/2021

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

Y - Air Resource Protection
N - Availability of Records
N - Backfill & Grading
Y - Excess Spoil and Dev. Waste
N - Explosives
N - Fish & Wildlife
Y - Hydrologic Balance
R - Gen. Compliance With Mine Plan
N - Other
Y - Processing Waste

Y - Roads
N - Reclamation Success
N - Revegetation
N - Subsidence
N - Slides and Other Damage
Y - Support Facilities On-site
N - Signs and Markers
N - Support Facilities Not On-site
N - Special Categories Of Mining
Y - Topsoil

COMMENTS

This was an aerial inspection of the Foidel Creek Mine; DRMS Permit No. C-1982-056, operated by Twentymile Coal, LLC. (TC). The photos were taken by Brock Bowles on 3/2 and the inspection report was written by Tabettha Lynch with the Colorado Division of Reclamation, Mining, and Safety (Division). The weather was clear and the site was snow covered during the inspection.

GENERAL MINE PLAN COMPLIANCE:

Mine facilities area is pictured below, looking east. Ponds appear to be mostly covered with the exception of the pit pond. Waste pile appears active, stable, and on the third lift. Topsoil piles appear stable, snow covered, and undisturbed. Roads appear to be plowed in facilities area.





Above is the road the 6 Main North and the passive treatment ponds near the 6MN reservoir and pad. Road appears to be plowed, no issues are noted. Topsoil piles along the road appear undisturbed. Passive treatment ponds are snow covered and appear inactive.



West end of facilities area and waste pile is pictured above. Topsoil piles in this area appear stable and undisturbed. Ponds are mostly snow covered. Roads appear well maintained. No issues were noted as a result of this inspection.

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.