




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Hall Pit	MINE/PROSPECTING ID#: M-1983-142	MINERAL: Sand and gravel	COUNTY: Mesa
INSPECTION TYPE: Monitoring	INSPECTOR(S): Amy Yeldell	INSP. DATE: March 17, 2021	INSP. TIME: 11:00
OPERATOR: Oldcastle SW Group, Inc. dba United Compas County	OPERATOR REPRESENTATIVE: Tyra Burtuska	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: \$22,152.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: DRMS	JOINT INSP. AGENCY: None	
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: March 23, 2021	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>NA</u>	(SF) PROCESSING FACILITIES----- <u>Y</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(ST) STIPULATIONS----- <u>Y</u>
(AT) ACID OR TOXIC MATERIALS----- <u>Y</u>	(OD) OFF-SITE DAMAGE----- <u>Y</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Colorado Division of Reclamation, Mining and Safety normal monitoring program. The Hall Pit is a 112c permitted site located off B ½ Road, approximately two miles south of Clifton, Colorado in Mesa County. Amy Yeldell of the Division conducted the inspection. Tyra Bartuska represented Oldcastle SW Group, Inc. dba United Companies of Mesa County and was present for the inspection

The permitted area is 50 acres, with a maximum disturbance of 9.4 acres. The Hall Pit is located adjacent to the BLM Pit No. 1 (M-2001-100) also permitted by Oldcastle. The mine identification sign and affected area boundary markers are in place and in compliance with Rule 3.1.12. The sign is located at the main pit entrance on the shared access gate. A scale and scale house remain in place along the access road. The pit was inactive at the time of the inspection and appears to be in an idol state. Commencement of final reclamation has not been declared.

A screen was located on site, but no other processing equipment was present. No fuel or other debris was located on site. All slopes have been graded to 3H: 1 V or less. According to the 2020 annual report 7 acres are currently affected and anticipated to be reclaimed in the next year. There are several stockpiles of processed material on site that will need to be removed. A small stockpile on the northeast corner of the affected lands appears to be "topsoil" though the material is poor in quality. Given the arid nature of this location noxious weeds need to be aggressively managed. The Operator may also wish to revise the seed mix and select or more arid adapted species, comparable to what is growing on the adjacent undisturbed areas.

The site appeared to be stable with no evidence of excessive erosion or ponding of water. Given the time of year no noxious weeds were observed actively growing.

The Division currently requires a financial warranty amount of \$22, 152 for this site. The bond was last recalculated with SI-1 in 2008. In an effort to ensure the Financial Warranty adequately, reflects the actual current cost of fulfilling the requirements of the approved reclamation plan the Division will be updating the reclamation cost estimate. If the current bond is found to be insufficient the Division will send a Notice of Surety Increase under a separate cover.

Responses to this inspection report should be directed to: Amy Yeldell at the Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. Direct contact can be made by phone at 303-866-3567 Ext 8183 or via email at amy.yeldell@state.co.us

PHOTOGRAPHS







Inspection Contact Address

Jason Burkey
Oldcastle SW Group, Inc. dba United Companies of Mesa County
2273 River Road
Grand Junction, CO 81505

Enclosure

EC:
Travis Marshall, Senior EPS, Grand Junction DRMS
Tyra Bartuska, Operator