

QUARTERLY POND INSPECTION REPORT

Operator:	ARC McClane Canyon LLC	Quarter:	First 2021
Mine:	McClane Canyon Mine C-1980-004	Inspection Date:	30-Mar-21

Pond Identification

Sediment					
Pond					

Status During Inspection:

Approximate Water Level	Pools				
Sediment (% total storage)	100%				
Outflow (cfs)	0				

Features

Problem					
Yes/No					

Erosional

Rills & Gulleys	No				
Inadequate Vegetation	No				
Outlet Channel Erosion	No				
Burrows	No				
Other	No				

Structural

Differential Settling	No				
Cracks or Slides	No				
Seepage	No				
Other	No				

Appurtenant Structures

Defective Spillways	No				
Dewatering Devices Clogged	No				
Faulty Gates, Etc.	No				
Other	No				


Additional Comments

Invert of primary spillway is at elevation 5457.00.
 Invert of emergency spillway is at elevation 5462.00.
 Pond bottom about 7' below primary spillway

Maintenance Required:

None

Name of Inspector: Jim Stover



J. E. Stover
 Colorado P. E. 19230 Date