



TRAPPER MINING INC.

April 13, 2021

Ms. Robin Reilley
Environmental Protection Specialist
Colorado Division of Reclamation, Mining, and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

Dear Ms. Robin Reilley:

**RE: Trapper Mining Inc., Permit C-81-010
First Quarter 2021 Sediment Pond Inspections**

All impoundment inspections were conducted by a qualified impoundment inspector. Inspections took place on March 19th through March 21st, of 2021.


There were no maintenance items recorded.

It is assumed that during the inspection of East Pyeatt #1 and East Pyeatt #2 conditions made it difficult to determine the sediment levels. The current sediment level of East Pyeatt #1 has exceeded the 60% sediment level and there is sediment accumulation in the delta of East Pyeatt #2. Trapper plans to clean East Pyeatt #1 and the sediment accumulation in the delta of East Pyeatt #2 as soon as time and weather permits.

Data related to pond capacity is attached. The last column on the table provides an estimate of the remaining capacity in each pond where remaining capacity is defined as the volume remaining after considering the estimated amount of sediment noted during the inspections.

Please contact me if you have any questions.

Sincerely,


Tonia Marie Perkins
CO PE 43864



C: EQ file 118.7

Trapper Mining Inc.
First Quarter 2021
Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 1 Estimated Sediment (acre-feet)	Qtr. 1 Approximate Rem. Capacity (acre-feet)
Far East Buzzard	2.0	0.03	0.02	1.4	0.01	10.00	0.00	0.03
Coyote	30.5	75.1	45.06	26.7	30.04	0.00	0.00	75.10
No Name #2	8.5	8.47	5.08	6.0	3.39	45.00	3.81	4.66
No Name #4	14.5	8.23	4.94	11.7	3.29	10.00	0.82	7.41
No Name #5	6.0	1.03	0.62	4.7	0.41	20.00	0.21	0.82
Johnson #6	9.0	1.80	1.08	7.1	0.72	25.00	0.45	1.35
Johnson #7R	7.0	2.99	1.79	5.2	1.20	35.00	1.05	1.94
Johnson #8	7.0	3.58	2.15	4.6	1.43	35.00	1.25	2.33
Johnson #9	8.5	2.74	1.64	6.6	1.10	20.00	0.55	2.19
Johnson #10	9.0	6.09	3.65	7.0	2.44	25.00	1.52	4.57
West Pyeatt #1	9.0	2.76	1.66	7.0	1.10	45.00	1.24	1.52
West Pyeatt #2	10.0	1.89	1.13	7.3	0.76	40.00	0.76	1.13
Middle Pyeatt #1	10.0	1.40	0.84	8.1	0.56	30.00	0.42	0.98
Middle Pyeatt #2	10.0	1.26	0.76	8.4	0.50	10.00	0.13	1.13
Middle Pyeatt #3	10.0	5.70	3.42	7.9	2.28	30.00	1.71	3.99
East Pyeatt #1	8.0	0.99	0.59	6.5	0.40	40.00	0.40	0.59
East Pyeatt #2	8.0	4.15	2.49	6.1	1.66	45.00	1.87	2.28
East Pyeatt #3	8.0	1.51	0.91	6.8	0.60	40.00	0.60	0.91
Grouse #1	7.5	3.35	2.01	5.7	1.34	40.00	1.34	2.01
Grouse # 2	4.5	0.79	0.47	3.6	0.32	10.00	0.08	0.71
Sage #1	8.0	2.67	1.60	6.4	1.07	10.00	0.27	2.40
Sage #2	7.0	2.07	1.24	5.8	0.83	10.00	0.21	1.86
Oak #1	13.0	1.43	0.86	10.6	0.57	45.00	0.64	0.79
Oak #2	9.5	0.93	0.56	7.7	0.37	5.00	0.05	0.88

Trapper Mining Inc.
First Quarter 2021
Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 1 Estimated Sediment (acre-feet)	Qtr. 1 Approximate Rem. Capacity (acre-feet)
West Flume	10.0	2.35	1.41	7.8	0.94	0.00	0.00	2.35
Middle Flume #1	11.7	0.80	0.48	9.0	0.32	15.00	0.12	0.68
Middle Flume # 3	14.0	3.36	2.02	10.5	1.34	10.00	0.34	3.02
East Middle Flume	13.0	2.56	1.54	9.2	1.02	10.00	0.26	2.30
East Flume	11.3	1.18	0.71	8.5	0.47	15.00	0.18	1.00
Ute	7.0	1.72	1.03	5.2	0.69	45.00	0.77	0.95
Horse	13.3	6.20	3.72	10.3	2.48	55.00	3.41	2.79
West Horse	13.0	2.00	1.20	9.7	0.80	20.00	0.40	1.60
Deal #1	16.8	2.00	1.20	15.1	0.80	45.00	0.90	1.10
Deal #2	6.0	1.66	0.60	3.1	1.06	0.00	0.00	1.66
Deacon #1	14.5	9.00	3.48	7.5	5.52	0.00	0.00	9.00
Deacon #2	12.0	7.03	3.60	7.7	3.43	0.00	0.00	7.03
Jeffway #1	9.0	2.86	1.20	5.3	1.66	0.00	0.00	2.86
Impoundment H	9.5	4.82	2.89	4.9	1.93	5.00	0.24	4.58

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Chris MillerSIGNATURE: Chris MillerDRAINAGE: **FAR EAST BUZZARD**DATE OF INSPECTION: 3-19-21

POND IDENTIFICATION	Far East Buzzard #1			
Approximate water level:	0			
Sediment level (% total storage):	10%			
Outflow (cfs):	0			
Sediment marker (install or replace)	In Place			
Identification sign (install or replace)	In Place			
EROSIONAL:				
Rills and/or gullies on downstream face.	NO			
Rills and/or gullies on upstream face.	NO			
Inadequate vegetation.	NO			
Outlet channel erosion.	NO			
Burrows.	NO			
Erosion of toe.	NO			
Water impounded against downstream toe.	NO			
Other.	NO			
STRUCTURAL:				
Differential settling.	NO			
Cracks, slides, or scarps.	NO			
Seepage (specify location, color, value).	NO			
Defective spillways.	NO			
Other.	-			
APPURTENANT STRUCTURES:				
Defective spillways.	NO			
Dewatering device clogged.	NO			
Cracking or crushing of pipes.	NO			
Other.	-			
COMMENTS:				



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Chris MillerSIGNATURE: Chris MillerDRAINAGE: **COYOTE**DATE OF INSPECTION: 3-19-21

POND IDENTIFICATION	Covote #1
Approximate water level:	3050
Sediment level (% total storage):	0
Outflow (cfs):	0
Sediment marker (install or replace)	N/A
Identification sign (install or replace)	By Blake
EROSIONAL:	
Rills and/or gullies on downstream face.	NO
Rills and/or gullies on upstream face.	NO
Inadequate vegetation.	NO
Outlet channel erosion.	NO
Burrows.	NO
Erosion of toe.	NO
Water impounded against downstream toe.	NO
Other.	-
STRUCTURAL:	
Differential settling.	NO
Cracks, slides, or scarps.	NO
Seepage (specify location, color, value).	NO
Defective spillways.	NO
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	NO
Dewatering device clogged.	NO
Cracking or crushing of pipes.	NO
Other.	-
COMMENTS:	

Sediment level is measured by a fixed surveyed elevation of 6298.11 ft. (9/29/10).



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Chris MillerSIGNATURE: Chris MillerDRAINAGE: **NO NAME**DATE OF INSPECTION: 3-19-21

POND IDENTIFICATION	No Name #2	No Name #4	No Name #5
Approximate water level:	100%	100%	100%
Sediment level (% total storage):	45%	10%	50%
Outflow (cfs):	21 cfs	21 cfs	21 cfs
Sediment marker (install or replace)	No	No	No
Identification sign (install or replace)	No	No	No
EROSIONAL:			
Rills and/or gullies on downstream face.	No	No	No
Rills and/or gullies on upstream face.	No	No	No
Inadequate vegetation.	No	No	No
Outlet channel erosion.	No	No	No
Burrows.	No	No	No
Erosion of toe.	No	No	No
Water impounded against downstream toe.	No	No	No
Other.	-	-	-
STRUCTURAL:			
Differential settling.	No	No	No
Cracks, slides, or scarps.	No	No	No
Seepage (specify location, color, value).	No	No	No
Defective spillways.	No	No	No
Other.	-	-	-
APPURTENANT STRUCTURES:			
Defective spillways.	No	No	No
Dewatering device clogged.	No	No	No
Cracking or crushing of pipes.	No	No	No
Other.	-	-	-
COMMENTS:			

#2: use riser/siphon tube as sediment marker; siphon top = 66%, bottom = 50%.

#4: use riser/siphon tube as sediment marker; siphon top = 75%, bottom = 60%.

#5: 60% level = top of post - 4.5'.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Chris MillerSIGNATURE: Chris MillerDRAINAGE: JOHNSON GULCHDATE OF INSPECTION: 3-19-21

POND IDENTIFICATION	Johnson #6	Johnson #7R	Johnson #8R	Johnson #9R	Johnson #10R
Approximate water level:	100%	100%	100%	100%	100%
Sediment level (% total storage):	85%	35%	35%	20%	25%
Outflow (cfs):	21 CFS	21 CFS	21 CFS	21 CFS	21 CFS
Sediment marker (install or replace)	In Place	Underwater	Underwater	Underwater	Underwater
Identification sign (install or replace)	In Place	In Place	In Place	In Place	In Place
EROSIONAL:					
Rills and/or gullies on downstream face.	NO	NO	NO	NO	NO
Rills and/or gullies on upstream face.	NO	NO	NO	NO	NO
Inadequate vegetation.	NO	NO	NO	NO	NO
Outlet channel erosion.	NO	NO	NO	NO	NO
Burrows.	NO	NO	NO	NO	NO
Erosion of toe.	NO	NO	NO	NO	NO
Water impounded against downstream toe.	NO	NO	NO	NO	NO
Other.	-	-	-	-	-
STRUCTURAL:					
Differential settling.	NO	NO	NO	NO	NO
Cracks, slides, or scarps.	NO	NO	NO	NO	NO
Seepage (specify location, color, value).	NO	NO	NO	NO	NO
Defective spillways.	NO	NO	NO	NO	NO
Other.	-	-	-	-	-
APPURTENANT STRUCTURES:					
Defective spillways.	NO	NO	NO	NO	NO
Dewatering device clogged.	NO	NO	NO	NO	NO
Cracking or crushing of pipes.	NO	NO	NO	NO	NO
Other.	-	-	-	-	-
COMMENTS:					
#6: use riser/siphon tube as sediment marker; siphon top = 90%, top - 1.5' = 60%.					



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Chris MollerSIGNATURE: Chris MollerDRAINAGE: WEST PYEATTDATE OF INSPECTION: 3-19-21

POND IDENTIFICATION	West Pyeatt #1	West Pyeatt #2
Approximate water level:	25' 6"	25' 6"
Sediment level (% total storage):	45%	45%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In place	In place
Identification sign (install or replace)	In place	In place
EROSIONAL:		
Rills and/or gullies on downstream face.	NO	NO
Rills and/or gullies on upstream face.	NO	NO
Inadequate vegetation.	NO	NO
Outlet channel erosion.	NO	NO
Burrows.	NO	NO
Erosion of toe.	NO	NO
Water impounded against downstream toe.	NO	NO
Other.	—	—
STRUCTURAL:		
Differential settling.	NO	NO
Cracks, slides, or scarps.	NO	NO
Seepage (specify location, color, value).	NO	NO
Defective spillways.	NO	NO
Other.	—	—
APPURTENANT STRUCTURES:		
Defective spillways.	NO	NO
Dewatering device clogged.	NO	NO
Cracking or crushing of pipes.	NO	NO
Other.	—	—
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Chris MollerSIGNATURE: Chris MollerDRAINAGE: **MIDDLE PYEATT**DATE OF INSPECTION: 3-19-21

POND IDENTIFICATION	Middle Pyeatt #1	Middle Pyeatt #2	Middle Pyeatt #3
Approximate water level:	100%	100%	100%
Sediment level (% total storage):	30%	100%	30%
Outflow (cfs):	0 cfs	0	0
Sediment marker (install or replace)	In Place	In Place	In Place
Identification sign (install or replace)	In Place	In Place	In Place
EROSIONAL:			
Rills and/or gullies on downstream face.	NO	NO	NO
Rills and/or gullies on upstream face.	NO	NO	NO
Inadequate vegetation.	NO	NO	NO
Outlet channel erosion.	NO	NO	NO
Burrows.	NO	NO	NO
Erosion of toe.	NO	NO	NO
Water impounded against downstream toe.	NO	NO	NO
Other.	-	-	-
STRUCTURAL:			
Differential settling.	NO	NO	NO
Cracks, slides, or scarps.	NO	NO	NO
Seepage (specify location, color, value).	NO	NO	NO
Defective spillways.	NO	NO	NO
Other.	-	-	-
APPURTENANT STRUCTURES:			
Defective spillways.	NO	NO	NO
Dewatering device clogged.	NO	NO	NO
Cracking or crushing of pipes.	NO	NO	NO
Other.	-	-	-
COMMENTS:			



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Chris MillerSIGNATURE: Chris MillerDRAINAGE: **EAST PYEATT**DATE OF INSPECTION: 3-19-21

POND IDENTIFICATION	East Pyeatt #1	East Pyeatt #2	East Pyeatt #3
Approximate water level:	100%	100%	100%
Sediment level (% total storage):	45%	45%	45%
Outflow (cfs):	215	215	215
Sediment marker (install or replace)	Underwater	Underwater	Underwater
Identification sign (install or replace)	In Place	In Place	In Place
EROSIONAL:			
Rills and/or gullies on downstream face.	NO	NO	NO
Rills and/or gullies on upstream face.	NO	NO	NO
Inadequate vegetation.	NO	NO	NO
Outlet channel erosion.	NO	NO	NO
Burrows.	NO	NO	NO
Erosion of toe.	NO	NO	NO
Water impounded against downstream toe.	NO	NO	NO
Other.	-	-	-
STRUCTURAL:			
Differential settling.	NO	NO	NO
Cracks, slides, or scarps.	NO	NO	NO
Seepage (specify location, color, value).	NO	NO	NO
Defective spillways.	NO	NO	NO
Other.	-	-	-
APPURTENANT STRUCTURES:			
Defective spillways.	NO	NO	NO
Dewatering device clogged.	NO	NO	NO
Cracking or crushing of pipes.	NO	NO	NO
Other.	-	-	-
COMMENTS:			



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Chris MillerSIGNATURE: Chris MillerDRAINAGE: **GROUSE GULCH**DATE OF INSPECTION: 3-19-21

POND IDENTIFICATION	Grouse #1	Grouse #2
Approximate water level:	DAY	DAY
Sediment level (% total storage):	40%	10%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	NO	NO
Rills and/or gullies on upstream face.	NO	NO
Inadequate vegetation.	NO	NO
Outlet channel erosion.	NO	NO
Burrows.	NO	NO
Erosion of toe.	NO	NO
Water impounded against downstream toe.	NO	NO
Other.	-	-
STRUCTURAL:		
Differential settling.	NO	NO
Cracks, slides, or scarps.	NO	NO
Seepage (specify location, color, value).	NO	NO
Defective spillways.	NO	NO
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	NO	NO
Dewatering device clogged.	NO	NO
Cracking or crushing of pipes.	NO	NO
Other.	-	-
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Chris MillerSIGNATURE: Chris MillerDRAINAGE: **SAGE GULCH**DATE OF INSPECTION: 3-19-21

POND IDENTIFICATION	Sage #1	Sage #2
Approximate water level:	DRY	DRY
Sediment level (% total storage):	100%	100%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In place	In place
Identification sign (install or replace)	In place	In place
EROSIONAL:		
Rills and/or gullies on downstream face.	NO	NO
Rills and/or gullies on upstream face.	NO	NO
Inadequate vegetation.	NO	NO
Outlet channel erosion.	NO	NO
Burrows.	NO	NO
Erosion of toe.	NO	NO
Water impounded against downstream toe.	NO	NO
Other.	-	-
STRUCTURAL:		
Differential settling.	NO	NO
Cracks, slides, or scarps.	NO	NO
Seepage (specify location, color, value).	NO	NO
Defective spillways.	NO	NO
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	NO	NO
Dewatering device clogged.	NO	NO
Cracking or crushing of pipes.	NO	NO
Other.	-	-
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Chris MillerSIGNATURE: Chris MillerDRAINAGE: OAK GULCHDATE OF INSPECTION: 3-19-21

POND IDENTIFICATION	Oak #1	Oak #2
Approximate water level:	75%	5%
Sediment level (% total storage):	45%	5%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	NO	NO
Rills and/or gullies on upstream face.	NO	NO
Inadequate vegetation.	NO	NO
Outlet channel erosion.	NO	NO
Burrows.	NO	NO
Erosion of toe.	NO	NO
Water impounded against downstream toe.	NO	NO
Other.	-	-
STRUCTURAL:		
Differential settling.	NO	NO
Cracks, slides, or scarps.	NO	NO
Seepage (specify location, color, value).	NO	NO
Defective spillways.	NO	NO
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	NO	NO
Dewatering device clogged.	NO	NO
Cracking or crushing of pipes.	NO	NO
Other.	-	-
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Chris MillerSIGNATURE: Chris MillerDRAINAGE: WEST FLUMEDATE OF INSPECTION: 3-19-21

POND IDENTIFICATION	West Flume #1
Approximate water level:	<u>0</u>
Sediment level (% total storage):	<u>0</u>
Outflow (cfs):	<u>0</u>
Sediment marker (install or replace)	<u>in place</u>
Identification sign (install or replace)	<u>in place</u>
EROSIONAL:	
Rills and/or gullies on downstream face.	<u>NO</u>
Rills and/or gullies on upstream face.	<u>NO</u>
Inadequate vegetation.	<u>NO</u>
Outlet channel erosion.	<u>NO</u>
Burrows.	<u>NO</u>
Erosion of toe.	<u>NO</u>
Water impounded against downstream toe.	<u>NO</u>
Other.	<u>-</u>
STRUCTURAL:	
Differential settling.	<u>NO</u>
Cracks, slides, or scarps.	<u>NO</u>
Seepage (specify location, color, value).	<u>NO</u>
Defective spillways.	<u>NO</u>
Other.	<u>-</u>
APPURTENANT STRUCTURES:	
Defective spillways.	<u>NO</u>
Dewatering device clogged.	<u>NO</u>
Cracking or crushing of pipes.	<u>NO</u>
Other.	<u>-</u>
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Chris MillerSIGNATURE: Chris MillerDRAINAGE: **MIDDLE FLUME**DATE OF INSPECTION: 3-19-21

POND IDENTIFICATION	Middle Flume #1	Middle Flume #3
Approximate water level:	<u>100%</u>	<u>100%</u>
Sediment level (% total storage):	<u>15%</u>	<u>10%</u>
Outflow (cfs):	<u>0</u>	<u>2 cfs</u>
Sediment marker (install or replace)	<u>In Place</u>	<u>In Place</u>
Identification sign (install or replace)	<u>In Place</u>	<u>In Place</u>
EROSIONAL:		
Rills and/or gullies on downstream face.	<u>NO</u>	<u>NO</u>
Rills and/or gullies on upstream face.	<u>NO</u>	<u>NO</u>
Inadequate vegetation.	<u>NO</u>	<u>NO</u>
Outlet channel erosion.	<u>NO</u>	<u>NO</u>
Burrows.	<u>NO</u>	<u>NO</u>
Erosion of toe.	<u>NO</u>	<u>NO</u>
Water impounded against downstream toe.	<u>NO</u>	<u>NO</u>
Other.	<u>-</u>	<u>-</u>
STRUCTURAL:		
Differential settling.	<u>NO</u>	<u>NO</u>
Cracks, slides, or scarps.	<u>NO</u>	<u>NO</u>
Seepage (specify location, color, value).	<u>NO</u>	<u>NO</u>
Defective spillways.	<u>NO</u>	<u>NO</u>
Other.	<u>-</u>	<u>-</u>
APPURTENANT STRUCTURES:		
Defective spillways.	<u>NO</u>	<u>NO</u>
Dewatering device clogged.	<u>NO</u>	<u>NO</u>
Cracking or crushing of pipes.	<u>NO</u>	<u>NO</u>
Other.	<u>-</u>	<u>-</u>
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Chris MillerSIGNATURE: Chris MillerDRAINAGE: EAST MIDDLE FLUMEDATE OF INSPECTION: 3-19-21

POND IDENTIFICATION	East Middle Flume #1
Approximate water level:	99%
Sediment level (% total storage):	10%
Outflow (cfs):	0
Sediment marker (install or replace)	under water
Identification sign (install or replace)	Dr. Miller
EROSIONAL:	
Rills and/or gullies on downstream face.	NO
Rills and/or gullies on upstream face.	NO
Inadequate vegetation.	NO
Outlet channel erosion.	NO
Burrows.	NO
Erosion of toe.	NO
Water impounded against downstream toe.	NO
Other.	-
STRUCTURAL:	
Differential settling.	NO
Cracks, slides, or scarps.	NO
Seepage (specify location, color, value).	NO
Defective spillways.	NO
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	NO
Dewatering device clogged.	NO
Cracking or crushing of pipes.	NO
Other.	-
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Chris MillerSIGNATURE: Chris MillerDRAINAGE: **EAST FLUME**DATE OF INSPECTION: 3-19-21

POND IDENTIFICATION	East Flume #1
Approximate water level:	50%
Sediment level (% total storage):	15%
Outflow (cfs):	0
Sediment marker (install or replace)	Do place
Identification sign (install or replace)	Do place
EROSIONAL:	
Rills and/or gullies on downstream face.	NO
Rills and/or gullies on upstream face.	NO
Inadequate vegetation.	NO
Outlet channel erosion.	NO
Burrows.	NO
Erosion of toe.	NO
Water impounded against downstream toe.	NO
Other.	-
STRUCTURAL:	
Differential settling.	NO
Cracks, slides, or scarps.	NO
Seepage (specify location, color, value).	NO
Defective spillways.	NO
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	NO
Dewatering device clogged.	NO
Cracking or crushing of pipes.	NO
Other.	-
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Chris MillerSIGNATURE: Chris Miller

DRAINAGE: UTE GULCH

DATE OF INSPECTION: 3-20-21

POND IDENTIFICATION	Ute #1	Ute #1	Ute #1
Approximate water level:			
Sediment level (% total storage):			
Outflow (cfs):			
Sediment marker (install or replace)			
Identification sign (install or replace)			
EROSIONAL:			
Rills and/or gullies on downstream face.			
Rills and/or gullies on upstream face.			
Inadequate vegetation.			
Outlet channel erosion.			
Burrows.			
Erosion of toe.			
Water impounded against downstream toe.			
Other.			
STRUCTURAL:			
Differential settling.			
Cracks, slides, or scarps.			
Seepage (specify location, color, value).			
Defective spillways.			
Other.			
APPURTENANT STRUCTURES:			
Defective spillways.			
Dewatering device clogged.			
Cracking or crushing of pipes.			
Other.			
COMMENTS:			



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Chaz MillerSIGNATURE: Chaz MillerDRAINAGE: **HORSE GULCH**DATE OF INSPECTION: 3-20-21

POND IDENTIFICATION	Horse #1		
Approximate water level:	<u>25%</u>		
Sediment level (% total storage):	<u>55%</u>		
Outflow (cfs):	<u>0'</u>		
Sediment marker (install or replace)	<u>No Place</u>		
Identification sign (install or replace)	<u>No Place</u>		
EROSIONAL:			
Rills and/or gullies on downstream face.	<u>NO</u>		
Rills and/or gullies on upstream face.	<u>NO</u>		
Inadequate vegetation.	<u>NO</u>		
Outlet channel erosion.	<u>NO</u>		
Burrows.	<u>NO</u>		
Erosion of toe.	<u>NO</u>		
Water impounded against downstream toe.	<u>NO</u>		
Other.	<u>—</u>		
STRUCTURAL:			
Differential settling.	<u>NO</u>		
Cracks, slides, or scarps.	<u>NO</u>		
Seepage (specify location, color, value).	<u>NO</u>		
Defective spillways.	<u>NO</u>		
Other.	<u>—</u>		
APPURTENANT STRUCTURES:			
Defective spillways.	<u>NO</u>		
Dewatering device clogged.	<u>NO</u>		
Cracking or crushing of pipes.	<u>NO</u>		
Other.	<u>—</u>		
COMMENTS:			



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Chris MillerSIGNATURE: Chris MillerDRAINAGE: **WEST HORSE GULCH**DATE OF INSPECTION: 3-20-21

POND IDENTIFICATION	West Horse #1
Approximate water level:	<u>DAY</u>
Sediment level (% total storage):	<u>25%</u>
Outflow (cfs):	<u>0</u>
Sediment marker (install or replace)	<u>replace</u>
Identification sign (install or replace)	<u>replace</u>
EROSIONAL:	
Rills and/or gullies on downstream face.	<u>NO</u>
Rills and/or gullies on upstream face.	<u>NO</u>
Inadequate vegetation.	<u>NO</u>
Outlet channel erosion.	<u>NO</u>
Burrows.	<u>NO</u>
Erosion of toe.	<u>NO</u>
Water impounded against downstream toe.	<u>NO</u>
Other.	<u>—</u>
STRUCTURAL:	
Differential settling.	<u>NO</u>
Cracks, slides, or scarps.	<u>NO</u>
Seepage (specify location, color, value).	<u>NO</u>
Defective spillways.	<u>NO</u>
Other.	<u>—</u>
APPURTENANT STRUCTURES:	
Defective spillways.	<u>NO</u>
Dewatering device clogged.	<u>NO</u>
Cracking or crushing of pipes.	<u>NO</u>
Other.	<u>—</u>
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Chris MillerSIGNATURE: Chris MillerDRAINAGE: DEAL GULCHDATE OF INSPECTION: 3-20-21

POND IDENTIFICATION	Deal #1	Deal #2
Approximate water level:	75%	NO
Sediment level (% total storage):	45%	normal
Outflow (cfs):	0	0
Sediment marker (install or replace)	NO	NO
Identification sign (install or replace)	NO	NO
EROSIONAL:		
Rills and/or gullies on downstream face.	NO	NO
Rills and/or gullies on upstream face.	NO	NO
Inadequate vegetation.	NO	NO
Outlet channel erosion.	NO	NO
Burrows.	NO	NO
Erosion of toe.	NO	NO
Water impounded against downstream toe.	NO	NO
Other.	—	—
STRUCTURAL:		
Differential settling.	NO	NO
Cracks, slides, or scarps.	NO	NO
Seepage (specify location, color, value).	NO	NO
Defective spillways.	NO	NO
Other.	—	—
APPURTENANT STRUCTURES:		
Defective spillways.	NO	NO
Dewatering device clogged.	NO	NO
Cracking or crushing of pipes.	NO	NO
Other.	—	—
COMMENTS:		



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Chris MillerSIGNATURE: Chris MillerDRAINAGE: DEACONDATE OF INSPECTION: 3-20-21

POND IDENTIFICATION	Deacon #1	Deacon #2
Approximate water level:	High	High
Sediment level (% total storage):	0	0
Outflow (cfs):	0	0
Sediment marker (install or replace)	No place	No place
Identification sign (install or replace)	No place	No place
EROSIONAL:		
Rills and/or gullies on downstream face.	NO	NO
Rills and/or gullies on upstream face.	NO	NO
Inadequate vegetation.	NO	NO
Outlet channel erosion.	NO	NO
Burrows.	NO	NO
Erosion of toe.	NO	NO
Water impounded against downstream toe.	NO	NO
Other.	—	—
STRUCTURAL:		
Differential settling.	NO	NO
Cracks, slides, or scarps.	NO	NO
Seepage (specify location, color, value).	NO	NO
Defective spillways.	NO	NO
Other.	—	—
APPURTENANT STRUCTURES:		
Defective spillways.	NO	NO
Dewatering device clogged.	NO	NO
Cracking or crushing of pipes.	NO	NO
Other.	—	—
COMMENTS:		



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR:

Chris Miller

SIGNATURE:

Chris Miller

DRAINAGE: JEFFWAY

DATE OF INSPECTION:

3-20-21

POND IDENTIFICATION	Jeffway #1			
Approximate water level:	10%			
Sediment level (% total storage):	0			
Outflow (cfs):	0			
Sediment marker (install or replace)	replace			
Identification sign (install or replace)	replace			
EROSIONAL:				
Rills and/or gullies on downstream face.	NO			
Rills and/or gullies on upstream face.	NO			
Inadequate vegetation.	NO			
Outlet channel erosion.	NO			
Burrows.	NO			
Erosion of toe.	NO			
Water impounded against downstream toe.	NO			
Other.	-			
STRUCTURAL:				
Differential settling.	NO			
Cracks, slides, or scarps.	NO			
Seepage (specify location, color, value).	NO			
Defective spillways.	NO			
Other.	-			
APPURTENANT STRUCTURES:				
Defective spillways.	NO			
Dewatering device clogged.	NO			
Cracking or crushing of pipes.	NO			
Other.	-			
COMMENTS:				



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

1st QUARTER 2021

INSPECTOR: Chris MillerSIGNATURE: Chris MillerDRAINAGE: **IMPOUNDMENT H**DATE OF INSPECTION: 3-21-21

POND IDENTIFICATION	Impoundment H
Approximate water level:	5' 6"
Sediment level (% total storage):	5%
Outflow (cfs):	0
Sediment marker (install or replace)	Replace
Identification sign (install or replace)	Replace
EROSIONAL:	
Rills and/or gullies on downstream face.	NO
Rills and/or gullies on upstream face.	NO
Inadequate vegetation.	NO
Outlet channel erosion.	NO
Burrows.	NO
Erosion of toe.	NO
Water impounded against downstream toe.	NO
Other.	-
STRUCTURAL:	
Differential settling.	NO
Cracks, slides, or scarps.	NO
Seepage (specify location, color, value).	NO
Defective spillways.	NO
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	NO
Dewatering device clogged.	NO
Cracking or crushing of pipes.	NO
Other.	-
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Chris MillerSIGNATURE: Chris Miller

DRAINAGE: INDUSTRIAL WASTE POND

DATE OF INSPECTION: 3-21-20

POND IDENTIFICATION	Industrial Waste Pond #1
Approximate water level:	90%
Sediment level (% total storage):	5%
Outflow (cfs):	0
Sediment marker (install or replace)	N/A
Identification sign (install or replace)	In place
EROSIONAL:	
Rills and/or gullies on downstream face.	NO
Rills and/or gullies on upstream face.	NO
Inadequate vegetation.	NO
Outlet channel erosion.	NO
Burrows.	NO
Erosion of toe.	NO
Water impounded against downstream toe.	NO
Other.	-
STRUCTURAL:	
Differential settling.	NO
Cracks, slides, or scarps.	NO
Seepage (specify location, color, value).	NO
Defective spillways.	NO
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	N/A
Dewatering device clogged.	N/A
Cracking or crushing of pipes.	N/A
Other.	-
COMMENTS:	

