


**PERMIT INFORMATION**

<b>Permit Number:</b> C-1982-056 <b>Mine Name:</b> Foidel Creek Mine <b>Operator:</b> Twentymile Coal, LLC <b>Operator Address:</b> Ms Miranda Kawcak 29515 Routt County Road No. 27 Oak Creek, CO 80467	<b>County:</b> Routt <b>Operation Type:</b> Underground <b>Permit Status:</b> Active <b>Ownership:</b> Private
<b>Operator Representative Present:</b>	
<b>Operator Representative Signature:</b> (Field Issuance Only)	

**INSPECTION INFORMATION**

<b>Inspection Start Date:</b> May 12, 2021 <b>Inspection Start Time:</b> 09:30 <b>Inspection End Date:</b> May 12, 2021 <b>Inspection End Time:</b> 09:45	<b>Inspection Type:</b> Aerial Inspection <b>Inspection Reason:</b> Normal <b>Weather:</b> Clear
<b>Joint Inspection Agency:</b>  None	<b>Joint Inspection Contacts:</b>
<b>Post Inspection Agency:</b>  None	<b>Post Inspection Contacts:</b>
<b>Inspector(s):</b>  Tabetha Lynch	<b>Inspector's Signature:</b>  <b>Signature Date:</b>  5/17/21

## Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

Y - Air Resource Protection  
N - Availability of Records  
N - Backfill & Grading  
Y - Excess Spoil and Dev. Waste  
N - Explosives  
Y - Fish & Wildlife  
R - Hydrologic Balance  
R - Gen. Compliance With Mine Plan  
N - Other  
Y - Processing Waste

Y - Roads  
N - Reclamation Success  
N - Revegetation  
N - Subsidence  
Y - Slides and Other Damage  
Y - Support Facilities On-site  
Y - Signs and Markers  
NA - Support Facilities Not On-site  
NA - Special Categories Of Mining  
Y - Topsoil

## COMMENTS

This was an aerial inspection of the Foidel Creek Mine; DRMS Permit No. C-1982-056, operated by Twentymile Coal, LLC. (TC). The photos were taken by Brock Bowles on 5/12 and the inspection report was written by Tabetha Lynch with the Colorado Division of Reclamation, Mining, and Safety (Division).

### HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Ponds are holding water, but appear lower than average for the time of year. Pond G shown below, with Foidel Creek at the top and topsoil pile at the bottom of the photo.



### GENERAL MINE PLAN COMPLIANCE:

Photo below shows Pond E at the top right, pit pond middle left and pond D just above. The wash plant and thickener tank are mid photo. Topsoil pile is at the bottom of the photo. Part of the waste refuse pile is lower right. No issues are noted from this photo.



Waste pile is pictured above with the truck and train loadout in top right. No issues are noted from this photo. Cattle are on site. Below is shown the passive treatment ponds at 6MN. Stock pond is shown bottom right.



**DOCUMENTS RECEIVED**

**OTHER (SPECIFY)**

**ENFORCEMENT ACTIONS/COMPLIANCE**

No enforcement actions were initiated as a result of this inspection, nor are any pending.