




COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

PERMIT INFORMATION

Permit Number: C-1992-081 Mine Name: Hayden Gulch Loadout Operator: Hayden Gulch Terminal, LLC Operator Address: Ms Miranda Kawcak P.O. Box 670 Hayden, CO 81639	County: Routt Operation Type: Loadout Permit Status: Active Ownership: Private Operator Representative Present: Kevin Copeland
Operator Representative Signature: (Field Issuance Only) 	

INSPECTION INFORMATION

Inspection Start Date: May 13, 2021 Inspection Start Time: 13:30 Inspection End Date: Inspection End Time:		Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Clear	
Joint Inspection Agency: None		Joint Inspection Contacts: 	
Post Inspection Agency: None		Post Inspection Contacts: 	
Inspector(s): Tabetha Lynch	Inspector's Signature: 		Signature Date: 5/18/21

Inspection Topic SummaryNOTE: **Y**=Inspected **N**=Not Inspected **R**=Comments Noted **V**=Violation Issued **NA**=Not Applicable

N - Air Resource Protection	Y - Roads
N - Availability of Records	R - Reclamation Success
Y - Backfill & Grading	N - Revegetation
N - Excess Spoil and Dev. Waste	N - Subsidence
N - Explosives	N - Slides and Other Damage
R - Fish & Wildlife	N - Support Facilities On-site
R - Hydrologic Balance	Y - Signs and Markers
Y - Gen. Compliance With Mine Plan	NA - Support Facilities Not On-site
N - Other	NA - Special Categories Of Mining
N - Processing Waste	Y - Topsoil

COMMENTS

This was a partial inspection of the Hayden Gulch Loadout; DRMS Permit No. C-1992-081, operated by Hayden Gulch Terminal, LLC. The inspection was conducted by Tabet Lynch with the Colorado Division of Reclamation, Mining, and Safety (Division) on 5/13.

No issues were noted as a result of this inspection.

FISH and WILDLIFE – Rule 4.18:

Sandhill cranes were present in the permit area at time of inspection

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

The truck loadout pond was holding water. The train loadout pond was dry. Dry Creek was flowing at the time of inspection.

Irrigation water has been diverted away from the area to reclaim north of Hwy 40.

RECLAMATION SUCCESS - Rule 4.15, Rule 3:

Additional track has been pulled from both sides of Hwy 40. The only track remaining during the inspection was that in Hwy 40.

Photo below is looking north from the north side of Hwy 40

Number of Partial Inspection this Fiscal Year: 8

Number of Complete Inspections this Fiscal Year: 3



Photo below shows remaining track and wiring to be removed.



Photo below is looking southwest across remaining area to be reclaimed on the north side of Hwy 40

Number of Partial Inspection this Fiscal Year: 8

Number of Complete Inspections this Fiscal Year: 3



DOCUMENTS RECEIVED

OTHER (SPECIFY)

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

Number of Partial Inspection this Fiscal Year: 8

Number of Complete Inspections this Fiscal Year: 3