



May 24, 2021

Mr. Zach Trujillo
Environmental Protection Specialist
Colorado Division of Reclamation Mining and Safety
Department of Natural Resources
1313 Sherman Street, Room 215
Denver, CO 80203


RE: Colowyo Coal Mine L.P.
Permit No. C-1981-019
Annual Impoundment Inspections

Dear Mr. Trujillo,

Tri-State Generation and Transmission Association Inc. (Tri-State), is the parent company to Axial Basin Coal Company, which is the general partner to Colowyo Coal Company L.P. Therefore, Tri-State on behalf of Colowyo, and in accordance with Rules 4.05.9(14) and 4.05.9(15), is submitting the enclosed annual impoundment and stock pond inspection reports.

If you should have any additional questions or concerns please feel free to contact Tony Tennyson at (970) 824-1232.

Sincerely,

DocuSigned by:

D250C711D0BF450...

Chris Gilbreath
Senior Manager
Remediation and Reclamation

CG:TT:der
Enclosure

cc: Tony Tennyson (via email)
Angela Aalbers (via email)
CF 17.18/2021
G471-11.3(21)h-4

Colowyo Coal Company L.P.
Permit No. C-1981-019

Annual Impoundment Inspections
2021

	Temporary Facilities Pond	Wilson Storage Pond	Section 36 Pond	Middle Pond	Section 25 Pond	Coal Stockpile	Sidehill Pond	Section 26 Pond
Inspection Date:	5/13/2021	5/13/2021	5/13/2021	5/13/2021	5/13/2021	5/13/2021	5/13/2021	5/13/2021
Inspector:	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale
Rule 4.05.9 (15)(a) Does the pond exhibit erosion, instability, structural weakness, or other hazardous conditions?	No	No	No	No	No	No	No	No
Rule 4.05.9(15)(b) Existing and required monitoring procedures.	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection
Rule 4.05.9(15)(b) Required Instrumentation	Not Applicable - Nondischarging Structure	Not Applicable - Nondischarging Structure	None	None	Parshall flume in place and functioning	Not Applicable - Nondischarging Structure	None	Parshall Flume in Place and scheduled for maintenance
Rule 4.05.9(15)(c) Depth of Impounded Water (ft)*	Dry	Dry	19.0	18.0	12.0	2.0	6.0	11.0
Rule 4.05.9(15)(c) Elevation of Impounded Water (ft)*	Dry	Dry	7124.0	7066.0	6867.0	7212.0	7160.0	6980.0
Rule 4.05.9(15)(d) Existing Storage Capacity (ac- ft)**	0.38	3.23	1.82	0.78	6.61	1.15	2.89	2.00
Rule 4.05.9(15)(e) Any additional items effecting stability or maintenance items	None	None	None	None	None	None	Erosion in inlet Ditch should be addressed	None

* Moment in time measurement of the elevation of the top of the captured pool of water within the pond.

**Impoundments volumes are estimated from pre-existing as-built surveys and estimates of accumulated sediment.

I am a Licensed Professional Engineer in the State of Colorado. The information contained in this document was provided by Colowyo Coal L.P. Being familiar with the Colowyo operation, and relying on the information provided to me by Colowyo Personnel, the information contained herein is reasonable and correct to the best of my knowledge and experience.



Colowyo Coal Company L.P.
Permit No. C-1981-019


Annual Impoundment Inspections
2021

	Streeter Pond	Work Area Pond	Gossard Pond	Stoker Siding Pond	Rail Loop Pond	Prospect Pond	West Pit Pond	Section 16 Pond	East Taylor Pond	West Taylor Pond	Section 28 Pond
Inspection Date:	5/13/2021	5/13/2021	5/13/2021	5/13/2021	5/13/2021	5/13/2021	5/13/2021	5/13/2021	5/13/2021	5/13/2021	5/13/2021
Inspector:	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale
Rule 4.05.9 (15)(a) Does the pond exhibit erosion, instability, structural weakness, or other hazardous conditions?	No	No	No	No	No	No	No	No	No	No	No
Rule 4.05.9(15)(b) Existing and required monitoring procedures.	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection
Rule 4.05.9(15)(b) Required Instrumentation	Parshall Flume In Place and Functioning	Parshall Flume In Place and Functioning	Not Applicable - Nondischarging Structure	Parshall Flume In Place and Functioning	Not Applicable - Nondischarging Structure	Parshall Flume In Place and Functioning	Parshall Flume In Place and Functioning	Parshall Flume In Place and Functioning	Parshall Flume In Place and Functioning	Parshall Flume In Place and Functioning	Parshall Flume In Place and Functioning
Rule 4.05.9(15)(c) Depth of Impounded Water (ft)*	4.8	6.0	6.5	3.0	3.6	2.5	Dry	Dry	14.0	13.0	Dry
Rule 4.05.9(15)(c) Elevation of Impounded Water (ft)*	6583.0	7152.0	6388.3	6325.0	6349.5	6742.0	Dry	Dry	6944.0	7468.0	Dry
Rule 4.05.9(15)(d) Existing Storage Capacity (ac-ft)**	1.70	9.54	2.47	0.33	0.57	0.90	4.31	1.14	2.52	1.33	1.67
Rule 4.05.9(15)(e) Any additional items effecting stability or maintenance items	None	Parshall Flume Scheduled for Replacement.	None	None	None	None	None	None	None	None	None

* Moment in time measurement of the elevation of the top of the captured pool of water within the pond.

**Impoundments volumes are estimated from pre-existing as-built surveys and estimates of accumulated sediment.

I am a Licensed Professional Engineer in the State of Colorado. The information contained in this document was provided by Colowyo Coal L.P. Being familiar with the Colowyo operation, and relying on the information provided to me by Colowyo Personnel, the information contained herein is reasonable and correct to the best of my knowledge and experience.



Colowyo Coal Company L.P.
Permit No. C-1981-019

Annual Stock Pond Inspections
2021

	PD1	PD2	NTEP1	EP1	EP2	TD1	TD2	ETD1
Inspection Date:	5/13/2021	5/13/2021	5/13/2021	5/13/2021	5/13/2021	5/13/2021	5/13/2021	5/13/2021
Inspector:	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale	Trevor Ragsdale
Rule 4.05.9 (15)(a) Does the pond exhibit erosion, instability, structural weakness, or other hazardous conditions?	No	No	No	No	No	No	No	No
Rule 4.05.9(15)(b) Existing and required monitoring procedures.	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection	Annual Inspection
Rule 4.05.9(15)(b) Required Instrumentation	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable
Rule 4.05.9(15)(c) Depth of Impounded Water (ft)*	6.0	3.0	0.5	5.8	11.0	2.5	10.0	2.0
Rule 4.05.9(15)(c) Elevation of Impounded Water (ft)*	7354.0	7559.0	7378.5	7375.8	7495.0	7285.5	7453.0	7285.0
Rule 4.05.9(15)(d) Existing Storage Capacity (ac-ft)**	0.91	1.44	1.96	1.16	2.02	0.69	2.28	0.85
Rule 4.05.9(15)(e) Any additional items effecting stability or maintenance items	Impounded water scheduled to be pumped	Impounded water scheduled to be pumped	None	None	Secondary Discharge Pipe installation scheduled	None	None	None

* Moment in time measurement of the elevation of the top of the captured pool of water within the pond.

**Impoundments volumes are estimated from pre-existing as-built surveys and estimates of accumulated sediment.

I am a Licensed Professional Engineer in the State of Colorado. The information contained in this document was provided by Colowyo Coal L.P. Being familiar with the Colowyo operation, and relying on the information provided to me by Colowyo Personnel, the information contained herein is reasonable and correct to the best of my knowledge and experience.

