



TRAPPER MINING INC.

June 18, 2021

Ms. Robin Reilley
Environmental Protection Specialist
Colorado Division of Reclamation, Mining, and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

Dear Ms. Robin Reilley:

**RE: Trapper Mining Inc., Permit C-81-010
Second Quarter 2021 Sediment Pond Inspections**

All impoundment inspections were conducted by a qualified impoundment inspector. Inspections took place on May 25th, May 26th, June 17th, and June 14th, of 2021.

Maintenance items noted during the inspections were as follows:


- ID sign for East Pyeatt #2 needs to be reattached.
- East Pyeatt #1 needs to be cleaned.
- East Pyeatt #2 needs to be cleaned.
- ID sign at Sage #2 needs to be replaced.
- Sediment marker at Deal #1 needs to be replaced.
- Sediment marker at Jeffway#1 needs to be replaced.

Trapper will address these maintenance items in a timely matter.

Data related to pond capacity is attached. The last column on the table provides an estimate of the remaining capacity in each pond where remaining capacity is defined as the volume remaining after considering the estimated amount of sediment noted during the inspections. Survey data confirmed the sediment amounts for No Name #2 and East Pyeatt #3 are lower than reported in the previous inspection.

Please contact me if you have any questions.

Sincerely,


Tonia Marie Perkins
CO PE 43864

C: EQ file 118.7



Trapper Mining Inc.
Second Quarter 2021
Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 2 Estimated Sediment (acre-feet)	Qtr. 2 Approximate Rem. Capacity (acre-feet)
Far East Buzzard	2.0	0.03	0.02	1.4	0.01	10.00	0.00	0.03
Coyote	30.5	75.1	45.06	26.7	30.04	0.00	0.00	75.10
No Name #2	8.5	8.47	5.08	6.0	3.39	20.00	1.69	6.78
No Name #4	14.5	8.23	4.94	11.7	3.29	10.00	0.82	7.41
No Name #5	6.0	1.03	0.62	4.7	0.41	20.00	0.21	0.82
Johnson #6	9.0	1.80	1.08	7.1	0.72	25.00	0.45	1.35
Johnson #7R	7.0	2.99	1.79	5.2	1.20	35.00	1.05	1.94
Johnson #8	7.0	3.58	2.15	4.6	1.43	35.00	1.25	2.33
Johnson #9	8.5	2.74	1.64	6.6	1.10	20.00	0.55	2.19
Johnson #10	9.0	6.09	3.65	7.0	2.44	25.00	1.52	4.57
West Pyeatt #1	9.0	2.76	1.66	7.0	1.10	45.00	1.24	1.52
West Pyeatt #2	10.0	1.89	1.13	7.3	0.76	40.00	0.76	1.13
Middle Pyeatt #1	10.0	1.40	0.84	8.1	0.56	30.00	0.42	0.98
Middle Pyeatt #2	10.0	1.26	0.76	8.4	0.50	10.00	0.13	1.13
Middle Pyeatt #3	10.0	5.70	3.42	7.9	2.28	30.00	1.71	3.99
East Pyeatt #1	8.0	0.99	0.59	6.5	0.40	95.00	0.94	0.05
East Pyeatt #2	8.0	4.15	2.49	6.1	1.66	85.00	3.53	0.62
East Pyeatt #3	8.0	1.51	0.91	6.8	0.60	25.00	0.38	1.13
Grouse #1	7.5	3.35	2.01	5.7	1.34	40.00	1.34	2.01
Grouse # 2	4.5	0.79	0.47	3.6	0.32	10.00	0.08	0.71
Sage #1	8.0	2.67	1.60	6.4	1.07	10.00	0.27	2.40
Sage #2	7.0	2.07	1.24	5.8	0.83	10.00	0.21	1.86
Oak #1	13.0	1.43	0.86	10.6	0.57	45.00	0.64	0.79
Oak #2	9.5	0.93	0.56	7.7	0.37	5.00	0.05	0.88

Trapper Mining Inc.
Second Quarter 2021
Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 2 Estimated Sediment (acre-feet)	Qtr. 2 Approximate Rem. Capacity (acre-feet)
West Flume	10.0	2.35	1.41	7.8	0.94	0.00	0.00	2.35
Middle Flume #1	11.7	0.80	0.48	9.0	0.32	20.00	0.16	0.64
Middle Flume # 3	14.0	3.36	2.02	10.5	1.34	35.00	1.18	2.18
East Middle Flume	13.0	2.56	1.54	9.2	1.02	10.00	0.26	2.30
East Flume	11.3	1.18	0.71	8.5	0.47	15.00	0.18	1.00
Ute	7.0	1.72	1.03	5.2	0.69	45.00	0.77	0.95
Horse	13.3	6.20	3.72	10.3	2.48	55.00	3.41	2.79
West Horse	13.0	2.00	1.20	9.7	0.80	20.00	0.40	1.60
Deal #1	16.8	2.00	1.20	15.1	0.80	55.00	1.10	0.90
Deal #2	6.0	1.66	0.60	3.1	1.06	0.00	0.00	1.66
Deacon #1	14.5	9.00	3.48	7.5	5.52	0.00	0.00	9.00
Deacon #2	12.0	7.03	3.60	7.7	3.43	0.00	0.00	7.03
Jeffway #1	9.0	2.86	1.20	5.3	1.66	0.00	0.00	2.86
Impoundment H	9.5	4.82	2.89	4.9	1.93	5.00	0.24	4.58

TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Graham RobertsSIGNATURE: *Sh Roberts*DRAINAGE: **FAR EAST BUZZARD**DATE OF INSPECTION: 5-25-21

POND IDENTIFICATION	Far East Buzzard #1
Approximate water level:	
Sediment level (% total storage):	0%
Outflow (cfs):	10%
Sediment marker (install or replace)	0 cfs
Identification sign (install or replace)	In place
	In place
EROSIONAL:	
Rills and/or gullies on downstream face.	No
Rills and/or gullies on upstream face.	No
Inadequate vegetation.	No
Outlet channel erosion.	No
Burrows.	Minimal
Erosion of toe.	No
Water impounded against downstream toe.	No
Other.	-
STRUCTURAL:	
Differential settling.	No
Cracks, slides, or scarps.	No
Seepage (specify location, color, value).	No
Defective spillways.	No
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	No
Dewatering device clogged.	NA
Cracking or crushing of pipes.	NA
Other.	-
COMMENTS:	



TRAPPER MINING INC. QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Graham RobertsSIGNATURE: *Graham Roberts*DRAINAGE: **COYOTE**DATE OF INSPECTION: 5-25-21

POND IDENTIFICATION	Coyote #1		
Approximate water level:	<u>10%</u>		
Sediment level (% total storage):	<u>min</u>		
Outflow (cfs):	<u>0 cfs</u>		
Sediment marker (install or replace)	<u>N/A</u>		
Identification sign (install or replace)	<u>In place</u>		
EROSIONAL:			
Rills and/or gullies on downstream face.	<u>No</u>		
Rills and/or gullies on upstream face.	<u>No</u>		
Inadequate vegetation.	<u>No</u>		
Outlet channel erosion.	<u>No</u>		
Burrows.	<u>No</u>		
Erosion of toe.	<u>No</u>		
Water impounded against downstream toe.	<u>No</u>		
Other.			
STRUCTURAL:			
Differential settling.	<u>No</u>		
Cracks, slides, or scarps.	<u>No</u>		
Seepage (specify location, color, value).	<u>No</u>		
Defective spillways.	<u>No</u>		
Other.	<u>-</u>		
APPURTENANT STRUCTURES:			
Defective spillways.	<u>No</u>		
Dewatering device clogged.	<u>No</u>		
Cracking or crushing of pipes.	<u>No</u>		
Other.	<u>-</u>		
COMMENTS:			

Sediment level is measured by a fixed surveyed elevation of 6298.11 ft. (9/29/10).

New primary spillway modifications complete.

TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR:

Tonia Perkins

DRAINAGE: NO NAME

SIGNATURE:

Donna Perkins

DATE OF INSPECTION:

5/25/2021

POND IDENTIFICATION	No Name #2	No Name #4	No Name #5
Approximate water level:	100%	100%	100%
Sediment level (% total storage):	20%	10%	20%
Outflow (cfs):	21CFS	41CFS	21CFS
Sediment marker (install or replace)	In Place	In Place	In Place
Identification sign (install or replace)	In Place	In Place	In Place
EROSIONAL:			
Rills and/or gullies on downstream face.	NO	NO	NO
Rills and/or gullies on upstream face.	NO	NO	NO
Inadequate vegetation.	NO	NO	NO
Outlet channel erosion.	NO	NO	NO
Burrows.	NO	NO	NO
Erosion of toe.	NO	NO	NO
Water impounded against downstream toe.	NO	NO	NO
Other.	-	-	-
STRUCTURAL:			
Differential settling.	NO	NO	NO
Cracks, slides, or scarps.	NO	NO	NO
Seepage (specify location, color, value).	NO	NO	NO
Defective spillways.	NO	NO	NO
Other.	-	-	-
APPURTENANT STRUCTURES:			
Defective spillways.	NO	NO	NO
Dewatering device clogged.	NO	NO	NO
Cracking or crushing of pipes.	NO	NO	NO
Other.	-	-	-
COMMENTS:			

#2: use riser/siphon tube as sediment marker; siphon top = 66%, bottom = 50%.

#4: use riser/siphon tube as sediment marker; siphon top = 75%, bottom = 60%.

#5: 60% level = top of post - 4.5'.

- Some vegetation is outflow of No Name #5,
 but it is not interrupting water flow.



TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR:

Tonia Perkins

SIGNATURE:

Tonia Perkins

DRAINAGE: JOHNSON GULCH

DATE OF INSPECTION:

5/25/2021

POND IDENTIFICATION	Johnson #6	Johnson #7R	Johnson #8R	Johnson #9R	Johnson #10R
Approximate water level:	100%.	100%.	100%.	100%.	100%.
Sediment level (% total storage):	25%.	35%.	35%.	20%.	25%.
Outflow (cfs):	21 CFS	21 CFS	21 CFS	21 CFS	21 CFS
Sediment marker (install or replace)	Under Water	Under Water	Under Water	Under Water	Under Water
Identification sign (install or replace)	In Place	In Place	In Place	In Place	In Place
EROSIONAL:					
Rills and/or gullies on downstream face.	no	no	no	no	no
Rills and/or gullies on upstream face.	no	no	no	no	no
Inadequate vegetation.	no	no	no	no	no
Outlet channel erosion.	no	no	no	no	no
Burrows.	no	no	no	no	no
Erosion of toe.	no	no	no	no	no
Water impounded against downstream toe.	no	no	no	no	no
Other.	—	—	—	—	—
STRUCTURAL:					
Differential settling.	no	no	no	no	no
Cracks, slides, or scarps.	no	no	no	no	no
Seepage (specify location, color, value).	no	no	no	no	no
Defective spillways.	no	no	no	no	no
Other.	—	—	—	—	—
APPURTENANT STRUCTURES:					
Defective spillways.	no	no	no	no	no
Dewatering device clogged.	no	no	no	no	no
Cracking or crushing of pipes.	no	no	no	no	no
Other.	—	—	—	—	—
COMMENTS:					

#6: use riser/siphon tube as sediment marker; siphon top = 90%, top - 1.5' = 60%.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Sean HovorkaSIGNATURE: Sean HovorkaDRAINAGE: WEST PYEATTDATE OF INSPECTION: 6-17-21

POND IDENTIFICATION	West Pyeatt #1	West Pyeatt #2
Approximate water level:	Dry	
Sediment level (% total storage):	45%	Dry 40%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	No	No
Rills and/or gullies on upstream face.	No	No
Inadequate vegetation.	No	No
Outlet channel erosion.	No	No
Burrows.	No	No
Erosion of toe.	No	No
Water impounded against downstream toe.	No	No
Other.	-	-
STRUCTURAL:		
Differential settling.	No	No
Cracks, slides, or scarps.	No	No
Seepage (specify location, color, value).	No	No
Defective spillways.	No	No
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	No	No
Dewatering device clogged.	No	No
Cracking or crushing of pipes.	No	No
Other.	-	-
COMMENTS:		



TRAPPER MINING INC. QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Sean HovorkaSIGNATURE: Sean HovorkaDRAINAGE: MIDDLE PYEATTDATE OF INSPECTION: 6-17-21

POND IDENTIFICATION	Middle Pyeatt #1	Middle Pyeatt #2	Middle Pyeatt #3
Approximate water level:	Dry		
Sediment level (% total storage):	38%	Dry 61%	Dry 30%
Outflow (cfs):	0	0	0
Sediment marker (install or replace)	In Place	In Place	In Place
Identification sign (install or replace)	In Place	In Place	In Place
EROSIONAL:			
Rills and/or gullies on downstream face.	No	No	No
Rills and/or gullies on upstream face.	No	No	No
Inadequate vegetation.	No	No	No
Outlet channel erosion.	No	No	No
Burrows.	No	No	No
Erosion of toe.	No	No	No
Water impounded against downstream toe.	No	No	No
Other.	-	-	-
STRUCTURAL:			
Differential settling.	No	No	No
Cracks, slides, or scarps.	No	No	No
Seepage (specify location, color, value).	No	No	No
Defective spillways.	No	No	No
Other.	-	-	-
APPURTENANT STRUCTURES:			
Defective spillways.			
Dewatering device clogged.			
Cracking or crushing of pipes.			
Other.	-	-	-
COMMENTS:			



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia PerkinsDRAINAGE: EAST PYEATTSIGNATURE: Tonia PerkinsDATE OF INSPECTION: 5/26/2021

POND IDENTIFICATION	East Pyeatt #1	East Pyeatt #2	East Pyeatt #3
Approximate water level:	100'	100'	95'
Sediment level (% total storage):	95%	85%	25%
Outflow (cfs):	41 CFS	21 CFS	0
Sediment marker (install or replace)	Underwater	Underwater	Underwater
Identification sign (install or replace)	In Place	Needs re-attached	In Place
EROSIONAL:			
Rills and/or gullies on downstream face.	NO	NO	NO
Rills and/or gullies on upstream face.	NO	NO	NO
Inadequate vegetation.	NO	NO	NO
Outlet channel erosion.	NO	NO	NO
Burrows.	NO	NO	NO
Erosion of toe.	NO	NO	NO
Water impounded against downstream toe.	NO	NO	NO
Other.	-	-	-
STRUCTURAL:			
Differential settling.	NO	NO	NO
Cracks, slides, or scarps.	NO	NO	NO
Seepage (specify location, color, value).	NO	NO	NO
Defective spillways.	NO	NO	NO
Other.	-	-	-
APPURTENANT STRUCTURES:			
Defective spillways.	NO	NO	NO
Dewatering device clogged.	NO	NO	NO
Cracking or crushing of pipes.	NO	NO	NO
Other.	-	-	-
COMMENTS:			



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Monte McCoySIGNATURE: [Signature]DRAINAGE: **GROUSE GULCH**DATE OF INSPECTION: 6-14-2021

POND IDENTIFICATION	Grouse #1	Grouse #2
Approximate water level:	Dry	Dry
Sediment level (% total storage):	40%	10%
Outflow (cfs):	0	0
Sediment marker (install or replace)	in place	in place
Identification sign (install or replace)	in place	in place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	—	—
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	—	—
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	—	—
COMMENTS:		



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Monte McCoySIGNATURE: Monte McCoyDRAINAGE: **SAGE GULCH**DATE OF INSPECTION: 6-14-2021

POND IDENTIFICATION	Sage #1	Sage #2
Approximate water level:	0	0
Sediment level (% total storage):	10%	100%
Outflow (cfs):	0	0
Sediment marker (install or replace)	in place	in place
Identification sign (install or replace)	in place	needs replaced
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	—	—
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	—	—
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	—	—
COMMENTS:		



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia PerkinsSIGNATURE: *Tonia Perkins*DRAINAGE: **OAK GULCH**DATE OF INSPECTION: 5/26/2021

POND IDENTIFICATION	Oak #1	Oak #2
Approximate water level:	50%.	0% - Dry
Sediment level (% total storage):	45%.	5%.
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	NO	NO
Rills and/or gullies on upstream face.	NO	NO
Inadequate vegetation.	NO	NO
Outlet channel erosion.	NO	NO
Burrows.	NO	NO
Erosion of toe.	NO	NO
Water impounded against downstream toe.	NO	NO
Other.	-	-
STRUCTURAL:		
Differential settling.	NO	NO
Cracks, slides, or scarps.	NO	NO
Seepage (specify location, color, value).	NO	NO
Defective spillways.	NO	NO
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	NO	NO
Dewatering device clogged.	NO	NO
Cracking or crushing of pipes.	NO	NO
Other.	-	-
COMMENTS:		

#1 & #2

Vegetation in the outlets, but not interfering w/ water flow.



TRAPPER MINING INC.

TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Monte McCoySIGNATURE: Monte McCoyDRAINAGE: **WEST FLUME**DATE OF INSPECTION: 6-14-2021

POND IDENTIFICATION	West Flume #1
Approximate water level:	0
Sediment level (% total storage):	0
Outflow (cfs):	0
Sediment marker (install or replace)	in place
Identification sign (install or replace)	in place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	—
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	—
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	—
COMMENTS:	



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia PerkinsSIGNATURE: *Tonia Perkins*DRAINAGE: **MIDDLE FLUME**DATE OF INSPECTION: 5/26/2021

POND IDENTIFICATION	Middle Flume #1	Middle Flume #3
Approximate water level:	20'	80'
Sediment level (% total storage):	20%	35%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	Underwater
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	-	-
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	no	no
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	no	no
COMMENTS:		



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia PerkinsSIGNATURE: DRAINAGE: **EAST MIDDLE FLUME**DATE OF INSPECTION: 5/26/2021

POND IDENTIFICATION	East Middle Flume #1
Approximate water level:	90%
Sediment level (% total storage):	10%
Outflow (cfs):	0
Sediment marker (install or replace)	Underwater
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	-
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tania PerkinsSIGNATURE: *Tania Perkins*DRAINAGE: **EAST FLUME**DATE OF INSPECTION: 5/26/2021

POND IDENTIFICATION	East Flume #1
Approximate water level:	<u>Dry</u>
Sediment level (% total storage):	<u>15%</u>
Outflow (cfs):	<u>0</u>
Sediment marker (install or replace)	<u>In Place</u>
Identification sign (install or replace)	<u>In Place</u>
EROSIONAL:	
Rills and/or gullies on downstream face.	<u>NO</u>
Rills and/or gullies on upstream face.	<u>NO</u>
Inadequate vegetation.	<u>NO</u>
Outlet channel erosion.	<u>NO</u>
Burrows.	<u>NO</u>
Erosion of toe.	<u>NO</u>
Water impounded against downstream toe.	<u>NO</u>
Other.	<u>-</u>
STRUCTURAL:	
Differential settling.	<u>NO</u>
Cracks, slides, or scarps.	<u>NO</u>
Seepage (specify location, color, value).	<u>NO</u>
Defective spillways.	<u>NO</u>
Other.	<u>-</u>
APPURTENANT STRUCTURES:	
Defective spillways.	<u>NO</u>
Dewatering device clogged.	<u>NO</u>
Cracking or crushing of pipes.	<u>NO</u>
Other.	<u>-</u>
COMMENTS:	



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia PerkinsSIGNATURE: Tonia Perkins

DRAINAGE: UTE GULCH

DATE OF INSPECTION: 5/25/2021

POND IDENTIFICATION	Ute #1		
Approximate water level:	50%		
Sediment level (% total storage):	45%		
Outflow (cfs):	0		
Sediment marker (install or replace)	In Place		
Identification sign (install or replace)	In Place		
EROSIONAL:			
Rills and/or gullies on downstream face.	no		
Rills and/or gullies on upstream face.	no		
Inadequate vegetation.	no		
Outlet channel erosion.	no		
Burrows.	no		
Erosion of toe.	no		
Water impounded against downstream toe.	no		
Other.	-		
STRUCTURAL:			
Differential settling.	no		
Cracks, slides, or scarps.	no		
Seepage (specify location, color, value).	no		
Defective spillways.	no		
Other.	-		
APPURTENANT STRUCTURES:			
Defective spillways.	no		
Dewatering device clogged.	no		
Cracking or crushing of pipes.	no		
Other.	-		
COMMENTS:			



TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia PerkinsSIGNATURE: Tonia PerkinsDRAINAGE: HORSE GULCHDATE OF INSPECTION: 5/26/2021

POND IDENTIFICATION	Horse #1			
Approximate water level:	<u>70.1</u>			
Sediment level (% total storage):	<u>55.1</u>			
Outflow (cfs):	<u>0</u>			
Sediment marker (install or replace)	<u>In Place</u>			
Identification sign (install or replace)	<u>In Place</u>			
EROSIONAL:				
Rills and/or gullies on downstream face.	<u>no</u>			
Rills and/or gullies on upstream face.	<u>no</u>			
Inadequate vegetation.	<u>no</u>			
Outlet channel erosion.	<u>no</u>			
Burrows.	<u>no</u>			
Erosion of toe.	<u>no</u>			
Water impounded against downstream toe.	<u>no</u>			
Other.	<u>-</u>			
STRUCTURAL:				
Differential settling.	<u>no</u>			
Cracks, slides, or scarps.	<u>no</u>			
Seepage (specify location, color, value).	<u>no</u>			
Defective spillways.	<u>no</u>			
Other.	<u>-</u>			
APPURTENANT STRUCTURES:				
Defective spillways.	<u>no</u>			
Dewatering device clogged.	<u>no</u>			
Cracking or crushing of pipes.	<u>no</u>			
Other.	<u>-</u>			
COMMENTS:				



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia PerkinsSIGNATURE: Tonia PerkinsDRAINAGE: WEST HORSE GULCHDATE OF INSPECTION: 5/26/2021

POND IDENTIFICATION	West Horse #1
Approximate water level:	<u>Dry</u>
Sediment level (% total storage):	<u>2018</u>
Outflow (cfs):	<u>0</u>
Sediment marker (install or replace)	<u>In Place</u>
Identification sign (install or replace)	<u>In Place</u>
EROSIONAL:	
Rills and/or gullies on downstream face.	<u>NO</u>
Rills and/or gullies on upstream face.	<u>NO</u>
Inadequate vegetation.	<u>NO</u>
Outlet channel erosion.	<u>NO</u>
Burrows.	<u>NO</u>
Erosion of toe.	<u>NO</u>
Water impounded against downstream toe.	<u>NO</u>
Other.	<u>-</u>
STRUCTURAL:	
Differential settling.	<u>NO</u>
Cracks, slides, or scarps.	<u>NO</u>
Seepage (specify location, color, value).	<u>NO</u>
Defective spillways.	<u>NO</u>
Other.	<u>-</u>
APPURTENANT STRUCTURES:	
Defective spillways.	<u>NO</u>
Dewatering device clogged.	<u>NO</u>
Cracking or crushing of pipes.	<u>NO</u>
Other.	<u>-</u>
COMMENTS:	



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR:

Tonia Perkins

SIGNATURE:

Chris L. L...DRAINAGE: **DEAL GULCH**

DATE OF INSPECTION:

5/26/2021

POND IDENTIFICATION	Deal #1	Deal #2
Approximate water level:	50%	Dry
Sediment level (% total storage):	55%	0
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	No	No
Rills and/or gullies on upstream face.	No	No
Inadequate vegetation.	No	No
Outlet channel erosion.	No	No
Burrows.	No	No
Erosion of toe.	No	No
Water impounded against downstream toe.	No	No
Other.	-	-
STRUCTURAL:		
Differential settling.	No	No
Cracks, slides, or scarps.	No	No
Seepage (specify location, color, value).	No	No
Defective spillways.	No	No
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	No	No
Dewatering device clogged.	No	No
Cracking or crushing of pipes.	No	No
Other.	-	-
COMMENTS:		

* Sediment marker post is bent over from cows.
 Needs to be fixed, but due to water level, it
 can't be accessed.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR:

Tonia Perkins

SIGNATURE:

John PerkinsDRAINAGE: **DEACON**

DATE OF INSPECTION:

5/26/2021

POND IDENTIFICATION	Deacon #1	Deacon #2
Approximate water level:	0 Dry	0 Dry
Sediment level (% total storage):	0	0
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	NO	NO
Rills and/or gullies on upstream face.	NO	NO
Inadequate vegetation.	NO	NO
Outlet channel erosion.	NO	NO
Burrows.	NO	NO
Erosion of toe.	NO	NO
Water impounded against downstream toe.	NO	NO
Other.	-	-
STRUCTURAL:		
Differential settling.	NO	NO
Cracks, slides, or scarps.	NO	NO
Seepage (specify location, color, value).	NO	NO
Defective spillways.	NO	NO
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	NO	NO
Dewatering device clogged.	NO	NO
Cracking or crushing of pipes.	NO	NO
Other.	-	-
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: JEFFWAY

SIGNATURE: Tonia Perkins

DATE OF INSPECTION: 5/26/2021

POND IDENTIFICATION	Jeffway #1
Approximate water level:	
Sediment level (% total storage):	Dry
Outflow (cfs):	0
Sediment marker (install or replace)	In Place
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	-
COMMENTS:	

* Sediment marker is bent from cows. Needs to be replaced. Cows are in area now, wait till they are gone.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia PerkinsSIGNATURE: [Signature] 2nd
1st QUARTER 2021

DRAINAGE: IMPOUNDMENT H

DATE OF INSPECTION: 5/26/2021

POND IDENTIFICATION	Impoundment H
Approximate water level:	<u>5'1"</u>
Sediment level (% total storage):	<u>5'1"</u>
Outflow (cfs):	<u>0</u>
Sediment marker (install or replace)	<u>EO Place</u>
Identification sign (install or replace)	<u>EO Place</u>
EROSIONAL:	
Rills and/or gullies on downstream face.	<u>No</u>
Rills and/or gullies on upstream face.	<u>No</u>
Inadequate vegetation.	<u>No</u>
Outlet channel erosion.	<u>No</u>
Burrows.	<u>No</u>
Erosion of toe.	<u>No</u>
Water impounded against downstream toe.	<u>No</u>
Other.	<u>-</u>
STRUCTURAL:	
Differential settling.	<u>No</u>
Cracks, slides, or scarps.	<u>No</u>
Seepage (specify location, color, value).	<u>No</u>
Defective spillways.	<u>No</u>
Other.	<u>-</u>
APPURTENANT STRUCTURES:	
Defective spillways.	<u>No</u>
Dewatering device clogged.	<u>No</u>
Cracking or crushing of pipes.	<u>No</u>
Other.	<u>-</u>
COMMENTS:	



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tania PerkinsSIGNATURE: *Tania Perkins*DRAINAGE: **INDUSTRIAL WASTE POND**DATE OF INSPECTION: 5/26/2021

POND IDENTIFICATION	Industrial Waste Pond #1
Approximate water level:	<u>30%</u>
Sediment level (% total storage):	<u>5%</u>
Outflow (cfs):	<u>0</u>
Sediment marker (install or replace)	<u>N/A</u>
Identification sign (install or replace)	<u>In Place</u>
EROSIONAL:	
Rills and/or gullies on downstream face.	<u>No</u>
Rills and/or gullies on upstream face.	<u>No</u>
Inadequate vegetation.	<u>No</u>
Outlet channel erosion.	<u>No</u>
Burrows.	<u>No</u>
Erosion of toe.	<u>No</u>
Water impounded against downstream toe.	<u>No</u>
Other.	<u>-</u>
STRUCTURAL:	
Differential settling.	<u>No</u>
Cracks, slides, or scarps.	<u>No</u>
Seepage (specify location, color, value).	<u>No</u>
Defective spillways.	<u>No</u>
Other.	<u>-</u>
APPURTENANT STRUCTURES:	
Defective spillways.	<u>N/A</u>
Dewatering device clogged.	<u>N/A</u>
Cracking or crushing of pipes.	<u>N/A</u>
Other.	
COMMENTS:	

