

**STATE OF
COLORADO****Ebert - DNR, Jared <jared.ebert@state.co.us>**

pictures of mining claim M2001-022 june 2021

JAMIE MCGILL <jam2finance@yahoo.com>

Wed, Jun 30, 2021 at 10:29 AM

To: Jared Ebert - DNR <jared.ebert@state.co.us>, Peter Hays - DNR <peter.hays@state.co.us>, Jeff Fugate <jeff.fugate@coag.gov>, Dc_construction <dc_construction@ymail.com>

Hi Jared,

I was wondering how you got my complaint? Is it because you have worked with LRM in the past with other mining claims and have worked with Stephanie Francher directly. My only concern is that you perhaps are not objective. I have attached some pictures that I am including in packages that I am sending out today to state and local governments. I do want you to consider the previous emails and documentation a appeal to your decision unless you are amended you decision on 5/28/2021 and if so please provide me a copy. These are pictures that reflect the violations that I have complained about and have not been corrected and for some reason not enforced by DRMS. I only want to correct the dangerous eroding slope and can not believe how hard it is to have fixed. I am hoping by reaching out to everyone that is directly or indirectly with this mining claim or perhaps has the ability to enforce the 3:1 slope for the whole lake, I will reach the right person. I will wait to receive your report in regards to the slope above the lake. I am waiting for the water results that LRM performed in June as well. We already know that they did not slope the lake 3:1 from bottom of lake to top as submitted in their reclamation plan, but we told you we would accept the underwater slope and we were only concerned from the water to the top of slope because that is where it is dangerous. Why you are worried about the parts that do not affect the safety of people and animals. I guess I do not understand unless there is a safety concern I am unaware of. Please advise if so.

Sincerely
Jamie Christensen
785-230-8400

2 attachments **62821.pdf**
18947K **62621.pdf**
2374K



There is
a hole
From Mining
was wondering
why not
filled in.

View of the west shoreline looking south in Cell 4



View of the vegetation in the southwest corner of Cell 4



This was
caused by
mining is
open to river
was wondering
why it is not
being filled
in?

Figure 9. Culvert from the Cell No. 4 area to the Big Thompson River.




Figure 10. View from near the northwest corner of the Cell No. 4 looking east.

June 28th 2021

1100-2000



More
Shore
ready to
Break
off




June
28th, 2021

628-2021

6-28-2021

June 28th
2021



6-28-2021

June
28, 2021



6-28-2021

June
28, 2021



June 28, 2021



June 28, 2021



June 28, 2021

A photograph of a stream or river. A yellow measuring tape is stretched across the water in the foreground. A green ruler is placed vertically on the right side of the frame. The water is clear, and the surrounding area is rocky and covered with some vegetation. The date "June 28, 2002" is written in black cursive at the bottom right.

June 28, 2002