




MINERALS PROGRAM INSPECTION REPORT

PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Geo-hydrology Drilling and Coring Program	MINE/PROSPECTING ID#: P-2006-013	MINERAL: Oil shale	COUNTY: Rio Blanco
INSPECTION TYPE: Monitoring	INSPECTOR(S): Amy Yeldell	INSP. DATE: July 1, 2021	INSP. TIME: 08:00
OPERATOR: Shell Frontier Oil & Gas Inc.	OPERATOR REPRESENTATIVE: Samantha Baker	TYPE OF OPERATION: MP - Mineral Prospecting	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: \$350,757.80	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: July 8, 2021	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>NA</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>NA</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>Y</u>
(AT) ACID OR TOXIC MATERIALS----- <u>NA</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Colorado Division of Reclamation, Mining, and Safety normal monitoring program. The Geo-hydrology Drilling and Coring Program is a Hard Rock NOI located in Rio Blanco County. Amy Yeldell of the Division conducted the inspection. Samantha Baker represented the Operator.

The permitted NOI includes a total of 5.53 acres and has a current bond of \$338,217.

All hydrology wells have been abandoned and pads have been reclaimed. The last reclamation efforts were completed in 2015 and now are awaiting adequate vegetation establishment. Over all pads are stable with no signs of erosion. All mining related debris has been removed from the site(s). Specific observations of each pad are listed below,

*Pad 80: Perimeter fence remains in place, will need to be pulled upon release. Pad is predominantly shrubs with some understory grasses. Overall vegetation is well established and robust with little to no evidence of weeds. Final reclamation has been achieved

*Pad 68-30-198: Gate at the access road and fenced to separate private from public. Road was recently used by the county and has significantly less cover than in years past however is still well established and bouncing back. Overall, the pad is primarily all shrubs with some grasses. Final reclamation has been achieved

* Indicates pads where final reclamation has been achieved

Responses to this inspection report should be directed to Amy Yeldell at the Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. Direct contact can be made by phone at 303-866-3567 Ext 8183 or via email at amy.yeldell@state.co.us

Inspection Contact Address

Samantha Baker
Shell Frontier Oil & Gas Inc.
150 N. Dairy Ashford, Bldg. E-1040G
Houston, TX 77079

Enclosure

CC:
Travis Marshall, Senior EPS, Grand Junction DRMS

PHOTOGRAPHS



