

PERMIT INFORMATION

Permit Number: C-1981-014 Mine Name: Southfield Mine Operator: Energy Fuels Coal, Inc. Operator Address:	County: Fremont Operation Type: Underground Permit Status: Revoked Ownership: Private			
Mr John Adams				
P.O. Box 773457	Operator Representative Present:			
Steamboat Springs, CO 80477	NT			
	None			
Operator Representative Signature: (Field Issuance Only)				

INSPECTION INFORMATION

Inspection Start Date: June 29, 2 Inspection Start Time: 08:00 Inspection End Date: Inspection End Time:	.021		Inspection Type: Coal Compl Inspection Reason: Normal Id Weather: Cloudy	*
Joint Inspection Agency: Joi		Join	oint Inspection Contacts:	
None		None		
Post Inspection Agency:		Post	Post Inspection Contacts:	
None		None		
Inspector(s):	Inspecto	r's Sig	gnature:	Signature Date:
Zach Trujillo	30	1	56	7/2/21

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection R - Roads

 ${f N}$ - Availability of Records ${f R}$ - Reclamation Success

N - Backfill & Grading N - Revegetation

N - Excess Spoil and Dev. Waste N - Subsidence

N - Explosives
 N - Slides and Other Damage
 N - Fish & Wildlife
 N - Support Facilities On-site
 N - Signs and Markers

N - Gen. Compliance With Mine Plan

N - Support Facilities Not On-site

N - Support Facilities Not On-site

N - Other N - Special Categories Of Mining

N - Processing Waste N - Topsoil

COMMENTS

This was a complete inspection of the Southfield Mine conducted by Zach Trujillo of Colorado Division of Reclamation, Mining and Safety (DRMS) on June 29, 2021. The Southfield Mine was an underground mine which the Division has revoked the bond and terminated the permit. Therefore, no mine operator remains. All bond monies available to the Division will be utilized as needed for reclamation and maintenance activities. The weather was cloudy and temperatures during the inspection were around seventy degrees fahrenheit.

On November 13, 2018, a meeting was held between the Division and The Corley Company. During this meeting, Dr. Corely, president of The Corley Company, informed the Division that it was best that the Division no longer access the site on the lands owned by The Corely Company. Based upon that meeting, the Division no longer inspects that portion of the Southfield Mine.

ROADS – Rule 4.03

Construction 4.03.1(3)/4.03.2(3), Drainage 4.03.1(4)/4.03.2(4), Surfacing and Maintenance 4.03.1(5) and (6)/4.03.2(5) and (6), Reclamation 4.03.1(7)/4.03.2(7):

The two track road off County Road 51 was inspected. Vegetation continues to establish itself along the road. No signs of use was observed on the road.

The reclaimed road spur and access road to the NW-MW well were inspected. The road spur is established with great vegetation and blends well with adjacent undisturbed land. The access road for the NW-MW well shows signs of increased vegetation growth. No issues were observed.

The reclaimed substation access road shows increased vegetation establishment. No recent use on the road was observed and has probably contributed to vegetation success along the corridor.

Number of <u>Partial</u> Inspection this Fiscal Year: 1 Number of <u>Complete</u> Inspections this Fiscal Year: 2





Two track road.

NW-MW well access road.





Road spur.

Access road to substation.

RECLAMATION SUCCESS - Rule 4.15, Rule 3:

The NW-MW well pad shows good signs of vegetation. No erosion or issues were observed.

The reclaimed substation pad also has good vegetative growth. The area blends well to adjacent undisturbed land.

Number of <u>Partial</u> Inspection this Fiscal Year: 1 Number of <u>Complete</u> Inspections this Fiscal Year: 2





NW-MW well pad.

Substation pad.

Number of <u>Partial</u> Inspection this Fiscal Year: 1 Number of <u>Complete</u> Inspections this Fiscal Year: 2