## **PERMIT INFORMATION**

County: Routt Operation Type: Underground Permit Status: Active Ownership: Private			
<b>Operator Representative Present:</b>			
Miranda Kawcak			
Operator Representative Signature: (Field Issuance Only)			

# **INSPECTION INFORMATION**

Inspection Start Date: July 27, 2 Inspection Start Time: 12:00 Inspection End Date: July 27, 20 Inspection End Time: 03:00			Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Clear
Joint Inspection Agency:		Joint	Inspection Contacts:
None			
Post Inspection Agency:		Post	Inspection Contacts:
None			
Inspector(s):	Inspector	Inspector's Signature: Signature I	
Tabetha Lynch	Titha	Typ	8/6/21

#### **Inspection Topic Summary**

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

**N** - Air Resource Protection

**N** - Availability of Records

N - Backfill & Grading

N - Excess Spoil and Dev. Waste

**N** - Explosives

N - Fish & Wildlife

N - Hydrologic Balance

**R** - Gen. Compliance With Mine Plan

N - Other

N - Processing Waste

Y - Roads

N - Reclamation Success

**N** - Revegetation

N - Subsidence

**N** - Slides and Other Damage

N - Support Facilities On-site

Y - Signs and Markers

N - Support Facilities Not On-site

N - Special Categories Of Mining

Y - Topsoil

#### **COMMENTS**

This was a partial inspection of the Foidel Creek Mine; DRMS Permit No. C-1982-056, operated by Twentymile Coal, LLC. (TC). This inspection was conducted by Tabetha Lynch with the Colorado Division of Reclamation, Mining, and Safety (Division). Overall the weather was clear and hot during the inspection.

#### GENERAL MINE PLAN COMPLIANCE:

The trash has been cleaned out of the portal ditch as requested in the previous inspection.

The 12L borehole pad was checked for clean-up and reclamation progress. An electric fence has been placed around the 12L pad and topsoil pile.



Electric fence at 12L shown above



Coal fines have been cleaned up on the pad.



12 L borehole is no longer backing up and pad will be reclaimed per operator.

At the time of inspection a drill was on site attempting to re-develop the 16L dewatering borehole. Photo below



At the time of inspection, MR319 was discussed with the operator, as a new dewatering borehole that would be proposed to branch off the existing access road to 16L.

The proposed location of 18L was observed, as well as a potential route for the access road. The property is owned by Camelletii/ Chance and the operator stated they were working on updating the lease with the surface owners. A GPS location of the proposed location of the pad was collected. Operator will be updating the county special use permit as well for the 18L pad and the TR97 revision currently under review.



Above shows the proposed location of the 18L dewatering borehole Looking NE



Above shows the proposed location of the 18L dewatering borehole looking SW to proposed access road

A cultural survey was to be started on the day of this inspection for the proposed area.

# DOCUMENTS RECEIVED OTHER (SPECIFY)

## ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.