




**COLORADO**  
Division of Reclamation,  
Mining and Safety  
Department of Natural Resources

**PERMIT INFORMATION**

<b>Permit Number:</b> C-1992-081 <b>Mine Name:</b> Hayden Gulch Loadout <b>Operator:</b> Hayden Gulch Terminal, LLC <b>Operator Address:</b> Ms Miranda Kawcak  P.O. Box 670 Hayden, CO 81639	<b>County:</b> Routt <b>Operation Type:</b> Loadout <b>Permit Status:</b> Active <b>Ownership:</b> Private  <b>Operator Representative Present:</b>  none
<b>Operator Representative Signature: (Field Issuance Only)</b>  	

**INSPECTION INFORMATION**

<b>Inspection Start Date:</b> July 28, 2021 <b>Inspection Start Time:</b> 13:30 <b>Inspection End Date:</b> <b>Inspection End Time:</b>		<b>Inspection Type:</b> Coal Partial Inspection <b>Inspection Reason:</b> Normal I&E Program <b>Weather:</b> Clear	
<b>Joint Inspection Agency:</b>  None		<b>Joint Inspection Contacts:</b>  	
<b>Post Inspection Agency:</b>  None		<b>Post Inspection Contacts:</b>  	
<b>Inspector(s):</b>  Tabetha Lynch	<b>Inspector's Signature:</b>  		<b>Signature Date:</b>  8/6/21

**Inspection Topic Summary**NOTE: **Y**=Inspected **N**=Not Inspected **R**=Comments Noted **V**=Violation Issued **NA**=Not Applicable**N** - Air Resource Protection**Y** - Roads**N** - Availability of Records**R** - Reclamation Success**Y** - Backfill & Grading**N** - Revegetation**N** - Excess Spoil and Dev. Waste**N** - Subsidence**N** - Explosives**N** - Slides and Other Damage**R** - Fish & Wildlife**N** - Support Facilities On-site**R** - Hydrologic Balance**Y** - Signs and Markers**Y** - Gen. Compliance With Mine Plan**NA** - Support Facilities Not On-site**N** - Other**NA** - Special Categories Of Mining**N** - Processing Waste**Y** - Topsoil**COMMENTS**

This was a partial inspection of the Hayden Gulch Loadout; DRMS Permit No. C-1992-081, operated by Hayden Gulch Terminal, LLC. The inspection was conducted by Tabetha Lynch with the Colorado Division of Reclamation, Mining, and Safety (Division) on 7/28.

**FISH and WILDLIFE – Rule 4.18:**

Pronghorn were present in the permit area at time of inspection

**HYDROLOGIC BALANCE - Rule 4.05**

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Ponds were dry.

**RECLAMATION SUCCESS - Rule 4.15, Rule 3:**

**Weeds were noted in the parking lot and all around the previous rail line, now being used as a community trail. Weed control will need to be mitigated in these areas. Photos below.**

Number of Partial Inspection this Fiscal Year: 8

Number of Complete Inspections this Fiscal Year: 3



**Weeds on trail shown above.**

**Weeds in parking lot shown below looking north.**



Number of Partial Inspection this Fiscal Year: 8  
Number of Complete Inspections this Fiscal Year: 3

**DOCUMENTS RECEIVED**

**OTHER (SPECIFY)**

**ENFORCEMENT ACTIONS/COMPLIANCE**

No enforcement actions were initiated as a result of this inspection, nor are any pending.

Number of Partial Inspection this Fiscal Year: 8

Number of Complete Inspections this Fiscal Year: 3