




COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

PERMIT INFORMATION

Permit Number: C-1992-081 Mine Name: Hayden Gulch Loadout Operator: Hayden Gulch Terminal, LLC Operator Address: Ms Miranda Kawcak P.O. Box 670 Hayden, CO 81639	County: Routt Operation Type: Loadout Permit Status: Active Ownership: Private Operator Representative Present: none
Operator Representative Signature: (Field Issuance Only) 	

INSPECTION INFORMATION

Inspection Start Date: July 30, 2021 Inspection Start Time: 13:30 Inspection End Date: Inspection End Time:		Inspection Type: Coal Aerial Inspection Reason: Normal I&E Program Weather: Clear/Smokey	
Joint Inspection Agency: None		Joint Inspection Contacts: 	
Post Inspection Agency: None		Post Inspection Contacts: 	
Inspector(s): Tabetha Lynch Brock Bowles	Inspector's Signature: 		Signature Date: 8/6/21

Inspection Topic SummaryNOTE: **Y**=Inspected **N**=Not Inspected **R**=Comments Noted **V**=Violation Issued **NA**=Not Applicable**N** - Air Resource Protection**N** - Availability of Records**Y** - Backfill & Grading**N** - Excess Spoil and Dev. Waste**N** - Explosives**N** - Fish & Wildlife**Y** - Hydrologic Balance**Y** - Gen. Compliance With Mine Plan**N** - Other**N** - Processing Waste**Y** - Roads**R** - Reclamation Success**N** - Revegetation**N** - Subsidence**N** - Slides and Other Damage**N** - Support Facilities On-site**N** - Signs and Markers**NA** - Support Facilities Not On-site**NA** - Special Categories Of Mining**Y** - Topsoil**COMMENTS**

This was an aerial inspection of the Hayden Gulch Loadout; DRMS Permit No. C-1992-081, operated by Hayden Gulch Terminal, LLC. The photos were taken by Brock Bowles on 7/30 and reviewed by Tabetha Lynch with the Colorado Division of Reclamation, Mining, and Safety (Division).

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18: Ponds are dry.

RECLAMATION SUCCESS - Rule 4.15, Rule 3:Number of Partial Inspection this Fiscal Year: 8Number of Complete Inspections this Fiscal Year: 3



Above shows the reclaim area just north and south of Hwy 40 where the tracks have been removed. North is roughly the left side of the photo and south to the right.



Shown above are the two dry ponds. Dry creek also appears to be dry.

Number of Partial Inspection this Fiscal Year: 8

Number of Complete Inspections this Fiscal Year: 3

DOCUMENTS RECEIVED

OTHER (SPECIFY)

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

Number of Partial Inspection this Fiscal Year: 8

Number of Complete Inspections this Fiscal Year: 3