




**MINERALS PROGRAM INSPECTION REPORT**  
**PHONE: (303) 866-3567**

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

<b>MINE NAME:</b> Borrow Site for Bennett Crossing Filing 2 (Parcel 2)	<b>MINE/PROSPECTING ID#:</b> M-2019-030	<b>MINERAL:</b> Borrow Material	<b>COUNTY:</b> Adams
<b>INSPECTION TYPE:</b> Surety Release Inspection	<b>INSPECTOR(S):</b> Patrick Lennberg	<b>INSP. DATE:</b> August 27, 2021	<b>INSP. TIME:</b> 09:00
<b>OPERATOR:</b> LGI Homes - Colorado, LLC	<b>OPERATOR REPRESENTATIVE:</b> Kacy Flemmons, LGI and Rick Mitchell, Landowner	<b>TYPE OF OPERATION:</b> 111(1)(b) - Special One-Time Incidental	
<b>REASON FOR INSPECTION:</b> Surety Release Requested	<b>BOND CALCULATION TYPE:</b> None	<b>BOND AMOUNT:</b> \$75,000.00	
<b>DATE OF COMPLAINT:</b> NA	<b>POST INSP. CONTACTS:</b> None	<b>JOINT INSP. AGENCY:</b> None	
<b>WEATHER:</b> Clear	<b>INSPECTOR'S SIGNATURE:</b> 	<b>SIGNATURE DATE:</b> September 13, 2021	

**GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>N</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

## **OBSERVATIONS**

The Borrow Site for Bennett Crossing Filing 2 Parcel 2 was inspected by Patrick Lennberg with the Division of Reclamation, Mining and Safety (Division/DRMS). The inspection was completed as part of a permit release request, submitted in accordance with Rule 4.17, received by the Division on July 20, 2021. The site was last inspected on May 13, 2021 as part of the Division's routine monitoring inspection program. Kacy Flemons with LGI Homes – Colorado LLC and Rick Mitchell, landowner, met me at the entrance prior to conducting the inspection. The weather was clear.

The entrance to Parcel 2 is located at the east end of Edward Ave off of 1<sup>st</sup> Street in Bennett, Colorado. The parcel is a 111(1)(b) operation permitted for 30 acres for the removal of borrow material to assist in home construction purposes in the immediate area. The site is surrounded by residential and rangeland with the post-mining land use of industrial/commercial.

The site was mulched and seeded in Fall 2019. Vegetation appears to be growing as expected for the area and with the wet Spring/Summer the vegetation has become well established. There were some weeds volunteering into the site but it is not acting as a source to the surrounding properties. Although the post-mining land use industrial/commercial the approved reclamation plan states that the parcel will be revegetated to meet the criteria as defined in Rule 3.1.10(1).

Based on observations made during this inspection, the operator has completed the reclamation in accordance with the reclamation plan. The majority of the revegetated area has suitable vegetation cover and appears stable. Therefore the release request of the permit will be approved. Notice of the Division's decision regarding the release request will be sent under a separate cover letter.

Photographs taken during the inspection are attached.

Please contact Patrick Lennberg (303)866-3567 ext. 8114 or email at [patrick.lennberg@state.co.us](mailto:patrick.lennberg@state.co.us) if you have any questions regarding this report.

### **Inspection Contact Address**

Kacy Flemons  
LGI Homes - Colorado, LLC  
14205 SE 36th Street  
Bellevue, WA 98006

cc: Jared Ebert, DRMS

ec: Kacy Flemons, LGI Homes LLC, [kacy.flemons@lgihomes.com](mailto:kacy.flemons@lgihomes.com)

**PHOTOGRAPHS**



**Photo 1:** Typical growth in the south end looking west



**Photo 2:** Typical growth looking northwest from the southeastern corner





**Photo 3:** Typical growth looking south from the southeastern corner



**Photo 4:** Typical growth looking south from the north central area of permit





**Photo 5:** Typical growth looking north from the north central area of permit



**Photo 6:** Typical growth looking east from the north central area of permit