

Notes:

The Annual Report maps have been revised to reflect the existing conditions at the mine.

(4) Mining continued in areas previously disturbed and material was removed from stockpiled material.

(8) Of the 5.6 acres disturbed approximately 0.77 acres of temporary sloping has been done along the north side. This will eventually be removed as mining progress to the north towards the final boundary.

(9) No new area was disturbed for mining.

(13) Mining will continue to deepen the disturbed area and temporary sloping will continue if needed. The backfilled area is along the northern slope.

(15) Some topsoil is stored on the northwest corner of the mined area sufficient to reseed the disturbed area.

(19) The bond is adequate to complete reclamation according to the May 2019 inspection report.