



October 11, 2021

Mrs. Janet Binns
Environmental Protection Specialist
Colorado Division of Reclamation, Mining and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

**RE: New Horizon Mine
Permit No. C-1981-008
4th Quarter 2021 Impoundment Inspections**

Dear Mrs. Binns:

Elk Ridge Mining and Reclamation, LLC (Elk Ridge) operates the New Horizon Mine. Tri-State Generation and Transmission Association, Inc. (Tri-State) is the parent company of Elk Ridge. The New Horizon Mine operates under Colorado Division of Reclamation, Mining and Safety (CDRMS) Permit No. C-1981-008.

In accordance with Rule 4.05.9(17), Tri-State is submitting the enclosed quarterly impoundment inspections on behalf of Elk Ridge.

If you have any questions about the enclosed quarterly impoundment reports, please contact Tony Tennyson at (970) 326-3560 at your convenience.

Sincerely,

DocuSigned by:
A handwritten signature in black ink that reads "Chris Gilbreath".
D250C711D0BF450...

Chris Gilbreath
Senior Manager
Remediation and Reclamation

CG:TT:der

Enclosures

cc: Tony Tennyson (via email)
G474-11.3(21)b-9

POND EXAMINATION FORM, 4th QUARTER 2021

Mine: **New Horizon 2 Mine**
 Pond Name: **Stock Pond 2 (SP2)**
 NPDES Permit & Outfall #: **CO-0000213**
 Date Examined: **7-October-2021**
 Location Description: **2 miles NW of Nucla**

Owner's Rep.: **C. Chiles, Mine Supervisor**
 Pond Type: **Partly Incised**
 CDRM & S #: **C-1981-008**
 Date Last Examined: **15-September-2021**
 Legal Location: **Sec 36 of T47N R16W**
 Inspector's Name: **Clifford Chiles**

Circle or Write appropriate Response

- | | | | | |
|-----|---|-----|---------------|----------------|
| 1. | Seepage (specify location, color, and approx. volume) _____ | Yes | No | N/A |
| 2. | Cracks or scarps on crest or slopes _____ | Yes | No | N/A |
| 3. | Sloughing or bulging on slopes _____ | Yes | No | N/A |
| 4. | Major erosion problems _____ | Yes | No | N/A |
| 5. | Surface movements in valley bottom or on hillside _____ | Yes | No | N/A |
| 6. | Water impounded against toe _____ | Yes | No | N/A |
| 7. | Clogging | | | |
| | a) Spillway channels and pipes _____ | Yes | No | N/A |
| | b) Decant system _____ | Yes | No | N/A |
| | c) Diversion Ditches _____ | Yes | No | N/A |
| 8. | Cracking or crushing of pipes | | | |
| | a) Spillway pipes _____ | Yes | No | N/A |
| | b) Decant system _____ | Yes | No | N/A |
| 9. | Trash racks clear and in place _____ | Yes | No | N/A |
| 10. | Monitoring instrumentation _____ | Yes | No | N/A |

Comments: **Pond bottom is dry.**

POND EXAMINATION FORM, 4th QUARTER 2021

Mine: **New Horizon 2 Mine**

Owner's Rep.: **C. Chiles, Mine Supervisor**

Pond Name: **Pond 012**

Pond Type: **Partly Incised**

NPDES Permit & Outfall #: **CO-0000213**

CDRM & S #: **C-1981-008**

Date Examined: **7-October-2021**

Date Last Examined: **15-September-2021**

Location Description: **2 miles NW of Nucla**

Legal Location: **Sec 36 of T47N R16W**

Inspector's Name: **Clifford Chiles**

Circle or Write appropriate Response

- | | | | | |
|-----|---|----------------|---------------|----------------|
| 1. | Seepage (specify location, color, and approx. volume) _____ | Yes | No | N/A |
| 2. | Cracks or scarps on crest or slopes _____ | Yes | No | N/A |
| 3. | Sloughing or bulging on slopes _____ | Yes | No | N/A |
| 4. | Major erosion problems _____ | Yes | No | N/A |
| 5. | Surface movements in valley bottom or on hillside _____ | Yes | No | N/A |
| 6. | Water impounded against toe _____ | Yes | No | N/A |
| 7. | Clogging | | | |
| | a) Spillway channels and pipes _____ | Yes | No | N/A |
| | b) Decant system _____ | Yes | No | N/A |
| | c) Diversion Ditches _____ | Yes | No | N/A |
| 8. | Cracking or crushing of pipes | | | |
| | a) Spillway pipes _____ | Yes | No | N/A |
| | b) Decant system _____ | Yes | No | N/A |
| 9. | Trash racks clear and in place _____ | Yes | No | N/A |
| 10. | Monitoring instrumentation _____ | Yes | No | N/A |

Comments: **Pond bottom is dry.**

POND EXAMINATION FORM, 4th QUARTER 2021

Mine: **New Horizon 2 Mine**

Pond Name: **Pond 013**

NPDES Permit & Outfall #s: **CO-0000213**

Date Examined: **7-October-2021**

Location Description: **2 miles West of Nucla**

Owner's Rep.: **C. Chiles, Mine Supervisor**

Pond Type: **Partly Incised**

CDRM & S #: **C-1981-008**

Date Last Examined: **15-September-2021**

Legal Location: **Sec 36 of T47N R16W**

Inspector's Name: **Clifford Chiles**

Circle or Write appropriate Response

- | | | | | |
|-----|--|----------------|---------------|-----|
| 1. | Seepage (specify location, color, and approx. volume) _____ | Yes | No | N/A |
| 2. | Cracks or scarps on crest or slopes _____ | Yes | No | N/A |
| 3. | Sloughing or bulging on slopes _____ | Yes | No | N/A |
| 4. | Major erosion problems _____ | Yes | No | N/A |
| 5. | Surface movements in valley bottom or on hillside _____ | Yes | No | N/A |
| 6. | Water impounded against toe _____ | Yes | No | N/A |
| 7. | Clogging | | | |
| | a) Spillway channels and pipes _____ | Yes | No | N/A |
| | b) Decant system _____ | Yes | No | N/A |
| | c) Diversion Ditches _____ | Yes | No | N/A |
| 8. | Cracking or crushing of pipes | | | |
| | a) Spillway pipes _____ | Yes | No | N/A |
| | b) Decant system _____ | Yes | No | N/A |
| 9. | Trash racks clear and in place _____ | Yes | No | N/A |
| 10. | Monitoring instrumentation Flume in place & functioning | Yes | No | N/A |

Comments: **Pond is discharging**

POND EXAMINATION FORM, 4th QUARTER 2021

Mine: **New Horizon 2 Mine**

Pond Name: **Pond 015**

NPDES Permit & Outfall #: **CO-0000213**

Date Examined: **7-October-2021**

Location Description: **2 miles West of Nucla**

Owner's Rep.: **C. Chiles, Mine Supervisor**

Pond Type: **Partly Incised**

CDRM & S #: **C-1981-008**

Date Last Examined: **15-September-2021**

Legal Location: **Sec 36 of T47N R16W**

Inspector's Name: **Clifford Chiles**

Circle or Write appropriate Response

- | | | | | |
|-----|---|-----|------------------------|-------------------------|
| 1. | Seepage (specify location, color, and approx. volume) _____ | Yes | No X | N/A |
| 2. | Cracks or scarps on crest or slopes _____ | Yes | No X | N/A |
| 3. | Sloughing or bulging on slopes _____ | Yes | No X | N/A |
| 4. | Major erosion problems _____ | Yes | No X | N/A |
| 5. | Surface movements in valley bottom or on hillside _____ | Yes | No X | N/A |
| 6. | Water impounded against toe _____ | Yes | No X | N/A |
| 7. | Clogging | | | |
| | a) Spillway channels and pipes _____ | Yes | No | N/A X |
| | b) Decant system _____ | Yes | No | N/A X |
| | c) Diversion Ditches _____ | Yes | No X | N/A |
| 8. | Cracking or crushing of pipes | | | |
| | a) Spillway pipes _____ | Yes | No | N/A X |
| | b) Decant system _____ | Yes | No | N/A X |
| 9. | Trash racks clear and in place _____ | Yes | No | N/A X |
| 10. | Monitoring instrumentation _____ | Yes | No | N/A X |

Comments: **Pond bottom is dry.**

POND EXAMINATION FORM, 4th QUARTER 2021

Mine: **New Horizon 2 Mine**

Pond Name: **Pond 016**

NPDES Permit & Outfall #: **CO-0000213**

Date Examined: **7-October-2021**

Location Description: **2 miles West of Nucla**

Owner's Rep.: **C. Chiles, Mine Supervisor**

Pond Type: **Partly Incised**

CDRM & S #: **C-1981-008**

Date Last Examined: **15-September-2021**

Legal Location: **Sec 36 of T47N R16W**

Inspector's Name: **Clifford Chiles**

Circle or Write appropriate Response

- | | | | | |
|-----|---|-----|------------------------|-------------------------|
| 1. | Seepage (specify location, color, and approx. volume) _____ | Yes | No X | N/A |
| 2. | Cracks or scarps on crest or slopes _____ | Yes | No X | N/A |
| 3. | Sloughing or bulging on slopes _____ | Yes | No X | N/A |
| 4. | Major erosion problems _____ | Yes | No X | N/A |
| 5. | Surface movements in valley bottom or on hillside _____ | Yes | No X | N/A |
| 6. | Water impounded against toe _____ | Yes | No X | N/A |
| 7. | Clogging | | | |
| | a) Spillway channels and pipes _____ | Yes | No X | N/A |
| | b) Decant system _____ | Yes | No | N/A X |
| | c) Diversion Ditches _____ | Yes | No X | N/A |
| 8. | Cracking or crushing of pipes | | | |
| | a) Spillway pipes _____ | Yes | No | N/A X |
| | b) Decant system _____ | Yes | No | N/A X |
| 9. | Trash racks clear and in place _____ | Yes | No | N/A X |
| 10. | Monitoring instrumentation _____ | Yes | No | N/A X |

Comments: **Pond bottom is dry.**

POND EXAMINATION FORM, 4th QUARTER 2021

Mine: **New Horizon 2 Mine**

Pond Name: **Pond 018**

NPDES Permit & Outfall #: **CO-0000213**

Date Examined: **7-October-2021**

Location Description: **0.1 miles West of Nucla**

Owner's Rep.: **C. Chiles, Mine Supervisor**

Pond Type: **Partly Incised**

CDRM & S #: **C-1981-008**

Date Last Examined: **15-September-2021**

Legal Location: **Sec 6 of T46N R15W**

Inspector's Name: **Clifford Chiles**

Circle or Write appropriate Response

- | | | | | |
|-----|---|-----|---------------|----------------|
| 1. | Seepage (specify location, color, and approx. volume) _____ | Yes | No | N/A |
| 2. | Cracks or scarps on crest or slopes _____ | Yes | No | N/A |
| 3. | Sloughing or bulging on slopes _____ | Yes | No | N/A |
| 4. | Major erosion problems _____ | Yes | No | N/A |
| 5. | Surface movements in valley bottom or on hillside _____ | Yes | No | N/A |
| 6. | Water impounded against toe _____ | Yes | No | N/A |
| 7. | Clogging | | | |
| | a) Spillway channels and pipes _____ | Yes | No | N/A |
| | b) Decant system _____ | Yes | No | N/A |
| | c) Diversion Ditches _____ | Yes | No | N/A |
| 8. | Cracking or crushing of pipes | | | |
| | a) Spillway pipes _____ | Yes | No | N/A |
| | b) Decant system _____ | Yes | No | N/A |
| 9. | Trash racks clear and in place _____ | Yes | No | N/A |
| 10. | Monitoring instrumentation _____ | Yes | No | N/A |

Comments: **Pond bottom is dry.**