




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Vondy Pit	MINE/PROSPECTING ID#: M-1986-105	MINERAL: Sand and gravel and commodity	COUNTY: Morgan
INSPECTION TYPE: Monitoring	INSPECTOR(S): Brock Bowles	INSP. DATE: October 15, 2021	INSP. TIME: 13:00
OPERATOR: Dilley's Sand & Gravel	OPERATOR REPRESENTATIVE: Chris Monahan	TYPE OF OPERATION: 110c - Construction Limited Impact	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE:	BOND AMOUNT: \$12,140.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: October 28, 2021	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>N</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>N</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted by Brock Bowles of the Division of Reclamation, Mining and Safety (Division). Mr. Chris Monahan representing Dilley's Sand and Gravel (operator) was present for the inspection. The Ayers Pit is located about 19 miles northeast of Fort Morgan. The site is a 110c operation with 9.9 acres permitted. The approved post mining land use is rangeland. The weather was clear, warm and the ground was dry. This inspection was carried out as a part of the Division's routine monitoring inspection program.

The permit entrance sign was in place (photo 1) and the permit boundary was marked with t-posts (photo 2).

An old drag line was on site but it appeared inoperable. No other mining equipment was on site and no mining was taking place during the inspection (photo 3). There was a lot of vegetation on the pit floor and the stockpiles indicating that it has been a while since mining has taken place. The annual report states that the last activity was in Feb 2020, which is consistent with the observed conditions.

The topsoil stock pile was on the south side of the permit area and was well vegetated.

PHOTOGRAPHS



Photo 1 – Mine entrance sign facing Hwy 71



Photo 2 – corner post



Photo 3 – Pit area, facing southeast

Inspection Contact Address

Chris Monahan
Dilleys Sand & Gravel
1914 Edmunds St
Brush, CO 80723

CC: