




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Green Bros Pit No 2	MINE/PROSPECTING ID#: M-1995-030	MINERAL: Sand and gravel	COUNTY: Morgan
INSPECTION TYPE: Monitoring	INSPECTOR(S): Brock Bowles	INSP. DATE: October 20, 2021	INSP. TIME: 12:30
OPERATOR: McAtee Construction Company	OPERATOR REPRESENTATIVE: Victor Anido	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE:	BOND AMOUNT: \$45,124.07	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: December 1, 2021	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>N</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>N</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted by Brock Bowles of the Division of Reclamation, Mining and Safety (Division). Victor Anido of McAtee Construction (Operator) were present for the inspection. The Green Brothers Pit #2 Pit is located northeast of Fort Morgan, CO, just outside the city limit. The site is an active 112c operation with 51.2 acres permitted and the post-mining land use is rangeland. The commodity is sand and gravel which is mined using a floating suction dredge. At the time of the inspection it was warm, clear and the ground was dry.

The dredge was in operation during the inspection (photo 1). The dredge was removing material from the southern bank of the pond. Material was being pumped to the screening equipment on the northwestern bank of the pond where it was sorted and stacked. The reject sand was being pumped back into the pond from the western bank.

The topsoil was stripped from in front of the mining area and was stored in a long stockpile (photo 2).

The permit boundary markers were noted. The eastern boundary is a fenceline. The southern boundary is I-76 right-of-way. The western boundary is a fenceline and a tree line. The northern boundary are a set of ponds that were previously released mined areas.

The current disturbed area is about 15 acres in size. The Division holds a \$45,124 bond which is adequate to cover the reclamation costs.

PHOTOGRAPHS



Photo 1 – Dredge and screening equipment in background



Photo 2 – Topsoil stripped from in front of mined area



Photo 3 – Eastern part of mined pond, facing north east

Inspection Contact Address

Victor Anido
McAtee Construction Company
P.O. Box 1908
Sterling, CO 80751

Enclosure

CC: