

PERMIT INFORMATION

Permit Number: C-1996-083	County: Delta			
Mine Name: Bowie No. 2 Mine	Operation Type: Underground			
Operator: Bowie Resources, LLC	Permit Status: Active			
Operator Address:	Ownership: Private			
Mr. Basil Bear	_			
P.O. Box 1488	Operator Representative Present:			
Paonia, CO 81428				
	None			
Operator Representative Signature: (Field Issuance Only)				

INSPECTION INFORMATION

Inspection Start Date: January 10 Inspection End Date: January 10 Inspection End Time: 13:15			Inspection Type: Coal Pa Inspection Reason: Norm Weather: Clear		
Joint Inspection Agency: Joint Inspection Agency:		Joint	oint Inspection Contacts:		
None					
Post Inspection Agency: Post		Post	Post Inspection Contacts:		
None					
Inspector(s):	Inspector's Signature: Signature Date:				
Robert Zuber, P.E.	Phot	D.	21		
Brock Bowles				1/11/2022	

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

Y - Air Resource Protection Y - Roads

N - Availability of Records R - Reclamation Success

N - Backfill & Grading N - Revegetation

Y - Excess Spoil and Dev. Waste
 NA - Explosives
 Y - Subsidence
 Y - Slides and Other Damage

N - Fish & Wildlife
 R - Hydrologic Balance
 NA - Support Facilities On-site
 N - Signs and Markers

Y - Gen. Compliance With Mine Plan

R - Support Facilities Not On-site

N - Other

N - Special Categories Of Mining

Y - Processing Waste N - Topsoil

COMMENTS

On January 10, 2022, Brock Bowles of DRMS took aerial photographs of the mine. The weather was clear, and much of the ground was covered with snow. Rob Zuber of DRMS reviewed the photos on January 11, 2022.

No mining or reclamation activities were being conducted at this site. BRL is focusing reclamation activities on Bowie No. 2 for the foreseeable future.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

The ponds at the West Mine, loadout, and the Coal Storage Area (near Black Bridge Road) contained snow. No problems were identified with these ponds.

RECLAMATION SUCCESS - Rule 4.15, Rule 3:

No erosion was seen at the reclaimed areas of the East Mine or West Mine.

OFFSITE SUPPORT FACILIITES - Rule 4.04, 4.28:

No problems were seen with the Coal Storage Area by Black Bridge Road.

No erosion or other problems were seen at the loadout. This includes the "Y" and the bridge at the northeast side

Number of <u>Partial</u> Inspection this Fiscal Year: 4 Number of <u>Complete</u> Inspections this Fiscal Year: 2 of the loadout area.

Two drill pads and roads to them were inspected: BV-2 and BRL-GMW-01. No erosion or other problems were identified within these areas.

DOCUMENTS RECEIVED - none

OTHER (SPECIFY) - none

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS




East Mine, upper area



East Mine, lower area with RDA and Old Waste Disposal Area

Number of <u>Partial</u> Inspection this Fiscal Year: 4 Number of <u>Complete</u> Inspections this Fiscal Year: 2



West Mine



Road to pad for BRL-GMW-01 (northwest of West Mine)



Road to BV-2 pad



Pad for BV-2 (northwest of East Mine)



Loadout - northeast area with bridge



Loadout (pond is circled)