



**PERMIT INFORMATION**

<b>Permit Number:</b> C-1992-081 <b>Mine Name:</b> Hayden Gulch Loadout <b>Operator:</b> Hayden Gulch Terminal, LLC <b>Operator Address:</b> Ms Miranda Kawcak  P.O. Box 670 Hayden, CO 81639	<b>County:</b> Routt <b>Operation Type:</b> Loadout <b>Permit Status:</b> Active <b>Ownership:</b> Private  <b>Operator Representative Present:</b>  None
<b>Operator Representative Signature: (Field Issuance Only)</b>  	

**INSPECTION INFORMATION**

<b>Inspection Start Date:</b> January 10, 2022 <b>Inspection Start Time:</b> 10:00 <b>Inspection End Date:</b> <b>Inspection End Time:</b>		<b>Inspection Type:</b> Aerial Inspection <b>Inspection Reason:</b> Normal I&E Program <b>Weather:</b> Clear	
<b>Joint Inspection Agency:</b>  None		<b>Joint Inspection Contacts:</b>  	
<b>Post Inspection Agency:</b>  None		<b>Post Inspection Contacts:</b>  	
<b>Inspector(s):</b>  Tabetha Lynch  Brock Bowles	<b>Inspector's Signature:</b>  		<b>Signature Date:</b>  1/19/2022

**Inspection Topic Summary**NOTE: **Y**=Inspected **N**=Not Inspected **R**=Comments Noted **V**=Violation Issued **NA**=Not Applicable**N** - Air Resource Protection**N** - Availability of Records**N** - Backfill & Grading**N** - Excess Spoil and Dev. Waste**N** - Explosives**N** - Fish & Wildlife**Y** - Hydrologic Balance**R** - Gen. Compliance With Mine Plan**N** - Other**N** - Processing Waste**Y** - Roads**Y** - Reclamation Success**N** - Revegetation**N** - Subsidence**N** - Slides and Other Damage**N** - Support Facilities On-site**N** - Signs and Markers**N** - Support Facilities Not On-site**N** - Special Categories Of Mining**N** - Topsoil**COMMENTS**

This was an aerial inspection of the Hayden Gulch Loadout; DRMS Permit No. C-1992-081, operated by Hayden Gulch Termnal, LLC. The photos were taken by Brock Bowles on 1/10/22 and evaluated by Tabettha Lynch with the Colorado Division of Reclamation, Mining, and Safety (Division) on 1/19/22. The weather was mostly clear and the site was snow covered during the inspection.

**GENERAL MINE PLAN COMPLIANCE:**

Reclamation of tracks on Hwy 40; Photo below shows the section of tracks that crossed Hwy 40 that were removed in 2021.

**ROADS – Rule 4.03**

Construction 4.03.1(3)/4.03.2(3), Drainage 4.03.1(4)/4.03.2(4), Surfacing and Maintenance 4.03.1(5) and

Number of Partial Inspection this Fiscal Year: 5

Number of Complete Inspections this Fiscal Year: 2

(6)/4.03.2(5) and (6), Reclamation 4.03.1(7)/4.03.2(7):

Former tie across haul road appears to be being plowed and maintained. Portions of the trail and the trail parking area appear to have been plowed (photo below).



Train Loop shown below. Ponds appear snow covered and not likely holding additional water as vegetation is visible. The loop is currently being used by public as a walking trail. TAHR is plowed in the photo below.



Number of Partial Inspection this Fiscal Year: 5

Number of Complete Inspections this Fiscal Year: 2

**ENFORCEMENT ACTIONS/COMPLIANCE**

No enforcement actions were initiated as a result of this inspection, nor are any pending.

Number of Partial Inspection this Fiscal Year: 5

Number of Complete Inspections this Fiscal Year: 2