



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

PERMIT INFORMATION

Permit Number: C-1982-056 Mine Name: Foidel Creek Mine Operator: Twentymile Coal, LLC Operator Address: Ms Miranda Kawcak 29515 Routt County Road No. 27 Oak Creek, CO 80467	County: Routt Operation Type: Underground Permit Status: Active Ownership: Private
	Operator Representative Present: Miranda Kawcak
Operator Representative Signature: (Field Issuance Only) 	

INSPECTION INFORMATION

Inspection Start Date: February 23, 2022 Inspection Start Time: 09:00 Inspection End Date: February 23, 2022 Inspection End Time: 13:00		Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Snowing	
Joint Inspection Agency: None		Joint Inspection Contacts: 	
Post Inspection Agency: None		Post Inspection Contacts: 	
Inspector(s): Tabetha Lynch	Inspector's Signature: 		Signature Date: 2/28/22

Inspection Topic SummaryNOTE: **Y**=Inspected **N**=Not Inspected **R**=Comments Noted **V**=Violation Issued **NA**=Not Applicable

N - Air Resource Protection
N - Availability of Records
N - Backfill & Grading
N - Excess Spoil and Dev. Waste
N - Explosives
N - Fish & Wildlife
Y - Hydrologic Balance
R - Gen. Compliance With Mine Plan
N - Other
N - Processing Waste

Y - Roads
N - Reclamation Success
N - Revegetation
Y - Subsidence
N - Slides and Other Damage
N - Support Facilities On-site
N - Signs and Markers
N - Support Facilities Not On-site
N - Special Categories Of Mining
Y - Topsoil

COMMENTS

This was a partial inspection of the Foidel Creek Mine; DRMS Permit No. C-1982-056, operated by Twentymile Coal, LLC. (TC). This inspection was conducted by Tabetha Lynch with the Colorado Division of Reclamation, Mining, and Safety (Division). Nikie Gagnon with the Division was also present. Weather was cold and snowing at the time of inspection. Not all areas of the mine were accessible due to snow and drifting.

GENERAL MINE PLAN COMPLIANCE:

At the time of inspection a grout was being mixed at the 7E cement drop pad. Fly ash trucks were hauling ash to the pad for the mixture. The grout/cement mixture will ultimately be mined out as the longwall passes through. Photos below of the work at the 7E pad.



Number of Partial Inspection this Fiscal Year: 6

Number of Complete Inspections this Fiscal Year: 2



Active roads were well plowed. Stream buffer signs and barrier were in place at the facilities area. Ponds were mostly snow and ice covered. Straw bales have been placed between the vent fan output and the access road to the ventilation pad. The water air was creating a visibility issue for traffic on the access road. Per the operator the bales are weed free straw. Shown below.



No issues were documented as a result of this inspection.

DOCUMENTS RECEIVED

Subsidence monitoring report was received onsite.

OTHER (SPECIFY)

Number of Partial Inspection this Fiscal Year: 6

Number of Complete Inspections this Fiscal Year: 2

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

Number of Partial Inspection this Fiscal Year: 6

Number of Complete Inspections this Fiscal Year: 2