

Zuber - DNR, Rob <rob.zuber@state.co.us>

# **Bowie No. 2 inspection report**

1 message

Zuber - DNR, Rob <rob.zuber@state.co.us> Mon, N To: Basil Bear <basilbear@wolverinefuels.com>, Tamme Bishop <tamme.jestover@bresnan.net>

Mon, Mar 7, 2022 at 7:02 AM

Basil -

Here is the report for Bowie #2.

Rob

Rob Zuber, P.E. Environmental Protection Specialist Active Mines Regulatory Program



I am working remotely and can be reached by cell at 720.601.2276.

Physical Address: 1313 Sherman Street, Room 215 Denver, CO 80203 Mailing Address: Division of Reclamation, Mining and Safety, Room 215 1001 East 62nd Avenue Denver, CO 80216 rob.zuber@state.co.us | http://drms.colorado.gov

T INSP-REPORTC\_C1996083\_RDZ\_03062022045003.pdf 2577K



# **PERMIT INFORMATION**

Permit Number: C-1996-083 Mine Name: Bowie No. 2 Mine Operator: Bowie Resources, LLC Operator Address: Mr. Basil Bear P.O. Box 1488 Paonia, CO 81428 County: Delta Operation Type: Underground Permit Status: Active Ownership: Private

**Operator Representative Present:** 

Basil Bear

**Operator Representative Signature:** (Field Issuance Only)

## **INSPECTION INFORMATION**

Inspection Start Date: March 3, 2 Inspection Start Time: 12:00 Inspection End Date: March 3, 2 Inspection End Time: 14:40			<b>Inspection Type:</b> Coal Comp <b>Inspection Reason:</b> Normal I <b>Weather:</b> Clear	*
Joint Inspection Agency:		Joint Inspection Contacts:		
None				
Post Inspection Agency:		Post	Inspection Contacts:	
None				
Inspector(s):	Inspecto	r's Sig	gnature:	Signature Date:
Robert Zuber, P.E.	Phot D. Zh			
				3/6/2022

#### Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

- Y Air Resource Protection
  R Availability of Records
  Y Backfill & Grading
  NA Excess Spoil and Dev. Waste
  NA Explosives
  R Fish & Wildlife
  R Hydrologic Balance
  Y Gen. Compliance With Mine Plan
- N Other
- **R** Processing Waste

- **R** Roads
- Y Reclamation Success
- Y Revegetation
- Y Subsidence
- ${\bf R}\,$  Slides and Other Damage
- ${\bf R}\,$  Support Facilities On-site
- ${\bf R}\,$  Signs and Markers
- ${\bf Y}\,$  Support Facilities Not On-site
- Y Special Categories Of Mining
- Y Topsoil

## **COMMENTS**

A complete inspection was conducted by Rob Zuber of DRMS on March 3, 2022. Basil Bear of Bowie Resources, LLC (BRL) did not participate in the field inspection, but was in the office during the records check.

BRL continues to focus their efforts on Gob Pile #3. Based on weather and ground conditions, Gob Pile #2 may be the focus for part of 2022.

The weather was clear and seasonably warm. The ground was covered with snow in some areas and very muddy in other areas. The sites along the Hubbard Creek Road were not inspected due to inaccessible road conditions. Basil indicated that he would have his staff address this problem in the near future.

### AVAILABILITY OF RECORDS - Rule 5.02.4(1):

The records were found to be well organized and complete. A list of records is provided at the end of this report.

FISH and WILDLIFE – Rule 4.18:

Many deer and elk were seen on site. Turkeys were seen near the train loadout.

### HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Six sediment ponds were inspected: B, C, D, F, J, and K. None of the ponds were discharging. Five of the ponds contained water from recent precipitation, but none of the ponds were close to full. (In Pond K, there was no standing water but the soil was muddy.) No significant problems were identified with embankments, spillways, inlet channels, or other features of the ponds.

Number of <u>Partial</u> Inspection this Fiscal Year: 4 Number of <u>Complete</u> Inspections this Fiscal Year: 3

Page 2 of 10

PROCESSING WASTE/COAL MINE WASTE PILES – Rule 4.10 and 4.11 Drainage Control; Surface Stabilization; Placement:

Overall the gob piles appeared stable. Due to extremely muddy conditions, the piles were observed from afar.

ROADS – Rule 4.03 Construction 4.03.1(3)/4.03.2(3), Drainage 4.03.1(4)/4.03.2(4), Surfacing and Maintenance4.03.1(5) and (6)/4.03.2(5) and (6), Reclamation 4.03.1(7)/4.03.2(7):

No significant problems were seen with the road to the portals, although some small areas of the road may require repairs in the next year or two to prevent larger problems. The hillsides above and below this road were generally stable.

The road to Gob Pile #2 was very muddy.

## SLIDES and DAMAGE - Rule 4.12:

It appears that slumps have not moved significantly in the recent past. These include slumps by the B Portal and by Curve Number 11 along the Haul Road. The Division recommends that these continue to be monitored closely by BRL.

### SUPPORT FACILITIES - Rule 4.04:

All benches appeared stable with no signs of erosion. These include the pads for the Utility Bench, B Portal bench and the D Portal bench. Other comments on facilities:

- No problems were seen in the area around the Pump House and Filter Building.
- No erosion was seen on the slopes near the Preparation Plant and nearby water tank.
- The slopes above and below the Coal Stockpile Pad are stable.
- The material storage area beside Topsoil Stockpile A is very stable.
- No erosion or other problems were seen along the conveyor corridors.
- No erosion or other problems were identified at the eastern portion of the Unit Train Loadout.

### SIGNS AND MARKERS – Rule 4.02:

Disturbance markers, topsoil stockpile markers, and entrance signs were seen in many locations, and no compliance issues were noted.

### **DOCUMENTS RECEIVED - none**

#### **OTHER (SPECIFY)** - none

## **ENFORCEMENT ACTIONS/COMPLIANCE**

No enforcement actions were initiated as a result of this inspection, nor are any pending.

## **PHOTOGRAPHS**



Road to Gob Pile #2, west of old power plant (pile on upper left)

Number of <u>Partial</u> Inspection this Fiscal Year: 4 Number of <u>Complete</u> Inspections this Fiscal Year: 3



North side of Gob Pile #3



East end of Gob Pile #3



**B** Portal bench



**B** Portal bench



Curve 11 slump



Slope below D Portal bench



Pond F





Number of <u>Partial</u> Inspection this Fiscal Year: 4 Number of <u>Complete</u> Inspections this Fiscal Year: 3

# **AVAILABILITY OF RECORDS**

PERMIT RECORDS		HYDROLOGIC RECORDS	
DRMS Permit	Exp. 4 April 2022	NPDES Permit	CO-0044776,
			Exp.Sept. 2024
Permit Application w/Revisions	yes	NPDES Records (DMRs)	Through
	-		February 2022
Findings Document	RN4,	Stormwater Management Plan	Revised
	20 Novmbr. 2017		January 2020
Insurance Certificate	Expires 1 May 2022	SPCC Plan	May 2013
Bond Documents	SEE	MSHA Pond Inspections	NA
	COMMENT 1	-	
Phased Bond Release	SL2,		NA
Documents/Findings	30 Decmbr. 2016	State Engineer's Pond Inspection	
Air Emission Permits	98DL0726	Quarterly Pond Inspections	4Q 2021
	Exp. 2024		
County Special Use Permits	NA	Annual Hydrology Reports	2020
UG Mining Landowner Notification	Several years	<ul> <li>Ground Water Monitoring</li> </ul>	yes
Subsidence Monitoring Reports	NA	• Surface Water Monitoring	yes
Subsidence Monitoring Data	NA	• Spring & Seep Monitoring	NA
Rill & Gully Survey	March 31, 2021	Mine Water Discharge	NA
		Monitoring	
Vegetation Monitoring Data	NA	• Mine Inflow Study	NA
Specific Variance Approvals	NA	• Water Consumption Records	NA
Annual Reclamation Reports	2020	Well Permits	NA
Midterm Review Documents	MT5,		
	3 October 2019		
DRMS/OSM Inspection	Through		
Reports/Enforcement Actions	January 2022	BLASTING RECORDS	
Transfers/Succession of Operator	10 August 2009	Blasting Publication	NA
Temporary Cessation Notification	NA	Blasting Records (3 years)	NA
Reclamation Cost Estimate	SEE	ATFE Explosives Permit	NA
	COMMENT 2		
CERTIFICATIONS		Blasting Variances	NA
Pond Certifications	2Q 2021	Pre-Blast Surveys	NA
Fill Certifications for Underground	Vol. IV for Gob	ADDITIONAL RECORDS	
Development Waste	Pile #1	(specify)	
<ul> <li>Quarterly Inspections</li> </ul>	4Q 2021	SWMP Report	January 2022
<ul> <li>Compaction Testing</li> </ul>	November 2021		
<ul> <li>Final Certification</li> </ul>	NA		
Certs. for Coal Processing Waste	Vols IX, XI (Gob		
Banks	Piles 2, 3, 4)		
Haul Road Certifications	Yes, 2013		
Access Road Certifications	Map 15 series		

Number of <u>Partial</u> Inspection this Fiscal Year: 4 Number of <u>Complete</u> Inspections this Fiscal Year: 3

### COMMENTS:

- 1. Bond documents entail five corporate sureties (Lexon Company) for total of \$10,971,057.58:
  - Bond # 1071397 for \$3,154,277.10
  - Bond # 1071402 for \$1,024,357.97
  - Bond # 1071403 for \$2,500,000.00
  - Bond # 1071404 for \$2,217,169.51
  - Bond # 1071405 for \$2,075,253.00.
- 2. The RCE for MT-05 totaled \$10,149,223. Additional \$311 from TR-119.