


Mining operation appears to be on the east side of the access point not the west side as shown on the DRMS document.



USR17-0055 CR 2 - Safety Concern

Mud on the road needs to be cleaned up.
Tracking control needs to be installed.

