




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Crader Gravel Pit	MINE/PROSPECTING ID#: M-1981-114	MINERAL: Sand and gravel	COUNTY: La Plata
INSPECTION TYPE: Monitoring	INSPECTOR(S): Lucas West	INSP. DATE: March 16, 2022	INSP. TIME: 15:50
OPERATOR: La Plata County	OPERATOR REPRESENTATIVE: Leslie Jakoby	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: \$0.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: April 13, 2022	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the normal monitoring program established by the Colorado Division of Reclamation, Mining and Safety. The Crader Pit is an active 112(c) permit located in and operated by La Plata County. The site consists of 37.9 permitted acres located just north of Highway 550 near Farmington hill at approximately 6780 feet in Elevation. Access to the site is shared with the Clayton Homes office on Highway 550 and is controlled by a locked gate along the access road. No financial warranty is held for the site. Five Photos accompany this report to illustrate current site conditions.

Proper mine identification signage was posted at the entrance to site and is shown in Photo One. The permit boundaries are clearly marked with signs and earthen berms around the site. The site was not active during the inspection and the only equipment noted on site was a Front End Loader. The mining activity is being carried out in phases with all of the active mining being located in Phase One. The active highwall is approximately 40 feet tall on average and stretches between 100 and 150 linear feet. The highwall is in good condition and appears to be stable as seen in Photo Two. The boundary between the Crader pit and the adjacent Montoya pit operated by C & J Gravel has been mined out and the boundary is marked by a suspended cable. The boundary can be seen in Photo Three.

Several stockpiles were observed on site, some being located on the pit floor shown in Photos Four and Five. All stockpiles were in good condition and appear to be stable. The un-mined areas of Phase 2 and Phase 8, which are adjacent sections, are being used as a materials storage area and fenced in facility. All materials and items being stored both in and out of the fenced area are in a neat and orderly fashion and are not considered a problem. The site exhibits positive drainage and no erosional issues were noted during this inspection. No noxious weeds were observed, and the operator indicated that the site undergoes ongoing weed management by the County weed department.

The overall footprint of the site is in good condition and free from trash and debris. No problems or possible violations were noted during the inspection. No problems or possible violations were observed on site, all responses to this report should be directed to Lucas West at the Colorado Division of Reclamation, Mining and Safety at Room 215, 1001 E 62nd Ave. Denver, CO 80216, by email at lucas.west@state.co.us or by phone at (303)-866-3567 Ext. 8187.

Inspection Contact Address

Leslie Jakoby
La Plata County
26616 Highway 160 South
Durango, CO 81301

CC: Travis Marshall, DRMS
Dustin Czapla, DRMS

PHOTOGRAPHS




Photo One: View southwest, showing the proper Mind ID signage posted at the entrance to the site.



Photo Two View west, showing an example of the highwall located on site. The highwall slopes to the north and is an average of 20 feet tall spanning approximately 150 LF.





Photo Five: View west, showing another small stockpile located on site. All stockpiles are in good condition and show no signs of erosion or instability.