



Seneca Yoast Mine
29515 Routt County Road 27
Oak Creek, CO 80467

April 19, 2022

Robin Reilly
Colorado Division of Reclamation, Mining and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

RE: Yoast Mine, Permit C-94-082, First Quarter 2022 IIR

CDRMS:

In accordance with Rule 4.05.9(17), please find enclosed the Yoast Mine (YM) Impoundment Inspection Report (IIR) and Impoundment Inspection Log (IIL). Please contact me with any comments and/or questions.

Sincerely,

Miranda Kawcak
Environmental Manager
Peabody, Colorado Operations

Enclosure: YM IIR

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yoast Mine(Seneca Coal Co)	Facility Configuration	Cross-Valley Pond	Quarterly Impoundment Inspection Form
	3/23/2022	Date Last Inspected	10/27/2021	
	Pond #010	Pond Location	NW¼ NE¼, Sec. 8, T5N, R87W	
	CO-0000221 D.P. 010	Site Location	8.5 mi SE of Hayden, CO	
	Miranda Kawcak	Inspector	Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (ft above or below principal spillway)			X	-0.6
Existing Embankment Freeboard (10.1 ft)			9.5	
Outflow (gpm)			X	0.0
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENACE				
Maintenance Required			X	SNOW COVERED
Maintenance Performed			X	
Additional Comments		X		

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yeast Mine(Seneca Coal Co)	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Cross-Vally Pond	Quarterly Impoundment Inspection Form
	3/23/2022		10/28/2021	
	Pond #011		NW¼ SW¼, Sec. 16, T5N, R87W	
	CO-0000221 D.P.011		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (ft above or below principal spillway)			X	-2.6
Existing Embankment Freeboard (5.1 ft)			2.5	
Outflow (gpm)			X	0.0
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENACE				
Maintenance Required			X	SNOW COVERED
Maintenance Performed			X	
Additional Comments		X		

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yoast Mine(Seneca Coal Co)	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Cross-Vally Pond	Quarterly Impoundment Inspection Form
	3/23/2022		10/27/2021	
	Pond #011A		SW¼ NW¼, Sec. 16, T5N, R87W	
	N/A		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (ft above or below principal spillway)			X	0.0
Existing Embankment Freeboard (4.6 ft)		4.6		
Outflow (gpm)			X	
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENANCE				
Maintenance Required			X	SNOW COVERED
Maintenance Performed			X	
Additional Comments		X		

Top of Sediment Storage = 2.1 feet below top of pipe

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yoast Mine(Seneca Coal Co)	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Cross-Vally Pond	Quarterly Impoundment Inspection Form
	3/22/2022		10/27/2021	
	Pond #012		NE¼ NW¼, Sec. 19, T5N, R87W	
	CO-0000221 D.P. 012		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (ft above or below principal spillway)		X		0.1
Existing Embankment Freeboard (9.0 ft)		8.9		
Outflow (gpm)		X		44.7
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENANCE				
Maintenance Required			X	SNOW COVERED
Maintenance Performed			X	
Additional Comments		X		

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yoast Mine(Seneca Coal Co)	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Cross-Vally Pond	Quarterly Impoundment Inspection Form
	3/22/2022		10/27/2021	
	Pond #012A		NE¼ NW¼, Sec. 19, T5N, R87W	
	N/A		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (ft above or below principal spillway)			X	-1.7
Existing Embankment Freeboard (4.6 ft)			2.9	
Outflow (gpm)			X	
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENANCE				
Maintenance Required			X	SNOW COVERED
Maintenance Performed			X	
Additional Comments		X		

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yoast Mine(Seneca Coal Co)	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Cross-Vally Pond	Quarterly Impoundment Inspection Form
	3/22/2022		10/27/2021	
	Pond #013		SE¼ NW¼, Sec. 19, T5N, R87W	
	CO-0000221 D.P. 013		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE	PROBLEM		COMMENTS	
	YES (Above)	NO (Below)		
GENERAL				
Water Level (ft above or below principal spillway)		X	-1.3	
Existing Embankment Freeboard (4.0 ft)		2.7		
Outflow (gpm)		X	0.0	
EROSION				
Rills & Gullies on Embankment		X		
Wave Erosion		X		
Spillway Erosion		X		
Burrows		X		
Other		X		
STRUCTURAL				
Differential Settling		X		
Cracks or Slides		X		
Seepage		X		
Other		X		
STRUCTURES				
Principal Spillway				
Clogged Orifice		X		
Clogged or Damaged Culvert		X		
Damaged Headgate		NA		
Emergency Spillway				
Erosion		X		
Riprap		X		
Clogged or Damaged Culvert		X		
Other		X		
MAINTENACE				
Maintenance Required		X	SNOW COVERED	
Maintenance Performed		X		
Additional Comments	X			

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yoast Mine(Seneca Coal Co)	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Cross-Vally Pond	Quarterly Impoundment Inspection Form
	3/22/2022		10/27/2021	
	Pond #014		NE¼ SW¼, Sec. 19, T5N, R87W	
	CO-0000221 D.P. 014		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (ft above or below principal spillway)			X	-2.0
Existing Embankment Freeboard (6.8 ft)			4.8	
Outflow (gpm)			X	0.0
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENANCE				
Maintenance Required			X	SNOW COVERED
Maintenance Performed			X	
Additional Comments		X		

Mining Area	Yeast Mine(Seneca Coal Co)	Facility Configuration	Stockpond	Quarterly Impoundment Inspection Form
Date Inspected	10/27/2021	Date Last Inspected	9/23/2021	
Impoundment	Stock Tank ST-1	Pond Location	SW¼ Sec. 20, T5N, R87W	
NPDES ID No	N/A	Site Location	8.5 mi SE of Hayden, CO	
Owner's Rep	Miranda Kawcak	Inspector	Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE	PROBLEM		COMMENTS	
	YES (Above)	NO (Below)		
GENERAL				
Water Level (ft above or below principal spillway)		X		
EROSION				
Rills & Gullies on Embankment		X		
Wave Erosion		X		
Spillway Erosion		X		
Burrows		X		
Other		X		
STRUCTURAL				
Differential Settling		X		
Cracks or Slides		X		
Seepage		X		
Other		X		
STRUCTURES				
Principal Spillway				
Clogged Orifice		NA		
Clogged or Damaged Culvert		NA		
Damaged Headgate		NA		
Emergency Spillway				
Erosion		X		
Riprap		X		
Clogged or Damaged Culvert		NA		
Other		X		
MAINTENANCE				
Maintenance Required		X	SNOW COVERED	
Maintenance Performed		X		
Additional Comments	X			

IMPOUNDMENT INSPECTION LOG

JOB DATA

JOB NAME: PEC Hydrologic Services	CLIENT: Peabody	JOB(s): 2021-095 (PSCM), 2021-096 (SCC)
-----------------------------------	-----------------	---

FLOW DATA

SITE ID	COMPANY	MINE	DATE	WATER LEVEL (FT)	OUTFLOW (GPM)	OBSERVATIONS	MAINTENANCE (Y/N)
002	Sage Creek	Sage Creek	3-22-22	0.4	32.7	water flowing under Flume	Y
003	Sage Creek	Sage Creek	3-22-22	0.1	1.0	snow covered	N
004	Sage Creek	Sage Creek	3-22-22	0.1	36.4	snow covered	N
Lower Sump	Sage Creek	Sage Creek	3-22-22	0.2	134	snow covered	N
PECOCO	Sage Creek	Sage Creek	3-22-22	0.2	107	snow covered	N
Portal Sump 1	Sage Creek	Sage Creek	3-22-22	-	-	snow covered, frozen	N
Portal Sump 2	Sage Creek	Sage Creek	3-22-22	-	-	snow covered	N
Spill Control 2	Sage Creek	Sage Creek	3-22-22	-	-	snow covered	N
Truck Wash	Sage Creek	Sage Creek	3-22-22	-	-	Dry	N
Upper Sump	Sage Creek	Sage Creek	3-22-22	0.2	71	snow covered	N
001	Seneca	Hayden Gulch	3-22-22	-	-	snow covered	N
002	Seneca	Hayden Gulch	3-22-22	-	-	snow covered	N
005	Seneca	Seneca II West	3-23-22	-2.1	-	snow covered	N
006	Seneca	Seneca II West	3-23-22	0.1	26.3	snow covered	N
009	Seneca	Seneca II West	3-22-22	-4.0	-	snow covered	N
015	Seneca	Seneca II West	3-22-22	-1.0	-	snow covered	N
016	Seneca	Seneca II West	3-23-22	0.1	27.7	snow covered	N
017	Seneca	Seneca II West	3-23-22	-0.6	-	snow covered	N
T-1	Seneca	Seneca II West	3-22-22	-	-	winter	-
T-18	Seneca	Seneca II West	3-22-22	-	-	winter	-
T-2	Seneca	Seneca II West	3-22-22	-	-	winter	-
T-20	Seneca	Seneca II West	3-22-22	-	-	winter	-
T-22	Seneca	Seneca II West	3-22-22	-	-	winter	-
T-24	Seneca	Seneca II West	3-22-22	-	-	winter	-
T-25	Seneca	Seneca II West	3-22-22	-	-	winter	-
T-26	Seneca	Seneca II West	3-22-22	-	-	winter	-

SITE ID	COMPANY	MINE	DATE	WATER LEVEL (FT)	OUTFLOW (GPM)	OBSERVATIONS	MAINTENANCE (Y/N)
T-27	Seneca	Seneca II West	3-22-22	-	-	winter	-
T-3	Seneca	Seneca II West	3-22-22	-	-	winter	-
T-5	Seneca	Seneca II West	3-22-22	-	-	winter	-
010	Seneca	Yoast	3-23-22	-0.6	-	snow covered	N
011	Seneca	Yoast	3-23-22	-2.6	-	snow covered	N
011A	Seneca	Yoast	3-23-22	-	-	winter	-
012	Seneca	Yoast	3-22-22	0.1	44.7	snow covered	N
012A	Seneca	Yoast	3-22-22	-1.7	-	snow covered	N
013	Seneca	Yoast	3-22-22	-1.3	-	snow covered	N
014	Seneca	Yoast	3-22-22	-2.0	-	snow covered	N
ST-1	Seneca	Yoast	3-23-22	-	-	winter	-

NOTES