




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Deakins Pit	MINE/PROSPECTING ID#: M-2001-060	MINERAL: Sand and gravel	COUNTY: Moffat
INSPECTION TYPE: Monitoring	INSPECTOR(S): Zach Trujillo	INSP. DATE: May 12, 2022	INSP. TIME: 10:00
OPERATOR: 3B Enterprises, LLC	OPERATOR REPRESENTATIVE: None	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: \$71,160.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
WEATHER: Windy	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: May 20, 2022	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Colorado Division of Reclamation, Mining and Safety normal monitoring program by Zach Trujillo. The Deakins Pit is a 112c permitted site that includes a total of 57.5 permitted acres with a 32.6 acre max disturbance. It is located off of East 1st Street in Craig Colorado. No representative from 3B Enterprises, LLC accompanied the inspection.

The Division currently holds a financial warranty amount of \$71,160 for this site. The bond was last reviewed in 2019 with SI-3. In an effort to ensure the Financial Warranty adequately, reflects the actual current cost of fulfilling the requirements of the approved reclamation plan the Division will be updating the reclamation cost estimate. You will be notified if the current bond is found insufficient. A copy of the staff calculations will be sent under separate cover.

Hydrologic Balance:

Both pit areas have exposed ground water. Based on the elevation and grade of both pits, all surface runoff is maintained within the affected pit areas.



East pit.

Gen. Compliance With Mine Plan:

The permit is divided into two pits, the east and west pit. The two pits are divided by 1st Street. The site was operating at the time of the inspection in both the east and west pits. Active mining is occurring within the east pit. Loader operations were taking sand and gravel from the east of the pit to a processing area. The west pit had no active mining going on but multiple stockpiles are located within the pit.



Stockpiles in west pit.

Reclamation Success:

Reclamation was inspected in both pit areas. Reclamation in the west pit is along south eastern portion of the pit adjacent to 1st Street. East pit reclamation is located to the north again adjacent to 1st Street. Both areas shows vegetation establishment. From the 2021 Annual Report, a total of 20 acres have been backfilled, 15 acres graded and topsoiled and 20 acres reseeded.

Signs and Markers:

The mine identification sign and affected area boundary markers are in place and in compliance with Rule 3.1.12. The sign is located at the entrance of the permit boundary on the east side including all information for compliance.



Mine identification sign.

Topsoil:

Topsoil piles were observed in both pits adjacent to 1st Street. Piles were vegetated and no issues observed.

Inspection Contact Address

None
3B Enterprises, LLC
P.O. Box 1665
Craig, CO 81626

Enclosure

CC: Jason Musick