



SECOND QUARTER 2022 POND INSPECTION REPORT

Pond Inspection Date: June 29, 2022

OPERATOR:	OXBOW MINING, LLC, (Formerly TCLLC.)	
MINE:	TERROR CREEK LOADOUT	
POND IDENTIFICATION	P-1 (001)	Dugout (002)
TYPE OF POND	Sediment	Sediment
APPROXIMATE WATER LEVEL	0.0' dry	0.0' dry
SEDIMENT (% total storage)	<5 %	<5%
OUTFLOW (cfs)	0	0
FEATURES		
EROSIONAL		
Rills & Gullies	No	No
Inadequate Vegetation	No	No
Outlet Channel Erosion	No	No
Burrows	No	No
Other	No	No
STRUCTURAL		
Differential Settling	No	No
Cracks or Slides	No	No
Seepage	No	No
Other	No	No
APPURTENANT STRUCTURES		
Defective Spillways	No	No
Dewatering Devices Clogged	No	No
Faulty Gates, Etc.	No	No
Other	No	No
MAINTENANCE REQUIRED	No	No

ADDITIONAL COMMENTS: The design sediment level is 18" below the invert of the primary spillway on P-1. No erosion and adequate vegetative growth remains. Ponds are maintained as designed and in accordance with the approved plan.

REFERENCE DRAWINGS:

Map 7


Exh. 9, p. 11

SWMP Controls: The SWMP control devices were inspected and all SWMP control devices were found to be in adequate condition. See Map 14 for details.

Inspected By:


Douglas A. Smith

Under Direction of:


Michael W. Ludlow
Colorado Registered Professional Engineer No. 24046