

QUARTERLY POND INSPECTION REPORT

Operator:	ARC McClane Canyon LLC	Quarter:	Second 2022
Mine:	McClane Canyon Mine C-1980-004	Inspection Date:	24-Jun-22

Pond Identification

Sediment				
Pond				

Status During Inspection:

Approximate Water Level	5,453.0			
Sediment (% total storage)	100%			
Outflow (cfs)	0			

Features

Problem				
Yes/No				

Erosional

Rills & Gulleys	No			
Inadequate Vegetation	No			
Outlet Channel Erosion	No			
Burrows	No			
Other	No			

Structural

Differential Settling	No			
Cracks or Slides	No			
Seepage	No			
Other	No			

Appurtenant Structures

Defective Spillways	No			
Dewatering Devices Clogged	No			
Faulty Gates, Etc.	No			
Other	No			


Additional Comments

Invert of primary spillway is at elevation 5457.00.
 Invert of emergency spillway is at elevation 5462.00.
 Pond bottom about 7' below primary spillway

Maintenance Required:

None

Name of Inspector: Chuck Silengo



J. E. Stover
 Colorado P. E. 19230 Date