




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

| | | | |
|---|---|--|-----------------------------|
| MINE NAME: Robins Consolidated Pit | MINE/PROSPECTING ID#: M-1991-133 | MINERAL: Gravel | COUNTY: Conejos |
| INSPECTION TYPE: Monitoring | INSPECTOR(S): Clayton Wein | INSP. DATE: August 9, 2022 | INSP. TIME: 10:30 |
| OPERATOR: Robins Construction, LLLP | OPERATOR REPRESENTATIVE: Randy Robins | TYPE OF OPERATION: 112c - Construction Regular Operation | |
| REASON FOR INSPECTION: Normal I&E Program | BOND CALCULATION TYPE: Complete Bond | BOND AMOUNT: \$24,407.62 | |
| DATE OF COMPLAINT: NA | POST INSP. CONTACTS: None | JOINT INSP. AGENCY: None | |
| WEATHER: Clear | INSPECTOR'S SIGNATURE:  | SIGNATURE DATE: August 23, 2022 | |

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

| | | |
|--|--|---------------------------------|
| (AR) RECORDS----- <u>N</u> | (FN) FINANCIAL WARRANTY----- <u>N</u> | (RD) ROADS----- <u>Y</u> |
| (HB) HYDROLOGIC BALANCE----- <u>Y</u> | (BG) BACKFILL & GRADING----- <u>N</u> | (EX) EXPLOSIVES----- <u>N</u> |
| (PW) PROCESSING WASTE/TAILING---- <u>N</u> | (SF) PROCESSING FACILITIES----- <u>Y</u> | (TS) TOPSOIL----- <u>Y</u> |
| (MP) GENL MINE PLAN COMPLIANCE- <u>Y</u> | (FW) FISH & WILDLIFE----- <u>N</u> | (RV) REVEGETATION---- <u>N</u> |
| (SM) SIGNS AND MARKERS----- <u>Y</u> | (SP) STORM WATER MGT PLAN---- <u>N</u> | (RS) RECL PLAN/COMP-- <u>N</u> |
| (ES) OVERBURDEN/DEV. WASTE----- <u>N</u> | (SC) EROSION/SEDIMENTATION--- <u>Y</u> | (ST) STIPULATIONS----- <u>N</u> |
| (AT) ACID OR TOXIC MATERIALS----- <u>N</u> | (OD) OFF-SITE DAMAGE----- <u>N</u> | |

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This was a normal monitoring inspection of the Robins Consolidated pit (also known as the Valdez Pit) conducted on August 9, 2022. The inspection was completed by Clayton Wein of the Colorado Division of Reclamation, Mining and Safety (the Division). The operator was represented by Randy Robins and Scott Johnson. The weather was clear with a temperature of 75 degrees F. The ground conditions were mostly dry with a few puddles from precipitation the day prior to the inspection.

The Robins Consolidated Pit is an 112c operation consisting of 45.85 acres. The site is located on the south end of Antonito Colorado, accessed from County Road 13.

The mine identification sign was posted to the right side of the entrance to the mine site. The sign displayed the permit number and operator. The affected area boundary markers were easily identified and could be located from one marker to the next. There were no indications of off-site impacts and all activities were occurring within the current boundary.

The site was active during the inspection. Material was being mined from the north highwall and material was being processed through the batch plant. Various stockpiles of material were located throughout the pit floor. Water was impounded in the sediment pond, located in the southern portion of the pit floor. The embankments of the pond were stable and there were no indications of erosion. The depth of the pit was at approximately 20 feet.

Topsoil stockpiles located at the site were stable with vegetative cover. There were no indications of erosion or loss of topsoil resource.

As a result of this inspection, the Division will be conducting an update to the reclamation cost estimate. The new reclamation cost estimate will be sent to the operator under a separate cover.

The Division did not identify any maintenance items or possible violations during the inspection.

Questions or responses to this inspection report should be directed to Clayton Wein at the Division of Reclamation, Mining and Safety Grand Junction Field Office, located at 101 south 3rd Street, Room 301, Grand Junction Colorado 81501. Or by phone at (303)-866-3567 x8185.

PHOTOGRAPHS





Inspection Contact Address

Randy Robins
Robins Construction, LLLP
38767 State Hwy 17
Antonito, CO 81120

Enclosure

CC: Travis Marshall, Senior Environmental Protection Specialist