

Notes:

The Annual Report Map has been revised to reflect the existing conditions at the mine.

(4) Mining continued in areas previously disturbed and material was removed from stockpiled material. The floor was lowered and the temporary slope in the NW corner of the disturbed area was pushed back to the base of the isolation berm as material was removed from the floor this year.

(8) Of the 5.6 acres disturbed approximately 0.81 acres of temporary sloping has been done along the north side. This will eventually be removed as mining progress to the north towards the final boundary.

(13) Mining will continue to deepen the disturbed area and temporary sloping will continue if needed. The backfilled area is along the northern slope.

(14) Weed control was one this year on the disturbed area. The Weed Works sprayed the mine area on July 7, 2022.

(19) The bond is adequate to complete reclamation according to the May 2019 inspection report.