



TRAPPER MINING INC.

September 26, 2022

Ms. Robin Reilley
Environmental Protection Specialist
Colorado Division of Reclamation, Mining, and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

Dear Ms. Robin Reilley:

**RE: Trapper Mining Inc., Permit C-81-010
Third Quarter 2022 Sediment Pond Inspections**

All impoundment inspections were conducted by a qualified impoundment inspector. Inspections took place on August 24th and 30th and September 1st, 8th and 13th.

Maintenance items noted during the inspections were as follows:

- East Pyeatt #1 sediment marker needs to be replace.
- East Pyeatt #2 sediment marker needs to be replace.
- East Pyeatt #3 sediment marker needs to be replace.
- Jeffway #1 identification sign needs to be put back up.


Trapper will address these maintenance items in a timely matter.

The sediment in No Name #2 Pond was removed this quarter.

Data related to pond capacity is attached. The last column on the table provides an estimate of the remaining capacity in each pond where remaining capacity is defined as the volume remaining after considering the estimated amount of sediment noted during the inspections.

Please contact me if you have any questions.

Sincerely,


Tonia Marie Perkins
CO PE 43864

C: EQ file 118.7



Trapper Mining Inc.

Third Quarter 2022

Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 2 Estimated Sediment (acre-feet)	Qtr. 2 Approximate Rem. Capacity (acre-feet)
Far East Buzzard	2.0	0.03	0.02	1.4	0.01	10.00	0.00	0.03
Coyote	30.5	75.1	45.06	26.7	30.04	0.00	0.00	75.10
No Name #2	8.5	8.47	5.08	6.0	3.39	0.00	0.00	8.47
No Name #4	14.5	8.23	4.94	11.7	3.29	10.00	0.82	7.41
No Name #5	6.0	1.03	0.62	4.7	0.41	20.00	0.21	0.82
Johnson #6	9.0	1.80	1.08	7.1	0.72	25.00	0.45	1.35
Johnson #7R	7.0	2.99	1.79	5.2	1.20	35.00	1.05	1.94
Johnson #8	7.0	3.58	2.15	4.6	1.43	35.00	1.25	2.33
Johnson #9	8.5	2.74	1.64	6.6	1.10	20.00	0.55	2.19
Johnson #10	9.0	6.09	3.65	7.0	2.44	25.00	1.52	4.57
West Pyeatt #1	9.0	2.76	1.66	7.0	1.10	45.00	1.24	1.52
West Pyeatt #2	10.0	1.89	1.13	7.3	0.76	45.00	0.85	1.04
Middle Pyeatt #1	10.0	1.40	0.84	8.1	0.56	40.00	0.56	0.84
Middle Pyeatt #2	10.0	1.26	0.76	8.4	0.50	20.00	0.25	1.01
Middle Pyeatt #3	10.0	5.70	3.42	7.9	2.28	40.00	2.28	3.42
East Pyeatt #1	8.0	0.99	0.59	6.5	0.40	10.00	0.10	0.89
East Pyeatt #2	8.0	4.15	2.49	6.1	1.66	10.00	0.42	3.74
East Pyeatt #3	8.0	1.51	0.91	6.8	0.60	25.00	0.38	1.13
Grouse #1	7.5	3.35	2.01	5.7	1.34	40.00	1.34	2.01
Grouse # 2	4.5	0.79	0.47	3.6	0.32	10.00	0.08	0.71
Sage #1	8.0	2.67	1.60	6.4	1.07	10.00	0.27	2.40
Sage #2	7.0	2.07	1.24	5.8	0.83	10.00	0.21	1.86
Oak #1	13.0	1.43	0.86	10.6	0.57	45.00	0.64	0.79
Oak #2	9.5	0.93	0.56	7.7	0.37	5.00	0.05	0.88

Trapper Mining Inc.

Third Quarter 2022

Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 2 Estimated Sediment (acre-feet)	Qtr. 2 Approximate Rem. Capacity (acre-feet)
West Flume	10.0	2.35	1.41	7.8	0.94	0.00	0.00	2.35
Middle Flume #1	11.7	0.80	0.48	9.0	0.32	40.00	0.32	0.48
Middle Flume # 3	14.0	3.36	2.02	10.5	1.34	35.00	1.18	2.18
East Middle Flume	13.0	2.56	1.54	9.2	1.02	15.00	0.38	2.18
East Flume	11.3	1.18	0.71	8.5	0.47	15.00	0.18	1.00
Ute	7.0	1.72	1.03	5.2	0.69	45.00	0.77	0.95
Horse	13.3	6.20	3.72	10.3	2.48	55.00	3.41	2.79
West Horse	13.0	2.00	1.20	9.7	0.80	20.00	0.40	1.60
Deal #1	16.8	2.00	1.20	15.1	0.80	10.00	0.20	1.80
Deal #2	6.0	1.66	0.60	3.1	1.06	0.00	0.00	1.66
Deacon #1	14.5	9.00	3.48	7.5	5.52	0.00	0.00	9.00
Deacon #2	12.0	7.03	3.60	7.7	3.43	0.00	0.00	7.03
Jeffway #1	9.0	2.86	1.20	5.3	1.66	0.00	0.00	2.86
Impoundment H	9.5	4.82	2.89	4.9	1.93	5.00	0.24	4.58

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Cassandra BrandtSIGNATURE: Cassandra BrandtDRAINAGE: **FAR EAST BUZZARD**DATE OF INSPECTION: 9-13-22

POND IDENTIFICATION	Far East Buzzard #1		
Approximate water level:	<u>0%</u>		
Sediment level (% total storage):	<u>10%</u>		
Outflow (cfs):	<u>0 cfs</u>		
Sediment marker (install or replace)	<u>In Place</u>		
Identification sign (install or replace)	<u>In Place</u>		
EROSIONAL:			
Rills and/or gullies on downstream face.	<u>No</u>		
Rills and/or gullies on upstream face.	<u>No</u>		
Inadequate vegetation.	<u>No</u>		
Outlet channel erosion.	<u>No</u>		
Burrows.	<u>No</u>		
Erosion of toe.	<u>No</u>		
Water impounded against downstream toe.	<u>No</u>		
Other.	<u>—</u>		
STRUCTURAL:			
Differential settling.	<u>No</u>		
Cracks, slides, or scarps.	<u>No</u>		
Seepage (specify location, color, value).	<u>No</u>		
Defective spillways.	<u>No</u>		
Other.	<u>—</u>		
APPURTENANT STRUCTURES:			
Defective spillways.	<u>No</u>		
Dewatering device clogged.	<u>No</u>		
Cracking or crushing of pipes.	<u>No</u>		
Other.	<u>—</u>		
COMMENTS:			

Dry Conditions. No issues noted.



TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: Cassandra BrandtSIGNATURE: *Cassandra Brandt*DRAINAGE: **COYOTE**DATE OF INSPECTION: 9-13-22

POND IDENTIFICATION	Coyote #1		
Approximate water level:	<u>0%</u>		
Sediment level (% total storage):	<u>min.</u>		
Outflow (cfs):	<u>0 cfs</u>		
Sediment marker (install or replace)	<u>N/A</u>		
Identification sign (install or replace)	<u>In Place</u>		
EROSIONAL:			
Rills and/or gullies on downstream face.	<u>No</u>		
Rills and/or gullies on upstream face.	<u>No</u>		
Inadequate vegetation.	<u>No</u>		
Outlet channel erosion.	<u>No</u>		
Burrows.	<u>No</u>		
Erosion of toe.	<u>No</u>		
Water impounded against downstream toe.	<u>No</u>		
Other.	<u>—</u>		
STRUCTURAL:			
Differential settling.	<u>No</u>		
Cracks, slides, or scarps.	<u>No</u>		
Seepage (specify location, color, value).	<u>No</u>		
Defective spillways.	<u>No</u>		
Other.	<u>—</u>		
APPURTENANT STRUCTURES:			
Defective spillways.	<u>No</u>		
Dewatering device clogged.	<u>No</u>		
Cracking or crushing of pipes.	<u>No</u>		
Other.	<u>—</u>		
COMMENTS:			

Sediment level is measured by a fixed surveyed elevation of 6298.11 ft. (9/29/10).

No water in Pond. Hot and dry conditions noted.

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: NO NAME

SIGNATURE: *Tonia Perkins*DATE OF INSPECTION: *8/24/2022*

POND IDENTIFICATION	No Name #2	No Name #4	No Name #5
Approximate water level:	<i>Minimal</i>	<i>100%</i>	<i>100%</i>
Sediment level (% total storage):	<i>*</i>	<i>10%</i>	<i>20%</i>
Outflow (cfs):	<i>*</i>	<i>LCFS</i>	<i>LCFS</i>
Sediment marker (install or replace)	<i>*</i>	<i>In Place</i>	<i>In Place</i>
Identification sign (install or replace)	<i>In Place</i>	<i>In Place</i>	<i>In Place</i>
EROSIONAL:			
Rills and/or gullies on downstream face.	<i>*</i>	<i>no</i>	<i>no</i>
Rills and/or gullies on upstream face.	<i>*</i>	<i>no</i>	<i>no</i>
Inadequate vegetation.	<i>*</i>	<i>no</i>	<i>no</i>
Outlet channel erosion.	<i>*</i>	<i>no</i>	<i>no</i>
Burrows.	<i>*</i>	<i>no</i>	<i>no</i>
Erosion of toe.	<i>*</i>	<i>no</i>	<i>no</i>
Water impounded against downstream toe.	<i>*</i>	<i>no</i>	<i>no</i>
Other.	<i>*</i>	<i>-</i>	<i>-</i>
STRUCTURAL:			
Differential settling.	<i>*</i>	<i>no</i>	<i>no</i>
Cracks, slides, or scarps.	<i>*</i>	<i>no</i>	<i>no</i>
Seepage (specify location, color, value).	<i>*</i>	<i>no</i>	<i>no</i>
Defective spillways.	<i>*</i>	<i>no</i>	<i>no</i>
Other.	<i>*</i>	<i>-</i>	<i>-</i>
APPURTENANT STRUCTURES:			
Defective spillways.	<i>*</i>	<i>no</i>	<i>no</i>
Dewatering device clogged.	<i>*</i>	<i>no</i>	<i>no</i>
Cracking or crushing of pipes.	<i>*</i>	<i>no</i>	<i>no</i>
Other.	<i>*</i>	<i>-</i>	<i>-</i>

COMMENTS:

#2: use riser/siphon tube as sediment marker; siphon top = 66%, bottom = 50%.

#4: use riser/siphon tube as sediment marker; siphon top = 75%, bottom = 60%.

#5: 60% level = top of post 4.5'.

No name #2 is currently being cleaned.There is some vegetation in the outlet of #4 + #5, the water flow is not obstructed.*

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: *Tonia Perkins*

DRAINAGE: JOHNSON GULCH

DATE OF INSPECTION: 8/24/2022

POND IDENTIFICATION	Johnson #6	Johnson #7R	Johnson #8R	Johnson #9R	Johnson #10R
Approximate water level:	100%	100%	100%	100%	90%
Sediment level (% total storage):	25%	35%	35%	20%	25%
Outflow (cfs):	21 CFS	21 CFS	21 CFS	21 CFS	0
Sediment marker (install or replace)	In Place	Underwater	Underwater	Underwater	Underwater
Identification sign (install or replace)	In Place	In Place	In Place	In Place	In Place
EROSIONAL:					
Rills and/or gullies on downstream face.	NO	NO	NO	NO	NO
Rills and/or gullies on upstream face.	NO	NO	NO	NO	NO
Inadequate vegetation.	NO	NO	NO	NO	NO
Outlet channel erosion.	NO	NO	NO	NO	NO
Burrows.	NO	NO	NO	NO	NO
Erosion of toe.	NO	NO	NO	NO	NO
Water impounded against downstream toe.	NO	NO	NO	NO	NO
Other.	-	-	-	-	-
STRUCTURAL:					
Differential settling.	NO	NO	NO	NO	NO
Cracks, slides, or scarps.	NO	NO	NO	NO	NO
Seepage (specify location, color, value).	NO	NO	NO	NO	NO
Defective spillways.	NO	NO	NO	NO	NO
Other.	-	-	-	-	-
APPURTENANT STRUCTURES:					
Defective spillways.	NO	NO	NO	NO	NO
Dewatering device clogged.	NO	NO	NO	NO	NO
Cracking or crushing of pipes.	NO	NO	NO	NO	NO
Other.	-	-	-	-	-
COMMENTS:					

#6: use riser/siphon tube as sediment marker; siphon top = 90%, top - 1.5' = 60%.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tim Cummins

SIGNATURE: Tim Cummins

DRAINAGE: WEST PYEATT

DATE OF INSPECTION: 8/30/22

POND IDENTIFICATION	West Pyeatt #1	West Pyeatt #2
Approximate water level:	0% damp	0% dry
Sediment level (% total storage):	45%	45%
Outflow (cfs):	0	0
Sediment marker (install or replace)	in place	in place
Identification sign (install or replace)	in place	in place
EROSIONAL:		
Rills and/or gullies on downstream face.	No	No
Rills and/or gullies on upstream face.	No	No
Inadequate vegetation.	No	No
Outlet channel erosion.	No	No
Burrows.	* 3	No
Erosion of toe.	No	No
Water impounded against downstream toe.	No	No
Other.	None	None
STRUCTURAL:		
Differential settling.	No	No
Cracks, slides, or scarps.	No	No
Seepage (specify location, color, value).	No	No
Defective spillways.	No	No
Other.	None	None
APPURTENANT STRUCTURES:		
Defective spillways.	No	No
Dewatering device clogged.	No	No
Cracking or crushing of pipes.	No	No
Other.	None	None
COMMENTS: * Burrows - non invasive		



TRAPPER MINING INC.

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tim Cummins

SIGNATURE: Jim Cummins

DRAINAGE: MIDDLE PYEATT

DATE OF INSPECTION: 8/30/22

POND IDENTIFICATION	Middle Pyeatt #1	Middle Pyeatt #2	Middle Pyeatt #3
Approximate water level:	40 %	0 % dry	
Sediment level (% total storage):	40 %	20 %	0 % dry
Outflow (cfs):	0	0	40 %
Sediment marker (install or replace)	in place	in place	in place
Identification sign (install or replace)	in place	in place	in place
EROSIONAL:			
Rills and/or gullies on downstream face.	No	No	No
Rills and/or gullies on upstream face.	No	No	No
Inadequate vegetation.	No	No	No
Outlet channel erosion.	No	No	No
Burrows.	No	No	No
Erosion of toe.	No	No	No
Water impounded against downstream toe.	No	No	No
Other.	None	None	None
STRUCTURAL:			
Differential settling.	No	No	No
Cracks, slides, or scarps.	No	No	No
Seepage (specify location, color, value).	No	No	No
Defective spillways.	No	No	No
Other.	None	None	None
APPURTENANT STRUCTURES:			
Defective spillways.	No	No	No
Dewatering device clogged.	No	No	No
Cracking or crushing of pipes.	No	No	No
Other.	None	None	None
COMMENTS:			



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tim Cummins

SIGNATURE: 

DRAINAGE: EAST PYEATT

DATE OF INSPECTION: 9/1/22

POND IDENTIFICATION	East Pyeatt #1	East Pyeatt #2	East Pyeatt #3
Approximate water level:	100%	80%	70%
Sediment level (% total storage):	10%	10%	25%
Outflow (cfs):	4 cfs	0	0
Sediment marker (install or replace)	replace	replace	replace
Identification sign (install or replace)	in place	in place	in place
EROSIONAL:			
Rills and/or gullies on downstream face.	No	No	No
Rills and/or gullies on upstream face.	No	No	No
Inadequate vegetation.	No	No	No
Outlet channel erosion.	No	No	No
Burrows.	No	No	No
Erosion of toe.	No	No	No
Water impounded against downstream toe.	No	No	No
Other.	None	None	None
STRUCTURAL:			
Differential settling.	No	No	No
Cracks, slides, or scarps.	No	No	No
Sepage (specify location, color, value).	No	No	No
Defective spillways.	No	No	No
Other.	None	None	None
APPURTENANT STRUCTURES:			
Defective spillways.	No	No	No
Dewatering device clogged.	No	No	No
Cracking or crushing of pipes.	No	No	No
Other.	None	None	None
COMMENTS:			



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Monte McCoy

SIGNATURE: 

DRAINAGE: GROUSE GULCH

DATE OF INSPECTION: 9-8-2022

POND IDENTIFICATION	Grouse #1	Grouse #2
Approximate water level:	Dry	Dry
Sediment level (% total storage):	40%	10%
Outflow (cfs):	0	0
Sediment marker (install or replace)	in place	in place
Identification sign (install or replace)	in place	in place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	—	—
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	—	—
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	—	—
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Monte McCoy

SIGNATURE: 

DRAINAGE: SAGE GULCH

DATE OF INSPECTION: 9-8-2022

POND IDENTIFICATION	Sage #1	Sage #2
Approximate water level:	Dry	Dry
Sediment level (% total storage):	10%	10%
Outflow (cfs):	0	0
Sediment marker (install or replace)	in place	in place
Identification sign (install or replace)	in place	in place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	N/A	N/A
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	N/A	N/A
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	N/A	N/A
COMMENTS:		



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: OAK GULCH

SIGNATURE: *Tonia Perkins*

DATE OF INSPECTION: 8/24/2022

POND IDENTIFICATION	Oak #1	Oak #2
Approximate water level:	40%	dry
Sediment level (% total storage):	45%	5%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	-	-
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	-	-

COMMENTS:
 Some vegetation in the outlet of both #1 & #2,
 but its not obstructing the water flow.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: WEST FLUME

SIGNATURE: 

DATE OF INSPECTION: 8/24/2022

POND IDENTIFICATION	West Flume #1
Approximate water level:	Dry
Sediment level (% total storage):	0%
Outflow (cfs):	0-1
Sediment marker (install or replace)	In Place
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	NO
Rills and/or gullies on upstream face.	NO
Inadequate vegetation.	NO
Outlet channel erosion.	NO
Burrows.	NO
Erosion of toe.	NO
Water impounded against downstream toe.	NO
Other.	-
STRUCTURAL:	
Differential settling.	NO
Cracks, slides, or scarps.	NO
Seepage (specify location, color, value).	NO
Defective spillways.	NO
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	NO
Dewatering device clogged.	NO
Cracking or crushing of pipes.	NO
Other.	-
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: Tonia Perkins

DRAINAGE: MIDDLE FLUME

DATE OF INSPECTION: 8/24/2022

POND IDENTIFICATION	Middle Flume #1	Middle Flume #3
Approximate water level:	10%	60%
Sediment level (% total storage):	40%	35%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	-	-
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	-	-
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: EAST MIDDLE FLUME

SIGNATURE: *Tonia Perkins*DATE OF INSPECTION: *8/24/2022*


POND IDENTIFICATION	East Middle Flume #1
Approximate water level:	<i>90%</i>
Sediment level (% total storage):	<i>15%</i>
Outflow (cfs):	<i>0%</i>
Sediment marker (install or replace)	<i>Underwater</i>
Identification sign (install or replace)	<i>In Place</i>
EROSIONAL:	
Rills and/or gullies on downstream face.	<i>no</i>
Rills and/or gullies on upstream face.	<i>no</i>
Inadequate vegetation.	<i>no</i>
Outlet channel erosion.	<i>no</i>
Burrows.	<i>no</i>
Erosion of toe.	<i>no</i>
Water impounded against downstream toe.	<i>no</i>
Other.	<i>-</i>
STRUCTURAL:	
Differential settling.	<i>no</i>
Cracks, slides, or scarps.	<i>no</i>
Seepage (specify location, color, value).	<i>no</i>
Defective spillways.	<i>no</i>
Other.	<i>-</i>
APPURTENANT STRUCTURES:	
Defective spillways.	<i>no</i>
Dewatering device clogged.	<i>no</i>
Cracking or crushing of pipes.	<i>no</i>
Other.	<i>-</i>
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: EAST FLUME

SIGNATURE: 

DATE OF INSPECTION: 8/24/2022

POND IDENTIFICATION	East Flume #1
Approximate water level:	30%
Sediment level (% total storage):	15%
Outflow (cfs):	0
Sediment marker (install or replace)	In Place
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	-
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: UTE GULCH

SIGNATURE: *Tonia Perkins*

DATE OF INSPECTION: 8/24/2022

POND IDENTIFICATION	Ute #1		
Approximate water level:	5%		
Sediment level (% total storage):	45%		
Outflow (cfs):	0%		
Sediment marker (install or replace)	In Place		
Identification sign (install or replace)	In Place		
EROSIONAL:			
Rills and/or gullies on downstream face.	No		
Rills and/or gullies on upstream face.	No		
Inadequate vegetation.	No		
Outlet channel erosion.	No		
Burrows.	No		
Erosion of toe.	No		
Water impounded against downstream toe.	No		
Other.	-		
STRUCTURAL:			
Differential settling.	No		
Cracks, slides, or scarps.	No		
Seepage (specify location, color, value).	No		
Defective spillways.	No		
Other.	-		
APPURTENANT STRUCTURES:			
Defective spillways.	No		
Dewatering device clogged.	No		
Cracking or crushing of pipes.	No		
Other.	-		
COMMENTS:			



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: HORSE GULCH

SIGNATURE: *Tonia Perkins*DATE OF INSPECTION: 8/24/2022

POND IDENTIFICATION	Horse #1		
Approximate water level:	30%		
Sediment level (% total storage):	55%		
Outflow (cfs):	0		
Sediment marker (install or replace)	In Place		
Identification sign (install or replace)	In Place		
EROSIONAL:			
Rills and/or gullies on downstream face.	no		
Rills and/or gullies on upstream face.	no		
Inadequate vegetation.	no		
Outlet channel erosion.	no		
Burrows.	no		
Erosion of toe.	no		
Water impounded against downstream toe.	no		
Other.	-		
STRUCTURAL:			
Differential settling.	no		
Cracks, slides, or scarps.	no		
Seepage (specify location, color, value).	no		
Defective spillways.	no		
Other.	-		
APPURTENANT STRUCTURES:			
Defective spillways.	no		
Dewatering device clogged.	no		
Cracking or crushing of pipes.	no		
Other.	-		
COMMENTS:			



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: WEST HORSE GULCH

SIGNATURE: *Tonia Perkins*

DATE OF INSPECTION: 8/24/2022

POND IDENTIFICATION	West Horse #1
Approximate water level:	Dry
Sediment level (% total storage):	20%
Outflow (cfs):	0
Sediment marker (install or replace)	In Place
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	No
Rills and/or gullies on upstream face.	No
Inadequate vegetation.	No
Outlet channel erosion.	No
Burrows.	No
Erosion of toe.	No
Water impounded against downstream toe.	No
Other.	-
STRUCTURAL:	
Differential settling.	No
Cracks, slides, or scarps.	No
Seepage (specify location, color, value).	No
Defective spillways.	No
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	No
Dewatering device clogged.	No
Cracking or crushing of pipes.	No
Other.	-
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: DEAL GULCH

SIGNATURE: *Tonia Perkins*

DATE OF INSPECTION: 8/24/2022

POND IDENTIFICATION	Deal #1	Deal #2
Approximate water level:	40%	Dry
Sediment level (% total storage):	10%	0%
Outflow (cfs):	0%	0%
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	-	-
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	-	-
COMMENTS:		



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia Perkins

DRAINAGE: DEACON

SIGNATURE:

DATE OF INSPECTION:



POND IDENTIFICATION	Deacon #1	Deacon #2
Approximate water level:	0%	0%
Sediment level (% total storage):	0%	0%
Outflow (cfs):	0%	0%
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	No	No
Rills and/or gullies on upstream face.	No	No
Inadequate vegetation.	No	No
Outlet channel erosion.	No	No
Burrows.	No	No
Erosion of toe.	No	No
Water impounded against downstream toe.	No	No
Other.	-	-
STRUCTURAL:		
Differential settling.	No	No
Cracks, slides, or scarps.	No	No
Seepage (specify location, color, value).	No	No
Defective spillways.	No	No
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	No	No
Dewatering device clogged.	No	No
Cracking or crushing of pipes.	No	No
Other.	-	-
COMMENTS:		

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: **JEFFWAY**

SIGNATURE: *Tonia Perkins*

DATE OF INSPECTION: *8/24/2022*

POND IDENTIFICATION	Jeffway #1
Approximate water level:	<i>Dry</i>
Sediment level (% total storage):	<i>0%</i>
Outflow (cfs):	<i>0%</i>
Sediment marker (install or replace)	<i>In Place</i>
Identification sign (install or replace)	<i>Instill *</i>
EROSIONAL:	
Rills and/or gullies on downstream face.	<i>NO</i>
Rills and/or gullies on upstream face.	<i>NO</i>
Inadequate vegetation.	<i>NO</i>
Outlet channel erosion.	<i>NO</i>
Burrows.	<i>NO</i>
Erosion of toe.	<i>NO</i>
Water impounded against downstream toe.	<i>NO</i>
Other	<i>-</i>
STRUCTURAL:	
Differential settling.	<i>NO</i>
Cracks, slides, or scarps.	<i>NO</i>
Seepage (specify location, color, value).	<i>NO</i>
Defective spillways.	<i>NO</i>
Other.	<i>-</i>
APPURTENANT STRUCTURES:	
Defective spillways.	<i>NO</i>
Dewatering device clogged.	<i>NO</i>
Cracking or crushing of pipes.	<i>NO</i>
Other.	<i>-</i>
COMMENTS:	

** Cows have knocked ID sign out of the ground.
 Needs to be pounded back into the ground.*



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: IMPOUNDMENT H

SIGNATURE: 

DATE OF INSPECTION: 8/24/2022


POND IDENTIFICATION	Impoundment H
Approximate water level:	Dry
Sediment level (% total storage):	5%
Outflow (cfs):	0%
Sediment marker (install or replace)	In Place
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	-
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: INDUSTRIAL WASTE POND

SIGNATURE: 

DATE OF INSPECTION: 8/24/2022

POND IDENTIFICATION	Industrial Waste Pond #1
Approximate water level:	60%
Sediment level (% total storage):	5%
Outflow (cfs):	0%
Sediment marker (install or replace)	N/A
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	NO
Rills and/or gullies on upstream face.	NO
Inadequate vegetation.	NO
Outlet channel erosion.	NO
Burrows.	NO
Erosion of toe.	NO
Water impounded against downstream toe.	NO
Other.	-
STRUCTURAL:	
Differential settling.	NO
Cracks, slides, or scarps.	NO
Seepage (specify location, color, value).	NO
Defective spillways.	NO
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	N/A
Dewatering device clogged.	N/A
Cracking or crushing of pipes.	N/A
Other.	-
COMMENTS:	

