




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Hunt Water, LLC Gravel Mine	MINE/PROSPECTING ID#: M-2018-027	MINERAL: Overburden and sand	COUNTY: Weld
INSPECTION TYPE: Monitoring	WEATHER: Clear	INSP. DATE: October 5, 2022	INSP. TIME: 09:45
OPERATOR: Hunt Water, LLC	OPERATOR REPRESENTATIVE: David Hunt	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: \$586,345.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Eric Scott	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: October 10, 2022	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>NA</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>NA</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>NA</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>NA</u>	(SF) PROCESSING FACILITIES----- <u>NA</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>NA</u>	(RV) REVEGETATION---- <u>NA</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>NA</u>	(RS) RECL PLAN/COMP-- <u>NA</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>NA</u>	(SC) EROSION/SEDIMENTATION--- <u>NA</u>	(ST) STIPULATIONS----- <u>NA</u>
(AT) ACID OR TOXIC MATERIALS----- <u>NA</u>	(OD) OFF-SITE DAMAGE----- <u>NA</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This was a routine monitoring inspection conducted by Eric Scott for the Division of Reclamation Mining and Safety (DRMS). DRMS met with permittee representatives David Hunt and Andrew Rodriguez of Civil Resources LLC at approximately 0945 at the site entrance located on the west side of WCR 27 at the northeast corner of the site. The permit boundary is still defined by existing fences and the site identification sign was present (photo 1).

The slurry wall surrounding the lined reservoir portion of the permit has been installed and provisionally approved by the SEO office, and the lined pond located in the SE corner of the permit has been completed. This lined pond may be released from the permit when the connecting pipeline proposed by the permittee is completed.

It was noted by DRMS that the site entrance has been modified by the permittee to comply with CDOT requirements and a permanent storm-water retention pond has been added (photo 2). A technical revision detailing these modifications should be submitted to the Division. Additional items that were discussed in the field that should be included in future revision(s) for this permit include: the proposed connecting piping under CO 85 to link the reservoir to the lined pond in the SE corner of the permit; and mining of additional area within the slurry wall when existing gas and oil pipelines and structures have been removed/relocated (photo 4).

Mining activity at the site was proceeding within the lined reservoir area according to the approved mining plan at this time (photo 3). No other issues were noted during this inspection, and DRMS left the site at approximately 1130.

Inspection Contact Address

David Hunt
Hunt Water, LLC
14460 WCR 40
Platteville, CO 80651

Andrew Rodriguez
Civil Resources, LLC
323 5th Street
Frederick, CO 80530

PHOTOGRAPHS



Photo 1 – Site identification sign located at site entrance.



Photo 2 – New storm water/settling pond located near improved site entrance.



Photo 3 – Mining within the provisionally approved slurry wall.



Photo 4 – Area in NW corner of existing slurry wall that will be mined when existing gas and oil features are removed.