



Bowie No. 1 Mine
PO Box 1488
Paonia, CO. 81428
(970)986-6236

October 11, 2022

Mr. Rob Zuber
Department of Natural Resources
Division of Reclamation, Mining and Safety
1313 Sherman Street, Room 215
Denver, CO. 80203

RE: Bowie Resources LLC
Bowie No. 1 Mine
DRMS Permit No. C-1981-038
Quarterly Pond Inspection Reports

Dear Mr. Zuber:

Find enclosed Bowie No. 1 Mine Pond inspection reports for the 3rd quarter of 2022.
If you have any questions or concerns regarding this submittal contact me at (970)986-6236.

Sincerely;

Basil R. Bear
Mine Manager

Bowie Resources LLC
Bowie #1 Mine
Sedimentation Pond

Loadout Pond

Quarter:	3
Inspection Date:	8-Sep-22
Inspected By:	brb

Primary Elevation:	5724.00
Cleanout Elevation:	5721.00

Approximate Water Elevation at Time of Inspection:	DRY
Approximate Sediment Elevation at Time of Inspection:	5720.00'
Outflow (C.F.S.)	0.00

Features:

Comments

Rills & Gullies on Embankment	No	
Inadequate Vegetation	No	
Outlet Channel Erosion	No	
Burrows	No	
Other		


Structural:

Differential Settling	No	
Cracks or Slides	No	
Seepage	No	
Other		

Appurtenant Structures

Defective Spillway	No	
Dewatering Device Clogged	No	
Faulty Gates, Baffles, Pumps	No	
Other	Gate Closed	

Additional Comments



Bowie Resources LLC
Bowie #1 Mine
Sedimentation Pond

Highway Pond

Quarter:	3
Inspection Date:	8-Sep-22
Inspected By:	brb

Primary Elevation:	5734.00
Cleanout Elevation:	5734.00

Approximate Water Elevation at Time of Inspection:	DRY
Approximate Sediment Elevation at Time of Inspection:	5730.00'
Outflow (C.F.S.)	0.00

Features:

		Comments
Rills & Gullies on Embankment	No	
Inadequate Vegetation	No	
Outlet Channel Erosion	No	
Burrows	No	
Other		


Structural:

Differential Settling	No	
Cracks or Slides	No	
Seepage	No	
Other		

Appurtenant Structures

Defective Spillway	No	
Dewatering Device Clogged	No	
Faulty Gates, Baffles, Pumps	No	
Other		

Additional Comments



Bowie Resources LLC
Bowie #1 Mine
Sedimentation Pond

WM WS-1 Pond

Quarter:	3
Inspection Date:	8-Sep-22
Inspected By:	brb

Primary Elevation:	7,064.50
Cleanout Elevation:	7,064.50

Approximate Water Elevation at Time of Inspection:	DRY
Approximate Sediment Elevation at Time of Inspection:	7061.00'
Outflow (C.F.S.)	0.00

Features:

Comments

Rills & Gullies on Embankment	No	
Inadequate Vegetation	No	
Outlet Channel Erosion	No	
Burrows	No	
Other	No	


Structural:

Differential Settling	No	
Cracks or Slides	No	
Seepage	No	
Other		

Appurtenant Structures

Defective Spillway	No	
Dewatering Device Clogged	No	
Faulty Gates, Baffles, Pumps	No	
Other	Gate Closed	

Additional Comments



Bowie Resources LLC
Bowie #1 Mine
Sedimentation Pond

WM WS-2 Pond

Quarter:	3
Inspection Date:	8-Sep-22
Inspected By:	brb

Primary Elevation:	7095.80
Cleanout Elevation:	7095.80

Approximate Water Elevation at Time of Inspection:	DRY
Approximate Sediment Elevation at Time of Inspection:	7091.00'
Outflow (C.F.S.)	0.00

Features:

		Comments
Rills & Gullies on Embankment	No	
Inadequate Vegetation	No	
Outlet Channel Erosion	No	
Burrows	No	
Other	No	

Structural:

Differential Settling	No	
Cracks or Slides	No	
Seepage	No	
Other		

Appurtenant Structures

Defective Spillway	No	
Dewatering Device Clogged	No	
Faulty Gates, Baffles, Pumps	No	
Other	Gate Open	

Additional Comments

