

**THIRD QUARTER 2022 POND INSPECTION REPORT**  
Pond Inspection Date: September 30, 2022

OPERATOR: OXBOW MINING, LLC, (Formerly TCLLC.)  
MINE: TERROR CREEK LOADOUT

POND IDENTIFICATION	P-1 (001)	Dugout (002)
TYPE OF POND	Sediment	Sediment
APPROXIMATE WATER LEVEL	0.0' dry	0.0' dry
SEDIMENT (% total storage)	<5 %	<5%
OUTFLOW (cfs)	0	0

**FEATURES**

**EROSIONAL**

Rills & Gullies	No	No
Inadequate Vegetation	No	No
Outlet Channel Erosion	No	No
Burrows	No	No
Other	No	No

**STRUCTURAL**

Differential Settling	No	No
Cracks or Slides	No	No
Seepage	No	No
Other	No	No

**APPURTENANT STRUCTURES**

Defective Spillways	No	No
Dewatering Devices Clogged	No	No
Faulty Gates, Etc.	No	No
Other	No	No

**MAINTENANCE REQUIRED**

No	No
----	----

**ADDITIONAL COMMENTS:** The design sediment level is 18" below the invert of the primary spillway on P-1. No erosion and adequate vegetative growth remains. Ponds are maintained as designed and in accordance with the approved plan.


**REFERENCE DRAWINGS:**

Map 7

Exh. 9, p. 11

**SWMP Controls:** The SWMP control devices were inspected and all SWMP control devices were found to be in adequate condition. See Map 14 for details.

Inspected By:

  
Doug A. Smith

Under Direction of:



Michael W. Ludlow  
Colorado Registered Professional Engineer No. 24046