



Seneca Yoast Mine  
29515 RCR 27  
Oak Creek, CO 80467

October 05, 2022

Robin Reilley  
Colorado Division of Reclamation, Mining and Safety  
1313 Sherman St., Room 215  
Denver, CO 80203

**RE: 3rd Quarter and Annual Pond Inspections – Seneca Yoast Mine (C 1994-082)**

Ms. Reilley:

Enclosed are the 3<sup>rd</sup> quarter 2022 and Annual pond inspection reports for the Seneca Yoast Mine. I personally inspected each pond and have provided a Professional Engineer's Statement on the following page of this letter to accompany the inspection reports. Please contact me if there are any questions or if you need any additional information.

Best Regards,

*Miranda Kawcak*

Miranda Kawcak  
Environmental Manager  
Peabody, Colorado Operations

**Attachments:**

Professional Engineer Certification (Miranda Kawcak, P.E.)  
Inspection Reports

**CERTIFICATION**

*I, Miranda Lynn Kawcak, a registered engineer in the State of Colorado do hereby certify that I have reviewed the attached Seneca Yoast Mine Sediment Pond Reports covering the third quarter of 2022, and that they are true and correct to the best of my knowledge and belief.*

*Miranda Kawcak*

---

10/05/2022

---

Miranda Lynn Kawcak  
CO P.E. No. 59419

Date



<b>Mining Area</b> <b>Date Inspected</b> <b>Impoundment</b> <b>NPDES ID No</b> <b>Owner's Rep</b>	Yoast Mine(Seneca Coal Co)	<b>Facility Configuration</b> <b>Date Last Inspected</b> <b>Pond Location</b> <b>Site Location</b> <b>Inspector</b>	Cross-Valley Pond	<b>Quarterly Impoundment Inspection Form</b>
	9/13/2022		6/20/2022	
	Pond# 010		NW¼ NE¼, Sec. 8, T5N, R87W	
	CO-0000221 D.P. 010		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Miranda Kawcak	
<b>Mark or Write in Appropriate Response:</b>				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
<b>GENERAL</b>				
Water Level (above or below principal spillway)			X	0.8 FT Below
Existing Embsnkmrnt Freeboard ( 10.1 ft)			10.9	
Outflow (gpm)			X	0 GPM
<b>EROSION</b>				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
<b>STRUCTURAL</b>				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
<b>STRUCTURES</b>				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
<b>MAINTENANCE</b>				
Maintenance Required			X	Outlet rusted but still functional
Maintenance Performed			X	
Additional Comments		X		

<b>Mining Area</b> <b>Date Inspected</b> <b>Impoundment</b> <b>NPDES ID No</b> <b>Owner's Rep</b>	Yeast Mine(Seneca Coal Co)	<b>Facility Configuration</b> <b>Date Last Inspected</b> <b>Pond Location</b> <b>Site Location</b> <b>Inspector</b>	Cross-Vally Pond	<b>Quarterly Impoundment Inspection Form</b>
	9/13/2022		6/20/2022	
	Pond #011		NW¼ SW¼, Sec. 16, T5N, R87W	
	CO-0000221 D.P.011		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Miranda Kawcak	
<b>Mark or Write in Appropriate Response:</b>				
FEATURE	PROBLEM		COMMENTS	
	YES (Above)	NO (Below)		
<b>GENERAL</b>				
Water Level (above or below principal spillway)		X	~8 FT Below	
Existing Embsnkmrnt Freeboard (5.1 ft)		13.1		
Outflow (gpm)		X	0	
<b>EROSION</b>				
Rills & Gullies on Embankment		X		
Wave Erosion		X		
Spillway Erosion		X		
Burrows		X		
Other		X		
<b>STRUCTURAL</b>				
Differential Settling		X		
Cracks or Slides		X		
Seepage		X		
Other		X		
<b>STRUCTURES</b>				
Principal Spillway				
Clogged Orifice		X		
Clogged or Damaged Culvert		X		
Damaged Headgate		NA		
Emergency Spillway				
Erosion		X		
Riprap		X		
Clogged or Damaged Culvert		X		
Other		X		
<b>MAINTENACE</b>				
Maintenance Required		X		
Maintenance Performed		X		
Additional Comments		X		

<b>Mining Area</b> <b>Date Inspected</b> <b>Impoundment</b> <b>NPDES ID No</b> <b>Owner's Rep</b>	Yoast Mine(Seneca Coal Co)	<b>Facility Configuration</b> <b>Date Last Inspected</b> <b>Pond Location</b> <b>Site Location</b> <b>Inspector</b>	Cross-Vally Pond	<b>Quarterly Impoundment Inspection Form</b>
	9/13/2022		6/21/2022	
	Pond #011A		SW¼ NW¼, Sec. 16, T5N, R87W	
	N/A		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Miranda Kawcak	
<b>Mark or Write in Appropriate Response:</b>				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
<b>GENERAL</b>				
Water Level (above or below principal spillway)			X	3 FT Below
Existing Embsnkmrnt Freeboard (4.6 ft)			7.6 FT	
Outflow (gpm)			X	0 GPM
<b>EROSION</b>				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
<b>STRUCTURAL</b>				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
<b>STRUCTURES</b>				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
<b>MAINTENACE</b>				
Maintenance Required			X	
Maintenance Performed			X	
Additional Comments			X	

Top of Sediment Storage = 2.1 feet below top of pipe

<b>Mining Area</b> <b>Date Inspected</b> <b>Impoundment</b> <b>NPDES ID No</b> <b>Owner's Rep</b>	Yeast Mine(Seneca Coal Co)	<b>Facility Configuration</b> <b>Date Last Inspected</b> <b>Pond Location</b> <b>Site Location</b> <b>Inspector</b>	Cross-Vally Pond	<b>Quarterly Impoundment Inspection Form</b>
	9/13/2022		6/20/2022	
	Pond #012		NE¼ NW¼, Sec. 19, T5N, R87W	
	CO-0000221 D.P. 012		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Miranda Kawcak	
<b>Mark or Write in Appropriate Response:</b>				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
<b>GENERAL</b>				
Water Level (above or below principal spillway)		X		~35 GPM
Existing Embsnkmmt Freeboard (9.0 ft)		9		
Outflow (gpm)		X		
<b>EROSION</b>				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
<b>STRUCTURAL</b>				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
<b>STRUCTURES</b>				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
<b>MAINTENACE</b>				
Maintenance Required			X	
Maintenance Performed			X	
Additional Comments			X	

<b>Mining Area</b>	Yoast Mine(Seneca Coal Co)	<b>Facility Configuration</b>	Cross-Vally Pond	<b>Quarterly Impoundment Inspection Form</b>
<b>Date Inspected</b>	9/13/2022	<b>Date Last Inspected</b>	6/20/2022	
<b>Impoundment</b>	Pond #012A	<b>Pond Location</b>	NE¼ NW¼, Sec. 19, T5N, R87W	
<b>NPDES ID No</b>	N/A	<b>Site Location</b>	8.5 mi SE of Hayden, CO	
<b>Owner's Rep</b>	Miranda Kawcak	<b>Inspector</b>	Miranda Kawcak	
<b>Mark or Write in Appropriate Response:</b>				
<b>FEATURE</b>	<b>PROBLEM</b>		<b>COMMENTS</b>	
	<b>YES (Above)</b>	<b>NO (Below)</b>		
<b>GENERAL</b>				
Water Level (above or below principal spillway)		X	Small pool of water	
Existing Embsnkmrnt Freeboard (4.6 ft)		8 Ft		
Outflow (gpm)		X	0 GPM	
<b>EROSION</b>				
Rills & Gullies on Embankment		X		
Wave Erosion		X		
Spillway Erosion		X		
Burrows		X		
Other		X		
<b>STRUCTURAL</b>				
Differential Settling		X		
Cracks or Slides		X		
Seepage		X		
Other		X		
<b>STRUCTURES</b>				
Principal Spillway				
Clogged Orifice		X		
Clogged or Damaged Culvert		X		
Damaged Headgate		NA		
Emergency Spillway				
Erosion		X		
Riprap		X		
Clogged or Damaged Culvert		X		
Other		X		
<b>MAINTENANCE</b>				
Maintenance Required		X		
Maintenance Performed		X		
Additional Comments		X		

<b>Mining Area</b> <b>Date Inspected</b> <b>Impoundment</b> <b>NPDES ID No</b> <b>Owner's Rep</b>	Yeast Mine(Seneca Coal Co)	<b>Facility Configuration</b> <b>Date Last Inspected</b> <b>Pond Location</b> <b>Site Location</b> <b>Inspector</b>	Cross-Vally Pond	<b>Quarterly Impoundment Inspection Form</b>
	9/13/2022		6/20/2022	
	Pond #013		SE¼ NW¼, Sec. 19, T5N, R87W	
	CO-0000221 D.P. 013		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Miranda Kawcak	
<b>Mark or Write in Appropriate Response:</b>				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
<b>GENERAL</b>				
Water Level (above or below principal spillway)			X	2.5 ft below outlet
Existing Embsnkmrnt Freeboard (4.0 ft)			6.5 FT	
Outflow (gpm)			X	0 GPM
<b>EROSION</b>				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
<b>STRUCTURAL</b>				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
<b>STRUCTURES</b>				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
<b>MAINTENACE</b>				
Maintenance Required			X	
Maintenance Performed			X	
Additional Comments			X	



<b>Mining Area</b> <b>Date Inspected</b> <b>Impoundment</b> <b>NPDES ID No</b> <b>Owner's Rep</b>	Yeast Mine(Seneca Coal Co)	<b>Facility Configuration</b> <b>Date Last Inspected</b> <b>Pond Location</b> <b>Site Location</b> <b>Inspector</b>	Cross-Vally Pond	<b>Quarterly Impoundment Inspection Form</b>
	9/13/2022		6/20/2022	
	Pond #014		NE¼ SW¼, Sec. 19, T5N, R87W	
	CO-0000221 D.P. 014		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Miranda Kawcak	
<b>Mark or Write in Appropriate Response:</b>				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
<b>GENERAL</b>				
Water Level (above or below principal spillway)			X	2.5 feet below outlet
Existing Embsnkmrnt Freeboard (6.8 ft)			9.3	
Outflow (gpm)			X	0 GPM
<b>EROSION</b>				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
<b>STRUCTURAL</b>				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
<b>STRUCTURES</b>				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
<b>MAINTENACE</b>				
Maintenance Required			X	
Maintenance Performed			X	
Additional Comments			X	