

MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:		MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
Schoolfield Pit		M-1993-027	Gravel	Custer
INSPECTION TYPE:		WEATHER: Windy	INSP. DATE:	INSP. TIME:
Monitoring		-	November 9, 2022	12:30
OPERATOR:		OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
Seifert Construction dba Seifert Enterprises, I		Eric Seifert	110c - Construction Limited Impact	
REASON FOR INSPECTION:		BOND CALCULATION TYPE:	BOND AMOUNT:	
Normal I&E Program		Partial Bond	\$25,000.00	
DATE OF COMPLAINT:		POST INSP. CONTACTS:	JOINT INSP. AGENCY:	
NA		None	None	
INSPECTOR(S):	INSPECTOR'S SIGNATURE:		SIGNATURE DATE:	
Eric Scott		Ein Lut	November 10, 2022	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY <u>Y</u>	(RD) ROADS <u>Y</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING NA	(EX) EXPLOSIVES <u>NA</u>
(PW) PROCESSING WASTE/TAILING NA	(SF) PROCESSING FACILITIES NA	(TS) TOPSOIL <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE NA	(RV) REVEGETATION <u>NA</u>
(SM) SIGNS AND MARKERS <u>Y</u>	(SP) STORM WATER MGT PLAN NA	(RS) RECL PLAN/COMP NA
(ES) OVERBURDEN/DEV. WASTE NA	(SC) EROSION/SEDIMENTATION NA	(ST) STIPULATIONS <u>NA</u>
(AT) ACID OR TOXIC MATERIALS NA	(OD) OFF-SITE DAMAGE <u>NA</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

PERMIT #: M-1993-027 INSPECTOR'S INITIALS: ECS INSPECTION DATE: November 9, 2022

OBSERVATIONS

This was a routine monitoring inspection conducted by Eric Scott of the Division of Reclamation Mining and Safety (DRMS) of the Schoolfield Pit, a 9.9 acre, 110c permit operated by Seifert Construction. Permittee representative Eric Seifert accompanied DRMS during the inspection. The Schoolfield Pit entrance/access road is located approximately 4.7 miles south of Westcliff, east of Hwy 69 on the south side of Rosita Rd (CR 328) immediately east of the County Landfill. The site was not active at the time of this inspection.

The site identification sign was present (photo 1), and permit boundary markers were observed in the field at the time of this inspection. The activity at the site appeared to be in compliance with the approved mining plan, and no issues were noted during this inspection. Approximately 5.5 acres (including the access road) have been affected at this time. The attached photos 2-3 show the general condition of the affected area at the time of this inspection.

Inspection Contact Address

Eric Seifert Seifert Construction dba Seifert Enterprises, LLC 198 Range View Loop Westcliffe, CO 81252

PHOTOGRAPHS



 $\label{eq:continuous} Photo \ 1-Site\ identification\ sign\ located\ on\ south\ side\ of\ CR\ 328\ at\ site\ access\ road.$



Photo 1 - NE corner of affected area looking WSW.



Photo 3 – NE corner of affected area looking South.