

PERMIT INFORMATION

Permit Number: C-1981-038	County: Delta			
Mine Name: Bowie No. 1 Mine	Operation Type: Underground			
Operator: Bowie Resources, LLC	Permit Status: Active			
Operator Address:	Ownership: Private			
Mr. Basil R Bear				
P.O. Box 1488	Operator Representative Present:			
Paonia, CO 81428				
	Basil Bear			
Operator Representative Signature: (Field Issuance Only)				

INSPECTION INFORMATION

Inspection Start Date: November Inspection Start Time: 07:45 Inspection End Date: November Inspection End Time: 11:20	•		Inspection Type: Coal Complete Inspection Inspection Reason: Normal I&E Program Weather: Cloudy	
Joint Inspection Agency:		Joint Inspection Contacts:		
None				
Post Inspection Agency:		Post Inspection Contacts:		
None				
Inspector(s):	Inspecto	r's Sig	nature: Signature Date:	
Robert Zuber, P.E.	Phot D. The			
			11/30/2022	

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

Y - Air Resource Protection R - Roads

Y - Backfill & Grading
 Y - Revegetation
 Y - Excess Spoil and Dev. Waste
 Y - Subsidence

NA - Explosives
Y - Slides and Other Damage
Y - Fish & Wildlife
NA - Support Facilities On-site

R - Hydrologic Balance **R** - Signs and Markers

Y - Gen. Compliance With Mine Plan
 R - Support Facilities Not On-site
 Y - Special Categories Of Mining

Y - Processing Waste Y - Topsoil

COMMENTS

A complete inspection was conducted by Rob Zuber of DRMS on November 29, 2022.

No mining or reclamation activities were being conducted at this site. BRL is focusing on Bowie No. 2 in 2022.

The weather was partly cloudy and cold. The ground was partially covered with snow.

AVAILABILITY OF RECORDS – Rule 5.02.4(1):

The records were found to be very well organized. Please see the Availability of Records form in this report.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

The ponds at the loadout, the Coal Storage Area (near Black Bridge Road), and the West Mine contained a small amount of snow, and no problems were identified with these ponds. Riprap ditches at the East Mine are stable.

ROADS – Rule 4.03

Construction 4.03.1(3)/4.03.2(3), Drainage 4.03.1(4)/4.03.2(4), Surfacing and Maintenance 4.03.1(5) and (6)/4.03.2(5) and (6), Reclamation 4.03.1(7)/4.03.2(7):

Roads at the East Mine and the road to the ROM area are in good shape.

RECLAMATION SUCCESS - Rule 4.15, Rule 3:

No erosion was seen at the reclaimed areas of the East Mine, including:

- The main area along the haul road and around the old portals
- The RDA
- The Old Waste Disposal Area
- The drainage where the reclaimed ponds (Ponds 1-4) are located.

The West Mine was in good shape, as viewed from Johnson Road.

SIGNS AND MARKERS – Rule 4.02:

Entrance signs and boundary markers were seen in many locations.

OFFSITE SUPPORT FACILIITES - Rule 4.04, 4.28:

No problems were seen with the Coal Storage Area by Black Bridge Road.

The slope below the loadout is stable. No erosion was seen at the loadout.

DOCUMENTS RECEIVED - none

OTHER (SPECIFY) - none

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Loadout slope, looking southwest



Loadout slope, looking east



West Mine from Johnson Road



East Mine from Old Waste Disposal Area



Drainage above Old Waste Disposal Area

AVAILABILITY OF RECORDS

PERMIT RECORDS		HYDROLOGIC RECORDS	
DRMS Permit	RN7 exp. 4/20/2023	NPDES Permit	CO-0049045
Permit Application w/Revisions	On shelf	NPDES Records (DMRs)	Exp. 2025 Thru
remit Application w/Nevisions	Oli sileli	NFDES Records (DIVINS)	October 2022
Findings Document	RN7 findings 3/30/2018	Stormwater Management Plan	Aug. 2018
Insurance Certificate	Exp.5/1/2023	SPCC Plan	No longer valid
Bond Document	SEE COMMENT 1	MSHA Pond Inspections	NA
Phased Bond Release	SL6, Findings		NA
Documents/Findings	2/15/2018	State Engineer's Pond Inspection	
Air Emission Permits	NA	Quarterly Pond Inspections	Thru
			September 2022
County Special Use Permits	NA	Annual Hydrology Reports	2021
UG Mining Landowner Notification	1993 and 1994	 Ground Water Monitoring 	2021 AHR
Subsidence Monitoring Reports	NA	 Surface Water Monitoring 	2021 AHR
Subsidence Monitoring Data	NA	 Spring & Seep Monitoring 	2021 AHR
Rill & Gully Survey	May 2022	Mine Water Discharge Monitoring	NA
Vegetation Monitoring Data		Mine Inflow Study	NA
Specific Variance Approvals	2.06.1(3) Steep Slope	Water Consumption Records	NA
Annual Reclamation Reports	2021	Well Permits	NA
Midterm Review Documents	MT8 10/13/2020		
DRMS/OSM Inspection	Thru		
Reports/Enforcement Actions (3 Years)	October 2022	BLASTING RECORDS	NA
Transfers/Succession of Operator	7/29/2009		
Temporary Cessation Notification	NA		
Reclamation Cost Estimate	SEE COMMENT 2		
CERTIFICATIONS			
Pond Certifications	W-1 and W-2 (2002)		
Annual Certifications for Large	NA		
Impoundments Fill Certifications for Excess Spoil or	Yes 2/4/1987	ADDITIONAL RECORDS	
Underground Development Waste	100 2171 1001	ABBITIONAL NEODIDO	
Quarterly Inspections	NA	CDOT Access Permit	Permit #399055 (June 1999)
 Compaction Testing 	NA	Annual Subsidence Report	2021 ARR
Final Certification	NA		
Coal Processing Waste Banks	NA		
Haul Road Certifications	Yes, several years		
Access Road Certifications	Yes, PAP Vol. 8A		
COMMENTO			

COMMENTS:

^{1.} Two instruments with Lexon Insurance Co.: \$2,500,000 + \$380,000 = \$2,880,000.

^{2.} The cost estimate of \$1,639,674 (from MT8) does not match liability. This is explained in SL-06 findings.