



TRAPPER MINING INC.

December 13, 2022

Ms. Robin Reilley
Environmental Protection Specialist
Colorado Division of Reclamation, Mining, and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

Dear Ms. Robin Reilley:

**RE: Trapper Mining Inc., Permit C-81-010
Fourth Quarter 2022 Sediment Pond Inspections**

All impoundment inspections were conducted by a qualified impoundment inspector. Inspections took place on October 18th and 19th, November 2nd and 29th, and December 8th and 10th.

Maintenance items noted during the inspections were as follows:

- East Pyeatt #1 sediment marker needs to be replace.
- East Pyeatt #2 sediment marker needs to be replace.
- East Pyeatt #3 sediment marker needs to be replace.

Trapper will address these maintenance items in a timely matter (when the water level decreases).

Data related to pond capacity is attached. The last column on the table provides an estimate of the remaining capacity in each pond where remaining capacity is defined as the volume remaining after considering the estimated amount of sediment noted during the inspections.

Please contact me if you have any questions.

Sincerely,


Tonia Marie Perkins
CO PE 43864

C: EQ file 118.7



Trapper Mining Inc.
Fourth Quarter 2022
Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 4 Estimated Sediment (acre-feet)	Qtr. 4 Approximate Rem. Capacity (acre-feet)
Far East Buzzard	2.0	0.03	0.02	1.4	0.01	10.00	0.00	0.03
Coyote	30.5	75.1	45.06	26.7	30.04	0.00	0.00	75.10
No Name #2	8.5	8.47	5.08	6.0	3.39	0.00	0.00	8.47
No Name #4	14.5	8.23	4.94	11.7	3.29	10.00	0.82	7.41
No Name #5	6.0	1.03	0.62	4.7	0.41	20.00	0.21	0.82
Johnson #6	9.0	1.80	1.08	7.1	0.72	25.00	0.45	1.35
Johnson #7R	7.0	2.99	1.79	5.2	1.20	35.00	1.05	1.94
Johnson #8	7.0	3.58	2.15	4.6	1.43	35.00	1.25	2.33
Johnson #9	8.5	2.74	1.64	6.6	1.10	20.00	0.55	2.19
Johnson #10	9.0	6.09	3.65	7.0	2.44	25.00	1.52	4.57
West Pyeatt #1	9.0	2.76	1.66	7.0	1.10	45.00	1.24	1.52
West Pyeatt #2	10.0	1.89	1.13	7.3	0.76	45.00	0.85	1.04
Middle Pyeatt #1	10.0	1.40	0.84	8.1	0.56	45.00	0.63	0.77
Middle Pyeatt #2	10.0	1.26	0.76	8.4	0.50	25.00	0.32	0.95
Middle Pyeatt #3	10.0	5.70	3.42	7.9	2.28	40.00	2.28	3.42
East Pyeatt #1	8.0	0.99	0.59	6.5	0.40	10.00	0.10	0.89
East Pyeatt #2	8.0	4.15	2.49	6.1	1.66	10.00	0.42	3.74
East Pyeatt #3	8.0	1.51	0.91	6.8	0.60	25.00	0.38	1.13
Grouse #1	7.5	3.35	2.01	5.7	1.34	40.00	1.34	2.01
Grouse # 2	4.5	0.79	0.47	3.6	0.32	10.00	0.08	0.71
Sage #1	8.0	2.67	1.60	6.4	1.07	10.00	0.27	2.40
Sage #2	7.0	2.07	1.24	5.8	0.83	10.00	0.21	1.86
Oak #1	13.0	1.43	0.86	10.6	0.57	45.00	0.64	0.79
Oak #2	9.5	0.93	0.56	7.7	0.37	5.00	0.05	0.88

Trapper Mining Inc.

Fourth Quarter 2022

Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 4 Estimated Sediment (acre-feet)	Qtr. 4 Approximate Rem. Capacity (acre-feet)
West Flume	10.0	2.35	1.41	7.8	0.94	0.00	0.00	2.35
Middle Flume #1	11.7	0.80	0.48	9.0	0.32	40.00	0.32	0.48
Middle Flume # 3	14.0	3.36	2.02	10.5	1.34	35.00	1.18	2.18
East Middle Flume	13.0	2.56	1.54	9.2	1.02	15.00	0.38	2.18
East Flume	11.3	1.18	0.71	8.5	0.47	15.00	0.18	1.00
Ute	7.0	1.72	1.03	5.2	0.69	45.00	0.77	0.95
Horse	13.3	6.20	3.72	10.3	2.48	55.00	3.41	2.79
West Horse	13.0	2.00	1.20	9.7	0.80	20.00	0.40	1.60
Deal #1	16.8	2.00	1.20	15.1	0.80	10.00	0.20	1.80
Deal #2	6.0	1.66	0.60	3.1	1.06	0.00	0.00	1.66
Deacon #1	14.5	9.00	3.48	7.5	5.52	0.00	0.00	9.00
Deacon #2	12.0	7.03	3.60	7.7	3.43	0.00	0.00	7.03
Jeffway #1	9.0	2.86	1.20	5.3	1.66	0.00	0.00	2.86
Impoundment H	9.5	4.82	2.89	4.9	1.93	5.00	0.24	4.58

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tim CumminsSIGNATURE: Tim CumminsDRAINAGE: **FAR EAST BUZZARD**DATE OF INSPECTION: 10/18/22

POND IDENTIFICATION	Far East Buzzard #1
Approximate water level:	0
Sediment level (% total storage):	10%
Outflow (cfs):	0
Sediment marker (install or replace)	In Place
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	No
Rills and/or gullies on upstream face.	No
Inadequate vegetation.	No
Outlet channel erosion.	No
Burrows.	No
Erosion of toe.	No
Water impounded against downstream toe.	No
Other.	-
STRUCTURAL:	
Differential settling.	No
Cracks, slides, or scarps.	No
Seepage (specify location, color, value).	No
Defective spillways.	No
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	No
Dewatering device clogged.	No
Cracking or crushing of pipes.	No
Other.	-

COMMENTS:

*Impoundment is dry
 No problems noted*



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tim CumminsSIGNATURE: Tim Cummins

DRAINAGE: COYOTE

DATE OF INSPECTION: 10/18/22

POND IDENTIFICATION	Coyote #1		
Approximate water level:	0		
Sediment level (% total storage):	minimal		
Outflow (cfs):	0		
Sediment marker (install or replace)	N/A		
Identification sign (install or replace)	In Place		
EROSIONAL:			
Rills and/or gullies on downstream face.	No		
Rills and/or gullies on upstream face.	No		
Inadequate vegetation.	No		
Outlet channel erosion.	No		
Burrows.	No		
Erosion of toe.	No		
Water impounded against downstream toe.	No		
Other.	—		
STRUCTURAL:			
Differential settling.	No		
Cracks, slides, or scarps.	No		
Seepage (specify location, color, value).	No		
Defective spillways.	No		
Other.	—		
APPURTENANT STRUCTURES:			
Defective spillways.	No		
Dewatering device clogged.	No		
Cracking or crushing of pipes.	No		
Other.	—		
COMMENTS:			

Sediment level is measured by a fixed surveyed elevation of 6298.11 ft. (9/29/10).

Impoundment is dry

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia PerkinsDRAINAGE: **NO NAME**SIGNATURE: Tonia PerkinsDATE OF INSPECTION: 10/18/22

POND IDENTIFICATION	No Name #2	No Name #4	No Name #5
Approximate water level:	58%	60%	100%
Sediment level (% total storage):	0%	10%	20%
Outflow (cfs):	0 cfs	2 cfs min	2 cfs
Sediment marker (install or replace)	In Place	In Place	Underwater
Identification sign (install or replace)	In Place	In Place	In Place
EROSIONAL:			
Rills and/or gullies on downstream face.	No	No	No
Rills and/or gullies on upstream face.	No	No	No
Inadequate vegetation.	No	No	No
Outlet channel erosion.	No	No	No
Burrows.	No	No	No
Erosion of toe.	No	No	No
Water impounded against downstream toe.	No	No	No
Other.	—	—	—
STRUCTURAL:			
Differential settling.	No	No	No
Cracks, slides, or scarps.	No	No	No
Seepage (specify location, color, value).	No	No	No
Defective spillways.	No	No	No
Other.	—	—	—
APPURTENANT STRUCTURES:			
Defective spillways.	No	No	No
Dewatering device clogged.	No	No	No
Cracking or crushing of pipes.	No/N/A	No	No
Other.	—	—	—
COMMENTS:			

#2: use riser/siphon tube as sediment marker; siphon top = 66%, bottom = 50%.

#4: use riser/siphon tube as sediment marker; siphon top = 75%, bottom = 60%.

#5: 60% level = top of post - 4.5'.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: JOHNSON GULCH

SIGNATURE: *Tonia Perkins*

DATE OF INSPECTION: 10/19/2022

POND IDENTIFICATION	Johnson #6	Johnson #7R	Johnson #8R	Johnson #9R	Johnson #10R
Approximate water level:	100%	100%	100%	100%	100%
Sediment level (% total storage):	25%	35%	35%	20%	25%
Outflow (cfs):	41 CFS	41 CFS	41 CFS	41 CFS	41 CFS
Sediment marker (install or replace)	In Place	Underwater	Underwater	Underwater	Underwater
Identification sign (install or replace)	In Place	In Place	In Place	In Place	In Place
EROSIONAL:					
Rills and/or gullies on downstream face.	NO	NO	NO	NO	NO
Rills and/or gullies on upstream face.	NO	NO	NO	NO	NO
Inadequate vegetation.	NO	NO	NO	NO	NO
Outlet channel erosion.	NO	NO	NO	NO	NO
Burrows.	NO	NO	NO	NO	NO
Erosion of toe.	NO	NO	NO	NO	NO
Water impounded against downstream toe.	NO	NO	NO	NO	NO
Other.	—	—	—	—	—
STRUCTURAL:					
Differential settling.	NO	NO	NO	NO	NO
Cracks, slides, or scarps.	NO	NO	NO	NO	NO
Seepage (specify location, color, value).	NO	NO	NO	NO	NO
Defective spillways.	NO	NO	NO	NO	NO
Other.	—	—	—	—	—
APPURTENANT STRUCTURES:					
Defective spillways.	NO	NO	NO	NO	NO
Dewatering device clogged.	NO	NO	NO	NO	NO
Cracking or crushing of pipes.	NO	NO	NO	NO	NO
Other.	—	—	—	—	—
COMMENTS:	#6: use riser/siphon tube as sediment marker; siphon top = 90%, top - 1.5' = 60%. Some vegetation in spillways of #8 & #9. Water flow is not hindered.				



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Andrew McCaslin

SIGNATURE: 

DRAINAGE: WEST PYEATT

DATE OF INSPECTION: 12/8/22

POND IDENTIFICATION	West Pyeatt #1	West Pyeatt #2
Approximate water level:	2' Snow	2' Snow
Sediment level (% total storage):	75%	75%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In place	In place
Identification sign (install or replace)	In place	In place
EROSIONAL:		
Rills and/or gullies on downstream face.	No	No
Rills and/or gullies on upstream face.	No	No
Inadequate vegetation.	No	No
Outlet channel erosion.	No	No
Burrows.	No	No
Erosion of toe.	No	No
Water impounded against downstream toe.	No	No
Other.	—	—
STRUCTURAL:		
Differential settling.	No	No
Cracks, slides, or scarps.	No	No
Seepage (specify location, color, value).	No	No
Defective spillways.	No	No
Other.	—	—
APPURTENANT STRUCTURES:		
Defective spillways.	No	No
Dewatering device clogged.	No	No
Cracking or crushing of pipes.	No	No
Other.	—	—
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Andrew McCaslin

SIGNATURE: 

DRAINAGE: MIDDLE PYEATT

DATE OF INSPECTION: 12/16/22

POND IDENTIFICATION	Middle Pyeatt #1	Middle Pyeatt #2	Middle Pyeatt #3
Approximate water level:	5070	Day	
Sediment level (% total storage):	75%	25%	98%
Outflow (cfs):	5	5	6
Sediment marker (install or replace)	in place	in place	in place
Identification sign (install or replace)	in place	in place	in place
EROSIONAL:			
Rills and/or gullies on downstream face.	No	No	No
Rills and/or gullies on upstream face.	No	No	No
Inadequate vegetation.	No	No	No
Outlet channel erosion.	No	No	No
Burrows.	No	No	No
Erosion of toe.	No	No	No
Water impounded against downstream toe.	No	No	No
Other.			
STRUCTURAL:			
Differential settling.	No	No	No
Cracks, slides, or scarps.	No	No	No
Seepage (specify location, color, value).	No	No	No
Defective spillways.	No	No	No
Other.			
APPURTENANT STRUCTURES:			
Defective spillways.	No	No	No
Dewatering device clogged.	No	No	No
Cracking or crushing of pipes.	No	No	No
Other.			
COMMENTS:			



TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Andrew McCaslin

SIGNATURE: *Andrew McCaslin*

DRAINAGE: EAST PYEATT

DATE OF INSPECTION: 12/10/22

POND IDENTIFICATION	East Pyeatt #1	East Pyeatt #2	East Pyeatt #3
Approximate water level:	100%	85%	75%
Sediment level (% total storage):	10%	10%	25%
Outflow (cfs):	100	0	0
Sediment marker (install or replace)	replace	replace	replace
Identification sign (install or replace)	in place	in place	in place
EROSIONAL:			
Rills and/or gullies on downstream face.	No	No	No
Rills and/or gullies on upstream face.	No	No	No
Inadequate vegetation.	No	No	No
Outlet channel erosion.	No	No	No
Burrows.	No	No	No
Erosion of toe.	No	No	No
Water impounded against downstream toe.	No	No	No
Other.	—	—	—
STRUCTURAL:			
Differential settling.	No	No	No
Cracks, slides, or scarps.	No	No	No
Seepage (specify location, color, value).	No	No	No
Defective spillways.	No	No	No
Other.	—	No	—
APPURTENANT STRUCTURES:			
Defective spillways.	No	No	No
Dewatering device clogged.	No	No	No
Cracking or crushing of pipes.	No	No	No
Other.	—	—	—

COMMENTS:

Sediment markers maybe under water



TRAPPER MINING INC.

TRAPPER MINING INC.

QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Andrew McCasin

SIGNATURE: 

DRAINAGE: GROUSE GULCH

DATE OF INSPECTION: 10/18/2022

POND IDENTIFICATION	Grouse #1	Grouse #2
Approximate water level:	Minimal	Dry
Sediment level (% total storage):	40%	10%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In place	In place
Identification sign (install or replace)	In place	In place
EROSIONAL:		
Rills and/or gullies on downstream face.	No	No
Rills and/or gullies on upstream face.	No	No
Inadequate vegetation.	No	No
Outlet channel erosion.	No	No
Burrows.	No	No
Erosion of toe.	No	No
Water impounded against downstream toe.	No	No
Other.	-	-
STRUCTURAL:		
Differential settling.	No	No
Cracks, slides, or scarps.	No	No
Seepage (specify location, color, value).	No	No
Defective spillways.	No	No
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	No	No
Dewatering device clogged.	No	No
Cracking or crushing of pipes.	No	No
Other.	-	-

COMMENTS:



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Andrew McCaslin

SIGNATURE: 

DRAINAGE: SAGE GULCH

DATE OF INSPECTION: 10/18/2022

POND IDENTIFICATION	Sage #1	Sage #2
Approximate water level:	Dry	Dry
Sediment level (% total storage):	10%	10%
Outflow (cfs):	0	0
Sediment marker (install or replace)	in place	in place
Identification sign (install or replace)	in place	in place
EROSIONAL:		
Rills and/or gullies on downstream face.	No	No
Rills and/or gullies on upstream face.	No	No
Inadequate vegetation.	No	No
Outlet channel erosion.	No	No
Burrows.	No	No
Erosion of toe.	No	No
Water impounded against downstream toe.	No	No
Other.	-	-
STRUCTURAL:		
Differential settling.	No	No
Cracks, slides, or scarps.	No	No
Seepage (specify location, color, value).	No	No
Defective spillways.	No	No
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	No	No
Dewatering device clogged.	No	No
Cracking or crushing of pipes.	No	No
Other.	-	-

COMMENTS:



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Monte McCoy

SIGNATURE: Monte McCoy

DRAINAGE: OAK GULCH

DATE OF INSPECTION: 11-29-2022

POND IDENTIFICATION	Oak #1	Oak #2
Approximate water level:	40%	Dry
Sediment level (% total storage):	45%	5%
Outflow (cfs):	0	0
Sediment marker (install or replace)	in place	in place
Identification sign (install or replace)	in place	in place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	—	—
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	—	—
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	—	—

COMMENTS:



TRAPPER MINING INC.

TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: Monte McCoySIGNATURE: *Monte McCoy*DRAINAGE: **WEST FLUME**DATE OF INSPECTION: 12/8/22

POND IDENTIFICATION	West Flume #1
Approximate water level:	<u>High</u>
Sediment level (% total storage):	<u>0%</u>
Outflow (cfs):	<u>0</u>
Sediment marker (install or replace)	<u>in place</u>
Identification sign (install or replace)	<u>in place</u>
EROSIONAL:	
Rills and/or gullies on downstream face.	<u>no</u>
Rills and/or gullies on upstream face.	<u>no</u>
Inadequate vegetation.	<u>no</u>
Outlet channel erosion.	<u>no</u>
Burrows.	<u>no</u>
Erosion of toe.	<u>no</u>
Water impounded against downstream toe.	<u>no</u>
Other.	<u>—</u>
STRUCTURAL:	
Differential settling.	<u>no</u>
Cracks, slides, or scarps.	<u>no</u>
Seepage (specify location, color, value).	<u>no</u>
Defective spillways.	<u>no</u>
Other.	<u>—</u>
APPURTENANT STRUCTURES:	
Defective spillways.	<u>no</u>
Dewatering device clogged.	<u>no</u>
Cracking or crushing of pipes.	<u>no</u>
Other.	<u>—</u>

COMMENTS:

Pond full of snow.No issues noted.

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: Tonia Perkins

DRAINAGE: MIDDLE FLUME

DATE OF INSPECTION: 10/19/2022

POND IDENTIFICATION	Middle Flume #1	Middle Flume #3
Approximate water level:	15'	90%
Sediment level (% total storage):	40%	35%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	Underwater
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	NO	NO
Rills and/or gullies on upstream face.	NO	NO
Inadequate vegetation.	NO	NO
Outlet channel erosion.	NO	NO
Burrows.	NO	NO
Erosion of toe.	NO	NO
Water impounded against downstream toe.	NO	NO
Other.	—	—
STRUCTURAL:		
Differential settling.	NO	NO
Cracks, slides, or scarps.	NO	NO
Seepage (specify location, color, value).	NO	NO
Defective spillways.	NO	NO
Other.	—	—
APPURTENANT STRUCTURES:		
Defective spillways.	NO	NO
Dewatering device clogged.	NO	NO
Cracking or crushing of pipes.	NO	NO
Other.	—	—
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: *Tonia Perkins*

DRAINAGE: EAST MIDDLE FLUME

DATE OF INSPECTION: 10/19/2022

POND IDENTIFICATION	East Middle Flume #1
Approximate water level:	90%
Sediment level (% total storage):	15%
Outflow (cfs):	0%
Sediment marker (install or replace)	Underwater
Identification sign (install or replace)	In place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	
COMMENTS:	



TRAPPER MINING INC.

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE

DRAINAGE: EAST FLUME

DATE OF INSPECTION:

10/19/2022

POND IDENTIFICATION	East Flume #1
Approximate water level:	40".
Sediment level (% total storage):	15-1.
Outflow (cfs):	0.
Sediment marker (install or replace)	In Place
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: Tonia Perkins

DRAINAGE: UTE GULCH

DATE OF INSPECTION: 11/2/2022

POND IDENTIFICATION	Ute #1		
Approximate water level:	35'		
Sediment level (% total storage):	45%		
Outflow (cfs):	0.1		
Sediment marker (install or replace)	In Place		
Identification sign (install or replace)	In Place		
EROSIONAL:			
Rills and/or gullies on downstream face.	NO		
Rills and/or gullies on upstream face.	NO		
Inadequate vegetation.	NO		
Outlet channel erosion.	NO		
Burrows.	NO		
Erosion of toe.	NO		
Water impounded against downstream toe.	NO		
Other.	-		
STRUCTURAL:			
Differential settling.	NO		
Cracks, slides, or scarps.	NO		
Seepage (specify location, color, value).	NO		
Defective spillways.	NO		
Other.	-		
APPURTENANT STRUCTURES:			
Defective spillways.	NO		
Dewatering device clogged.	NO		
Cracking or crushing of pipes.	NO		
Other.	-		
COMMENTS:			



TRAPPER MINING INC.

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: Tonia Perkins

DRAINAGE: HORSE GULCH

DATE OF INSPECTION: 12/19/2022

POND IDENTIFICATION	Horse #1
Approximate water level:	DRY
Sediment level (% total storage):	55%
Outflow (cfs):	0
Sediment marker (install or replace)	In Place
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	-

COMMENTS:



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia PerkinsDRAINAGE: **WEST HORSE GULCH**SIGNATURE: Tonia PerkinsDATE OF INSPECTION: 10/19/2022

POND IDENTIFICATION	West Horse #1
Approximate water level:	<u>DRY</u>
Sediment level (% total storage):	<u>2011</u>
Outflow (cfs):	<u>0</u>
Sediment marker (install or replace)	<u>In Place</u>
Identification sign (install or replace)	<u>In Place</u>
EROSIONAL:	
Rills and/or gullies on downstream face.	<u>NO</u>
Rills and/or gullies on upstream face.	<u>NO</u>
Inadequate vegetation.	<u>NO</u>
Outlet channel erosion.	<u>NO</u>
Burrows.	<u>NO</u>
Erosion of toe.	<u>NO</u>
Water impounded against downstream toe.	<u>NO</u>
Other.	
STRUCTURAL:	
Differential settling.	<u>NO</u>
Cracks, slides, or scarps.	<u>NO</u>
Seepage (specify location, color, value).	<u>NO</u>
Defective spillways.	<u>NO</u>
Other.	<u>-</u>
APPURTENANT STRUCTURES:	
Defective spillways.	<u>NO</u>
Dewatering device clogged.	<u>NO</u>
Cracking or crushing of pipes.	<u>NO</u>
Other.	<u>-</u>
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: Tonia Perkins

DRAINAGE: DEAL GULCH

DATE OF INSPECTION: 10/19/2022

POND IDENTIFICATION	Deal #1	Deal #2
Approximate water level:	45%	DRY
Sediment level (% total storage):	10%	0%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	NO	NO
Rills and/or gullies on upstream face.	NO	NO
Inadequate vegetation.	NO	NO
Outlet channel erosion.	NO	NO
Burrows.	NO	NO
Erosion of toe.	NO	NO
Water impounded against downstream toe.	NO	NO
Other.	-	-
STRUCTURAL:		
Differential settling.	NO	NO
Cracks, slides, or scarps.	NO	NO
Seepage (specify location, color, value).	NO	NO
Defective spillways.	NO	NO
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	NO	NO
Dewatering device clogged.	NO	NO
Cracking or crushing of pipes.	NO	NO
Other.	-	-
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: DEACON

SIGNATURE: *Tonia Perkins*

DATE OF INSPECTION: 10/19/2022

POND IDENTIFICATION	Deacon #1	Deacon #2
Approximate water level:	DRY	DRY
Sediment level (% total storage):	0%	0%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	-	-
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	-	-
COMMENTS:		



TRAPPER MINING INC.

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia PerkinsDRAINAGE: **JEFFWAY**SIGNATURE: Tonia PerkinsDATE OF INSPECTION: 10/19/2022

POND IDENTIFICATION	Jeffway #1			
Approximate water level:	5%			
Sediment level (% total storage):	0%			
Outflow (cfs):	0			
Sediment marker (install or replace)	In Place			
Identification sign (install or replace)	In Place			
EROSIONAL:				
Rills and/or gullies on downstream face.	no			
Rills and/or gullies on upstream face.	no			
Inadequate vegetation.	no			
Outlet channel erosion.	no			
Burrows.	no			
Erosion of toe.	no			
Water impounded against downstream toe.	no			
Other.	-			
STRUCTURAL:				
Differential settling.	no			
Cracks, slides, or scarps.	no			
Seepage (specify location, color, value).	no			
Defective spillways.	no			
Other.	-			
APPURTENANT STRUCTURES:				
Defective spillways.	no			
Dewatering device clogged.	no			
Cracking or crushing of pipes.	no			
Other.	-			
COMMENTS:				



TRAPPER MINING INC.

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: *Tonia Perkins*

DRAINAGE: IMPOUNDMENT H

DATE OF INSPECTION: 5/19/2022

POND IDENTIFICATION	Impoundment H			
Approximate water level:	100%			
Sediment level (% total storage):	5%			
Outflow (cfs):	21 CFS			
Sediment marker (install or replace)	In place			
Identification sign (install or replace)	In place			
EROSIONAL:				
Rills and/or gullies on downstream face.	no			
Rills and/or gullies on upstream face.	no			
Inadequate vegetation.	no			
Outlet channel erosion.	no			
Burrows.	no			
Erosion of toe.	no			
Water impounded against downstream toe.	no			
Other.	-			
STRUCTURAL:				
Differential settling.	no			
Cracks, slides, or scarps.	no			
Seepage (specify location, color, value).	no			
Defective spillways.	no			
Other.	-			
APPURTENANT STRUCTURES:				
Defective spillways.	no			
Dewatering device clogged.	no			
Cracking or crushing of pipes.	no			
Other.	-			
COMMENTS:				



TRAPPER MINING INC.

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

SIGNATURE: Tonia Perkins

DRAINAGE: INDUSTRIAL WASTE POND

DATE OF INSPECTION: 10/19/2022

POND IDENTIFICATION	Industrial Waste Pond #1
Approximate water level:	60%
Sediment level (% total storage):	5%
Outflow (cfs):	0
Sediment marker (install or replace)	N/A
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	No
Rills and/or gullies on upstream face.	No
Inadequate vegetation.	No
Outlet channel erosion.	No
Burrows.	No
Erosion of toe.	No
Water impounded against downstream toe.	No
Other.	-
STRUCTURAL:	
Differential settling.	No
Cracks, slides, or scarps.	No
Seepage (specify location, color, value).	No
Defective spillways.	No
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	N/A
Dewatering device clogged.	N/A
Cracking or crushing of pipes.	N/A
Other.	-
COMMENTS:	

