Stock Pond Inspection Form

Time Name		pector: Coop Ruppe el and XC Being Mined: HW553 NHGXC 19 s) Being Inspected: NO 570ch Ponos Wirmin TWICE Prodected andre of DIAN OF SUBSIDENCE
Yes	No	
	×	Is the stock pond within twice the projected angle of draw of subsidence? If yes, which pond(s):
		Are there visible surface cracks in or near the stock pond? If yes, describe (location, width, length, etc.):
		Is there any evidence of potential subsidence induced water loss? If yes, describe:
		Is there water in the pond? If yes, describe:
		Is mitigation needed? If yes, list suggestions:
Notes	5:	

Signature of Inspector: _

* If any potential subsidence induced features are observed that could cause harm to the pond, notify Jessica Wilczek immediately.

(W:\MCC-Engineering\ENV PERMITTING\REG AGENCIES\CDRMS\Inspection-Survey USFS Ponds & Rds\Ponds\Stock Pond Inspection Form)