

**Stock Pond  
Inspection Form**

Date: 10/11/22

Time: 2:00 PM

Name of Inspector: Cody Rapp

Current Panel and XC Being Mined: LWS53 XC 21 HG.

Stock Pond(s) Being Inspected: No stock ponds within twice  
projected angle of draw of subsidence

Yes    No

☐ ☒ Is the stock pond within twice the projected angle of draw of  
subsidence? If yes, which pond(s):


☐ ☐ Are there visible surface cracks in or near the stock pond? If yes,  
describe (location, width, length, etc.):

☐ ☐ Is there any evidence of potential subsidence induced water loss? If  
yes, describe:

☐ ☐ Is there water in the pond? If yes, describe:

☐ ☐ Is mitigation needed? If yes, list suggestions:

Notes:

Signature of Inspector: 

\* If any potential subsidence induced features are observed that could cause harm  
to the pond, notify Jessica Wilczek immediately.