

Forest Service Roads
Inspection Form

Date: 10/11/22

Time: 3:00 PM

Name of Inspector: Cory Rapke

Current Panel and XC Being Mined: LW553 ~X621 H6

Road(s) Being Inspected: Dry Fork & Deer Creek

Yes No

☐ ☒ Is the Forest Service road within the projected angle of draw of subsidence? If yes, which road(s):

☐ ☒ Are there visible surface cracks on the road? If yes, describe (location, width, length, etc.):

☐ ☒ Is there any recent evidence of potential subsidence induced slope failure? If yes, describe:

☐ ☒ Are there any other potentially damaging, subsidence induced features on or near the road? If yes, describe:

☐ ☒ Is mitigation needed? If yes, list suggestions:

Notes:

Signature of Inspector: _____



* If any potential subsidence induced features are observed that could cause harm to the public or operations, notify Jessica Wilczek immediately.