

PERMIT INFORMATION

Permit Number:C-1981-008CourseMine Name:New Horizon MineOpenOperator:Elk Ridge Mining and Reclamation,PermeLLCOwnOpenOperator Address:Mr Tony TennysonOpenP.O. Box 62827646 West 5th AvenueMindNucla, CO 81424

County: Montrose Operation Type: Surface Permit Status: Active Ownership: Private

Operator Representative Present:

Mindy Sickels

Operator Representative Signature: (Field Issuance Only)

INSPECTION INFORMATION

| Inspection Start Date: November 9, 2022 Inspection Start Time: 12:00 Inspection End Date: November 9, 2022 Inspection End Time: 13:45 | | | Inspection Type: Coal Complete Inspection Inspection Reason: Normal I&E Program Weather: Windy | |
|--|----------|----------------------------------|---|--|
| Joint Inspection Agency: | | Joint Inspection Contacts: | | |
| None | | | | |
| Post Inspection Agency: | | Post Inspection Contacts: | | |
| None | | | | |
| Inspector(s): | Inspecto | tor's Signature: Signature Date: | | |
| Janet Binns | Jan | | | |

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

R- Air Resource ProtectionY- RoadsR- Availability of RecordsY- ReclamaR- Backfill & GradingR- RevegetNA- Excess Spoil and Dev. WasteNA- SubsideNA- ExplosivesY- Slides atR- Fish & WildlifeR- SupportR- Hydrologic BalanceY- Signs atY- Gen. Compliance With Mine PlanNA- SupportNA- OtherNA- SpeciaNA- Processing WasteR- Topsoil

Y - Roads
Y - Reclamation Success
R - Revegetation
NA - Subsidence
Y - Slides and Other Damage
R - Support Facilities On-site
Y - Signs and Markers
NA - Support Facilities Not On-site
NA - Special Categories Of Mining

COMMENTS

This was a complete inspection conducted by Janet Binns of CDRMS. Mindy Sickels of Elk Ridge Mining and Reclamation accompanied the inspection and represented the operator. The weather was cloudy and extremely windy. A winter storm was howling in from the west.

The weather turned to a hard rain at the end of the inspection.

AIR RESOURCE PROTECTION – Rule 4.17:

Wind gusts were quite strong. But the reclaimed lands, topsoil and bench 1 stockpiles were not blowing dust. The site was quite stable and not contributing excessive dust under the high wind conditions.

AVAILABILITY OF RECORDS - Rule 5.02.4(1):

Records are stored in the main office building. Records have been maintained. The operator had the liability bond document for New Horizon North in the New Horizon Mine records notebook. ERMR needs to update this to reflect the current liability bond pertaining to C1981008.

FISH and WILDLIFE – Rule 4.18:

A flock of mallard ducks flew up from pond 13 as we approached. Pond 13 was slightly protected from the wind. The baffles and other sediment control structure did not appear to limit the ducks use of the pond.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

During the inspection portions of the mine site were damp. Mindy noted that the area had received some precipitation recently. SP2 pond was holding a shallow pool of water well below the discharge elevation. The inslopes were in good condition with the vegetation beginning to fill in. No concerns were noted with this stock tank.

Pond 13 was accessible. Mindy thought the inflow screen was due for a clean out soon. She estimated that it gets Number of <u>Partial</u> Inspection this Fiscal Year: 3 Number of <u>Complete</u> Inspections this Fiscal Year: 2

Number of Complete Inspections this Fiscal Year: 2

cleaned approximately once per month. The inflow rate was lower than the summer flow as irrigation water has been turned off for a while. Inflows were 285 gpm and 286 gpm= 571gpm on the two inflow pipe gauges. The baffles in the pond look secure and appear to be functioning.

Pond 15 had a damp puddle in the bottom. No concerns were noted with this pond. The collection ditch to Pond 15 looked to be in good shape as well.

Pond 12 was visited and was holding a steady pool of water covering the bottom of the pond. The water elevation was several feet below the discharge elevation, and there was no evidence that the pond had discharged previously. The pond inslopes were well vegetated. No concerns were noted with this pond.

Pond 18 was holding a shallow pool of water at the southern end of the pond. Thee water elevation was feet below the discharge elevation. No discharge form this pond had occurred.

Pond 16 was dry, with no concerns with this pond.

REVEGETATION - Rule 4.15

Vegetative Cover; Timing:

The Morgan property Irrigated Cropland was viewed for the hill on the north side of BB road. The IC1 field has been cut, hay bales removed and is still green. No obvious concerns were noted at this time. The Irrigated pasture Lloyd field was cut, still green and had no obvious concerns that were observed.

SUPPORT FACILITIES - Rule 4.04:

The facilities area is clean a tidy. ERMR continues to get rid of unused supplies and equipment. Nothing was blowing around in the wind storm. All petroleum products were properly stored. There were not concerns at the facilities area.

TOPSOIL - Rule 4.06

Removal 4.06.2; Substitute Materials 4.06.4(4); Storage and Protection 4.06.3; Redistribution 4.06.4:

The topsoil stockpile were well signed, ring ditches appeared intact. Although topsoil stockpile 12 still exhibits thin vegetative cover, the pile is stable, wasn't blowing with the windstorm, and did not show pronounced evidence of rilling or movement of the resource from runoff.

Topsoil stockpile footprint E still exhibits dry vegetation from this summer. The reclaimed pile is beginning to fill in with permanent vegetation. There was no evidence of rilling, gullies or soil blowing. The area appeared stable.

DOCUMENTS RECEIVED NA

OTHER (SPECIFY) NA

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

Number of <u>Partial</u> Inspection this Fiscal Year: 3 Number of <u>Complete</u> Inspections this Fiscal Year: 2

PHOTOGRAPHS



Photo 1: SP2

Photo 2: Pond 13 inflow



Photo 3: Pond 15

Photo 4: Pond 12



Photo 5: Irrigated Cropland across BB road

Photo 6: Pond 18

Number of <u>Partial</u> Inspection this Fiscal Year: 3 Number of <u>Complete</u> Inspections this Fiscal Year: 2



Photo 7: Topsoil stockpile E footprint

Number of <u>Partial</u> Inspection this Fiscal Year: 3 Number of <u>Complete</u> Inspections this Fiscal Year: 2

AVAILABILITY OF RECORDS C1981-008

| PERMIT RECORDS DRMS Permit | X – exp | HYDROLOGIC RECORDS NPDES Permit | X – exp. |
|---|--------------------------|------------------------------------|---|
| DRWS Fernit | 5/26/2023 | NI DES Fernit | 3/31/2021 *1 |
| Permit Application w/Revisions | Х | NPDES Records | X main office and online & 7/2022 |
| Findings Document | X - RN7 | Stormwater Management Plan | X 3/5/2019 |
| Insurance Certificate | X - 8/1/2023 | SPCC Plan | NA |
| Bond Document | Х | MSHA Pond Inspections | NA |
| Phased Bond Release | X – SL25 under | | NA |
| Documents/Findings | review | State Engineer's Pond Inspection | |
| Air Emission Permits | X 88MO234F | Quarterly Pond Inspections | Thru 1 st ¹ ⁄ ₄ 2022 |
| County Special Use Permits | X SU-99-0834 | Annual Hydrology Reports | X -12/2021 |
| UG Mining Landowner Notification | NA | Ground Water Monitoring | Х |
| Subsidence Monitoring Reports | NA | Surface Water Monitoring | Х |
| Subsidence Monitoring Data | NA | • Spring & Seep Monitoring | Х |
| Rill & Gully Survey | NA | Mine Water Discharge Monitoring | Х |
| Vegetation Monitoring Data | SL appl. | Mine Inflow Study | NA |
| Specific Variance Approvals | NA | • Water Consumption Records | Х |
| Annual Reclamation Reports | X - 2020 | Well Permits | Х |
| Midterm Review Documents | X - MT7 | | |
| DRMS/OSM Inspection | X – in Laserfiche | | |
| Reports/Enforcement Actions (3 | &through | | |
| Years) | 10/27/22 | BLASTING RECORDS | |
| Transfers/Succession of Operator | X SO-2 | | NA |
| | 10/3/2016 | Blasting Publication | |
| Temporary Cessation Notification | NA | Blasting Records (3 years) | Х |
| Reclamation Cost Estimate | X RN7 | ATFE Explosives Permit | NA |
| CERTIFICATIONS | | Blasting Variances | NA |
| Pond Certifications | X 2 nd ¼ 2022 | Pre-Blast Surveys | Χ |
| Annual Certifications for Impoundments | X 5/21/2021 | | |
| Fill Certifications for Excess Spoil | NA | ADDITIONAL RECORDS | |
| or Underground Development Waste | | (specify) | |
| Quarterly Inspections | NA | | |
| Compaction Testing | NA | | |
| Final Certification | NA | | |
| Coal Processing Waste Banks | NA | | |
| Haul Road Certifications | Х | | |
| Access Road Certifications | NA | | |

*1 Applied for CDPS renewal on 3/9/2021. *2 Need 3rd ¹/₄ 2022 Pond Inspection reports filed

Need to file SL24 Findings, NPDES DMR submitted via laserfiche Please file Liability bond for Permit C1981008

end of report

Number of <u>Partial</u> Inspection this Fiscal Year: 3 Number of <u>Complete</u> Inspections this Fiscal Year: 2

COMMENTS: