




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: East Bradbury Pit	MINE/PROSPECTING ID#: M-2010-016	MINERAL: Sand and gravel	COUNTY: Mesa
INSPECTION TYPE: Surety Release Inspection	WEATHER: Clear	INSP. DATE: January 10, 2023	INSP. TIME: 11:00
OPERATOR: Grand Junction Pipe & Supply Co.	OPERATOR REPRESENTATIVE: Jim Doody	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Surety Release Requested	BOND CALCULATION TYPE: None	BOND AMOUNT: \$107,139.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: DRMS	JOINT INSP. AGENCY: None	
INSPECTOR(S): Amy Yeldell	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: January 19, 2023	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>NA</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>NA</u>	(SF) PROCESSING FACILITIES----- <u>NA</u>	(TS) TOPSOIL----- <u>NA</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>NA</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>NA</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION-- <u>NA</u>	(ST) STIPULATIONS----- <u>Y</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>NA</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted in response to the request for full/final release (SL-1) submitted to the Colorado Division of Reclamation, Mining and Safety (Division), on December 22, 2022. The East Bradbury Pit is a 112c permitted site that includes a total of 129 permitted acres. The site located is approximately six miles southeast of Whitewater, Colorado and is accessed from Highway 50. The Division currently holds a financial warranty amount of \$107,139 for this site. Jim Doody of Grand Junction Pipe & Supply Co. represented the operator and accompanied Amy Yeldell of the Division on the inspection.

There is a locked gate to access the pit from Highway 50. The short access road to get on top of the bluff remains. This site has yet to commence mining activity and remains undisturbed. There are no stockpiles, equipment, fuel, structures or etc. on site. The access road and gate are a part of the approved reclamation plan and therefore may remain. Vegetation on the site overall is poor however since it was not affected by mining the Operator is not obligated to reclaim/ improve it. No problems or violations were noted during this inspection.

Bases on this inspection it is determined that the Operator has successfully complied with the requirements of the Act, Rules and Regulations, and the approved Reclamation Plan, and that the permit area is ready to be released from any further reclamation responsibility. SL-1 was called complete and notices were sent on January 3, 2023. The close of the comment period was January 18, 2023. No comments or objections were received. A decision letter will be sent separately.

Responses to this inspection report should be directed to: Amy Yeldell at the Division of Reclamation, Mining and Safety, Rm 215, 1001 E 62nd Ave, Denver, CO 80216. Direct contact can be made by phone at 303-866-3567 or via email at amy.yeldell@state.co.us

Inspection Contact Address

Jim Doody
Grand Junction Pipe & Supply Co.
556 Struthers Ave.
Grand Junction, CO 81501

Enclosure

CC:
Travis Marshall, Senior EPS, Grand Junction DRMS

PHOTOGRAPHS







