Forest Service Roads Inspection Form

Date: 1-12-23 Time: Name of Inspector: ハイのいつ Current Panel and XC Being Mined: 353 Road(s) Being Inspected:		
Yes	No	
	Ø	Is the Forest Service road within the projected angle of draw of subsidence? If yes, which road(s):
		Are there visible surface cracks on the road? If yes, describe (location, width, length, etc.):
		Is there any recent evidence of potential subsidence induced slope failure? If yes, describe:
		Are there any other potentially damaging, subsidence induced features on or near the road? If yes, describe:
		Is mitigation needed? If yes, list suggestions:
Notes:		
N	o a	ccess-winter conditions
Signature of Inspector: Mul U Bu Lo		

^{*} If any potential subsidence induced features are observed that could cause harm to the public or operations, notify Jessica Wilczek immediately.