<u>Forest Service Roads</u> <u>Inspection Form</u>

Date: 3-13-23 Time: Name of Inspector: N-1200S Current Panel and XC Being Mined: 553 Road(s) Being Inspected:		
Yes	No	
	۶ کر	Is the Forest Service road within the projected angle of draw of subsidence? If yes, which road(s):
		Are there visible surface cracks on the road? If yes, describe (location, width, length, etc.):
		Is there any recent evidence of potential subsidence induced slope failure? If yes, describe:
		Are there any other potentially damaging, subsidence induced features on or near the road? If yes, describe:
		Is mitigation needed? If yes, list suggestions:
Notes:		
No access-winter conditions		
Signature of Inspector: MUCO UPar Los		

/ ·~~ \

. ب * If any potential subsidence induced features are observed that could cause harm to the public or operations, notify Jessica Wilczek immediately.