

Zuber - DNR, Rob <rob.zuber@state.co.us>

Bowie #1 Inspection Report, 12 April 2023

1 message

Zuber - DNR, Rob <rob.zuber@state.co.us>

Thu, Apr 20, 2023 at 11:53 AM

To: Basil Bear <basilbear@wolverinefuels.com>, Tamme Bishop <tammekb@gmail.com> Cc: DNR DRMS_CoalAdmin - DNR <dnr_drms_coal_admin@state.co.us>

Basil and Tamme -

Please see the attached inspection report for Bowie #1.

Thanks, Rob

Rob Zuber, P.E. **Environmental Protection Specialist** Active Mines Regulatory Program



I am working remotely and can be reached by cell at 720.601.2276.

Physical Address: 1313 Sherman Street, Room 215

Denver, CO 80203 Mailing Address:

Division of Reclamation, Mining and Safety, Room 215

1001 East 62nd Avenue Denver, CO 80216

rob.zuber@state.co.us | http://drms.colorado.gov

INSP-REPORTC_C1981038_RDZ_04202023113031.pdf 1600K



PERMIT INFORMATION

| Permit Number: C-1981-038 Mine Name: Bowie No. 1 Mine Operator: Bowie Resources, LLC Operator Address: Mr. Basil R Bear | County: Delta Operation Type: Underground Permit Status: Active Ownership: Private | | | |
|---|--|--|--|--|
| P.O. Box 1488 | Operator Representative Present: | | | |
| Paonia, CO 81428 | operator may be resourced. | | | |
| 1 aoma, CO 01420 | None | | | |
| | | | | |
| Operator Representative Signature: (Field Issuance Only) | | | | |
| | | | | |
| | | | | |
| | | | | |

INSPECTION INFORMATION

| Inspection Start Date: April 12, 2023 Inspection Start Time: 07:30 Inspection End Date: April 12, 2023 Inspection End Time: 09:00 | | | Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Clear | |
|--|----------|----------------------------|---|-----------------|
| Joint Inspection Agency: | | Joint Inspection Contacts: | | |
| None | | | | |
| Post Inspection Agency: | | Post Inspection Contacts: | | |
| None | | | | |
| Inspector(s): | Inspecto | r's Sig | nature: | Signature Date: |
| Robert Zuber, P.E. | Phot | D. | 24 | |
| | | | | 4/20/2023 |

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource ProtectionN - Availability of Records

N - Backfill & Grading

N - Excess Spoil and Dev. Waste

NA - Explosives N - Fish & Wildlife R - Hydrologic Balance

 $\boldsymbol{Y}\,$ - Gen. Compliance With Mine Plan

N - Other

Y - Processing Waste

Y - Roads

 $\boldsymbol{Y}\,$ - Reclamation Success

Y - Revegetation

Y - Subsidence

R - Slides and Other DamageNA - Support Facilities On-site

R - Signs and Markers

R - Support Facilities Not On-siteY - Special Categories Of Mining

R - Topsoil

COMMENTS

A partial inspection was conducted by Rob Zuber of DRMS on April 12, 2023. No BRL representative was at the mine site.

No mining or reclamation activities were being conducted at this site. BRL is focusing on reclamation at Bowie No. 2 in 2023.

The weather was clear and warm. The ground was clear of snow except the West Mine, which had a lot of snow and mud (it is not south facing).

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

The ponds at the loadout and the Coal Storage Area (near Black Bridge Road) were dry, and no problems were identified with these ponds.

SLIDES and DAMAGE - Rule 4.12:

A significant slide was seen at the East Mine (see photograph). It was a circular shape, approximately 10-foot radius, with a resulting face of two feet high. It is in the same location as a slide from 2017. Large rocks were seen on the road to the portals at the East Mine. The steep slope above appears to be generally stable, but these rocks have fallen from this area and pose a hazard, especially during and after rain and snow events.

A large number of rills were seen at the West Mine. Most of the impacted area was released with SL-08, but the sediment from the rills is impacting the unreclaimed area near East Roatcap Creek.

SIGNS AND MARKERS – Rule 4.02:

Entrance signs were seen at the East Mine and at the Coal Storage Area by Black Bridge Road.

OFFSITE SUPPORT FACILIITES - Rule 4.04, 4.28:

No problems were seen with the Coal Storage Area by Black Bridge Road.

No erosion was seen at the loadout, including the steep slope between the loadout and the orchard below. The trestle across the river appears stable.

TOPSOIL - Rule 4.06

Removal 4.06.2; Substitute Materials 4.06.4(4); Storage and Protection 4.06.3; Redistribution 4.06.4:

Signs were not seen at the topsoil stockpiles at the loadout. These should be added or repaired.

DOCUMENTS RECEIVED - none

OTHER (SPECIFY) - none

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Lower portion of East Mine, from road above



East Mine, from Old Waste Disposal Area



East Mine – rocks below steep slope



East Mine steep slope



Slide at East Mine





Rills on West Mine



Slope below the loadout



Coal Storage by Highway and Black Bridge Road



Pond at Coal Storage by Highway and Black Bridge Road